



INSPECTION REPORT
122 Dobbin Ln
 Mooresville NC 28117

INSPECTED BY
Alex Parr 3692
Above Parr Home
Inspections

INSPECTION DATE
📅 1/31/2024
🕒 02:00:00 PM

Michael A Parr
3692

INVOICE

Above Parr Home Inspections

Inspected By: Alex Parr 3692

Inspection Date: 1/31/2024
Report ID: 013124AP1

Customer Info:	Inspection Property:
Bryan Kobus Customer's Real Estate Professional: Kelly Myers NextHome at the Lake	122 Dobbin Ln Mooreville NC 28117

Inspection Fee:

Service	Price	Amount	Sub-Total
Inspection Fee	600.00	1	600.00
WDI/Termite	75.00	1	75.00

Tax \$0.00
Total Price \$675.00

Payment Method: Credit Card
Payment Status: Paid
Note:

GENERAL INFO

Property Address

122 Dobbin Ln
Mooresville NC 28117

Date of Inspection

1/31/2024

Report ID

013124AP1

Customer(s)

Bryan Kobus

Time of Inspection

02:00:00 PM

Real Estate Agent

Kelly Myers
NextHome at the Lake

INSPECTION DETAILS

Approximate age of building:

Over 25 Years

In Attendance:

Vacant (inspector only),

Radon Test:

No

Water Test:

No

Mold/Fungal Testing:

No

Wood Destroying Insect Report:

Yes

Type of building:

Single Family (2 story)

COMMENT KEY & DEFINITIONS

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

Inspected (IN) = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI) = I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

■ ■ ■ TABLE OF CONTENTS

Cover Page	1
Invoice	2
Intro Page	3
Table of Contents	4
General Summary	5
1 Property Overview	17
2 Roofing	20
3 Exterior	22
4 Structural Components	27
5 Plumbing System	30
6 Electrical System	33
7 Heating / Central Air Conditioning	37
8 Interiors	40
9 Insulation and Ventilation	43
10 Built-In Kitchen Appliances	48

GENERAL SUMMARY

Above Parr Home Inspections

Customer

Bryan Kobus

Address

122 Dobbin Ln
Mooresville NC 28117

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling**; or **warrants further investigation by a specialist**, or **requires subsequent observation**. This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

"This summary page is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your North Carolina real estate agent or an attorney."

The summary page must describe any system or component of the home that does not function as intended, allowing for normal wear and tear that does not prevent the system or component from functioning as intended. The summary page must also describe any system or component that appears not to function as intended, based upon documented tangible evidence, and that requires either subsequent examination or further investigation by a specialist. The summary page may describe any system or component that poses a safety concern.


1. PROPERTY OVERVIEW

1.0 SUBJECT PROPERTY PROSPECTIVE


REPAIR OR REPLACE

1. Discoloration and some type of mold (Microbial) growth is present in the structure at several areas including but not limited to the crawl space and interior spaces. Evidence suggests that this condition is from a past or present elevated moisture conditions. We did not inspect, test or determine if this type of substance is or is not a health hazard. Further investigation is needed.

We recommend you contact a properly licensed expert for testing, investigation and or correction as deemed appropriate.



1.0 Item 1 (Picture)



1.0 Item 2 (Picture)


1.1 INSPECTION LIMITATIONS

REPAIR OR REPLACE

(1) The home inspection was limited, due to the following conditions:

1. The deck was currently under repairs at the time of inspection. Therefore I did not inspect deck. Further investigation and repairs are needed.

We recommend having all personal items removed and these areas inspected prior to closing.



1.1 Item 1 (Picture)

(2) The home inspection was limited, one or more areas were not accessible due to the following conditions:

1. Furniture, storage and or personal items in the garage and throughout the house. As a result the areas were not inspected. Hidden damage may be present. Further investigation and repairs are needed.

We recommend having all personal items removed and these areas inspected prior to closing.



1.1 Item 2 (Picture)



1.1 Item 3 (Picture)

2. ROOFING

2.0 ROOF COVERINGS

 REPAIR OR REPLACE

1. The roof shingles are damaged at the front of home. This damage should be repaired or replaced.
Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



2.0 Item 1 (Picture)



2.0 Item 2 (Picture)



2.0 Item 3 (Picture)



2.0 Item 4 (Picture)



2.0 Item 5 (Picture)



2.0 Item 6 (Picture)

3. EXTERIOR

3.1 EAVES, SOFFITS AND FASCIAS

 REPAIR OR REPLACE

1. Evidence of water damage at the front of the home. Further deterioration can occur if not corrected.
Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



3.1 Item 1 (Picture)



3.1 Item 2 (Picture)




3.1 Item 3 (Picture)



3.1 Item 4 (Picture)



3.1 Item 5 (Picture)



3.1 Item 6 (Picture)



3.1 Item 7 (Picture)

3.3 DOORS (EXTERIOR)

REPAIR OR REPLACE

1. The sliding glass door lock at the rear of home does not work. Therefore you cannot lock the door. Repairs are needed.

A qualified person should repair or replace as needed.



3.3 Item 1 (Picture)



3.3 Item 2 (Picture)

3.5 VEGETATION, GRADING, DRAINAGE, DRIVEWAYS, PATIO FLOOR, WALKWAYS AND RETAINING WALLS (WITH RESPECT TO THEIR EFFECT ON THE CONDITION OF THE BUILDING)

REPAIR OR REPLACE


(1)

1. The concrete drive at the left side (facing front) uneven, and can be a tripping hazard. Water can cause further deterioration if not repaired and sealed properly. A fall or injury can occur if not corrected. Further investigation and repair are needed.

A qualified contractor should inspect and repair as needed.



3.5 Item 1 (Picture)



3.5 Item 2 (Picture)



3.5 Item 3 (Picture)



3.5 Item 4 (Picture)



3.5 Item 5 (Picture)

(2)

1. The concrete sidewalk at the front of the home uneven, and can be a tripping hazard. Water can cause further deterioration if not repaired and sealed properly. A fall or injury can occur if not corrected. Further investigation and repair are needed.

A qualified contractor should inspect and repair as needed.



3.5 Item 6 (Picture)



3.5 Item 7 (Picture)



3.5 Item 8 (Picture)



3.5 Item 9 (Picture)



3.5 Item 10 (Picture)


4. STRUCTURAL COMPONENTS

4.0 WALLS (STRUCTURAL)

REPAIR OR REPLACE

1. The foundation wall at the right side (facing front) has cracks present. The wall(s) may need reinforcement. Further investigation and repairs are needed.

A qualified licensed general contractor should inspect further and repair as needed.



4.0 Item 1 (Picture)



4.0 Item 2 (Picture)



4.0 Item 3 (Picture)




4.0 Item 4 (Picture)



4.0 Item 5 (Picture)



4.0 Item 6 (Picture)




4.0 Item 7 (Picture)



4.0 Item 8 (Picture)



4.0 Item 9 (Picture)




4.0 Item 10 (Picture)

4.5 WOOD DETERIORATION

☐ REPAIR OR REPLACE

1. Wood debris is in contact with the crawl space floor in numerous areas. This can attract wood destroying organisms. Removal is needed.

A qualified contractor should inspect and repair as needed.



4.5 Item 1 (Picture)

4.6 FOUNDATIONS, BASEMENT AND CRAWLSPACE (REPORT SIGNS OF ABNORMAL OR HARMFUL WATER PENETRATION INTO THE BUILDING OR SIGNS OF ABNORMAL OR HARMFUL CONDENSATION ON BUILDING COMPONENTS.)

☐ REPAIR OR REPLACE

1. Visible signs of water intrusion in the crawlspace (right side of home facing rear) are present from standing water on plastic vapor barrier. Water intrusion can lead to more costly repairs and increase damage if not corrected. Further investigation and repairs are needed.

I recommend further investigation or correction by a qualified licensed contractor or water infiltration specialist.



4.6 Item 1 (Picture)

6. ELECTRICAL SYSTEM

6.4 CONNECTED DEVICES AND FIXTURES (OBSERVED FROM A REPRESENTATIVE NUMBER OPERATION OF CEILING FANS, LIGHTING FIXTURES, SWITCHES AND RECEPTACLES LOCATED INSIDE THE HOUSE, GARAGE, AND ON THE DWELLING'S EXTERIOR WALLS)

☐ REPAIR OR REPLACE

(1)

1. The ceiling fan does not work and in the guest bedroom. Electrical issues are considered a hazard until repaired. Repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 1 (Picture)


7. HEATING / CENTRAL AIR CONDITIONING

7.3 DISTRIBUTION SYSTEMS (INCLUDING FANS, PUMPS, DUCTS AND PIPING, WITH SUPPORTS, INSULATION, AIR FILTERS, REGISTERS, RADIATORS, FAN COIL UNITS AND CONVECTORS)

☐ REPAIR OR REPLACE

1. The ducts have been repaired improperly with duct tape in the crawlspace. Energy loss is occurring where duct tape has failed. Further investigation and repairs are needed..

I recommend further inspection by a licensed HVAC contractor.



7.3 Item 1 (Picture)



7.3 Item 2 (Picture)



7.3 Item 3 (Picture)

8. INTERIORS

8.6 WINDOWS (REPRESENTATIVE NUMBER)

☐ REPAIR OR REPLACE

(1)

1. The windows at the throughout the home have damaged sash springs. This can allow the window to come down suddenly causing glass breakage and or injury. (Safety Issue) Repairs are needed.

A qualified person should repair or replace as needed.



8.6 Item 1 (Picture)



8.6 Item 2 (Picture)



8.6 Item 3 (Picture)



8.6 Item 4 (Picture)



8.6 Item 5 (Picture)



8.6 Item 6 (Picture)

(2)

1. One window at the guest bedroom has a damaged tilt clip. This can allow the window to come down suddenly causing glass breakage and or injury. (Safety issue). Repairs are needed.

A qualified person should repair or replace as needed.



8.6 Item 7 (Picture)



8.6 Item 8 (Picture)

9. INSULATION AND VENTILATION

9.1 VENTILATION OF ATTIC AND FOUNDATION AREAS


☐ REPAIR OR REPLACE

1. Several foundation vents are loose and missing screens at the exterior. Rodents, reptiles or insects could enter into crawlspace. Repairs are needed.

A qualified person should repair or replace as needed.



9.1 Item 1 (Picture)



9.1 Item 2 (Picture)



9.1 Item 3 (Picture)



9.1 Item 4 (Picture)



9.1 Item 5 (Picture)

9.2 INSULATION IN ATTIC

☐ REPAIR OR REPLACE

(1)

1. Evidence of animal feces in the attic (above Living room). I was unable to determine if this was an active infestation. Sometimes pests can cause damage to home or components. Further investigation is needed.

A pest control company should inspect further and correct as needed.



9.2 Item 1 (Picture)



9.2 Item 2 (Picture)



9.2 Item 3 (Picture)



9.2 Item 4 (Picture)

(2)

1. Fiberglass (Batts) insulation in attic is missing in areas. Heat loss can occur more on this home than one that is properly insulated. Repairs are needed..

A qualified person should repair or replace as needed.



9.2 Item 5 (Picture)



9.2 Item 6 (Picture)



9.2 Item 7 (Picture)



9.2 Item 8 (Picture)

10. BUILT-IN KITCHEN APPLIANCES

10.0 DISHWASHER

☐ REPAIR OR REPLACE


(1)

1. The dishwasher rack is rusted in areas. Further deterioration will occur. I recommend repair as necessary.

I recommend contacting appliance repair company.



10.0 Item 1 (Picture)



10.0 Item 2 (Picture)

10.1 RANGES/OVENS/COOKTOPS

☐ REPAIR OR REPLACE

1. The range/oven needs to be properly attached/anchored to the structure as to keep it from tipping over when the oven door is opened and/or oven racks are pulled out during use. This is a safety issue. Repairs are needed.

I recommend contacting appliance repair company.



10.1 Item 1 (Picture)

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a

licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge <http://www.HomeGauge.com> : Licensed To Alex Parr 3692

✓ RESULTS AT A GLANCE

83

✓ ITEMS INSPECTED
Total number in report.

20

📋 SUMMARY COMMENTS
Total number in report.

109

📷 PHOTOS
Total number in report.

🏠 1. PROPERTY OVERVIEW

🔧 STYLES & MATERIALS: PROPERTY OVERVIEW

Temperature:

Below 60 (F) = 15.5 (C)

Weather:

Cloudy

Rain in last 3 days:

Yes


👁️ ITEMS: PROPERTY OVERVIEW

1.0 SUBJECT PROPERTY PROSPECTIVE


📋 REPAIR OR REPLACE

1. Discoloration and some type of mold (Microbial) growth is present in the structure at several areas including but not limited to the crawl space and interior spaces. Evidence suggests that this condition is from a past or present elevated moisture conditions. We did not inspect, test or determine if this type of substance is or is not a health hazard. Further investigation is needed.

We recommend you contact a properly licensed expert for testing, investigation and or correction as deemed appropriate.



1.0 Item 1 (Picture)



1.0 Item 2 (Picture)


1.1 INSPECTION LIMITATIONS

REPAIR OR REPLACE

(1) The home inspection was limited, due to the following conditions:

1. The deck was currently under repairs at the time of inspection. Therefore I did not inspect deck. Further investigation and repairs are needed.

We recommend having all personal items removed and these areas inspected prior to closing.



1.1 Item 1 (Picture)

(2) The home inspection was limited, one or more areas were not accessible due to the following conditions:

1. Furniture, storage and or personal items in the garage and throughout the house. As a result the areas were not inspected. Hidden damage may be present. Further investigation and repairs are needed.

We recommend having all personal items removed and these areas inspected prior to closing.



1.1 Item 2 (Picture)



1.1 Item 3 (Picture)

1.2 RADON TESTING

☑ NOT INSPECTED

🏠 2. ROOFING

📋 DESCRIPTION

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

🔧 STYLES & MATERIALS: ROOFING

Roof Covering: Architectural	Age: 10-15 Yrs	Viewed roof covering from: Ground Camera Optical Zoom
Sky Light(s): None	Chimney (exterior): N/A	Roof-Type: Gable

👁️ ITEMS: ROOFING

2.0 ROOF COVERINGS

📋 REPAIR OR REPLACE

1. The roof shingles are damaged at the front of home. This damage should be repaired or replaced.
Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



2.0 Item 1 (Picture)



2.0 Item 2 (Picture)



2.0 Item 3 (Picture)



2.0 Item 4 (Picture)



2.0 Item 5 (Picture)



2.0 Item 6 (Picture)

2.1 FLASHINGS

✓ INSPECTED

2.2 SKYLIGHTS, CHIMNEYS AND ROOF PENETRATIONS

✓ INSPECTED

2.3 ROOF DRAINAGE SYSTEMS

✓ INSPECTED

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 3. EXTERIOR



📋 DESCRIPTION

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

✂️ STYLES & MATERIALS: EXTERIOR

Siding Style:

Lap

Siding Material:

Brick veneer

Exterior Entry Doors:

Steel

Insulated glass

Appurtenance:

Deck with steps

Covered porch

Sidewalk

Driveway:

Concrete

👁️ ITEMS: EXTERIOR

3.0 WALL CLADDING FLASHING AND TRIM

✅ REPAIR OR REPLACE

1. The vinyl siding at the left side (facing front) is loose or not sealed properly. Deterioration can eventually occur if not corrected. Repairs are needed.

A qualified person should repair or replace as needed.



3.0 Item 1 (Picture)



3.0 Item 2 (Picture)



3.0 Item 3 (Picture)



3.0 Item 4 (Picture)



3.0 Item 5 (Picture)



3.0 Item 6 (Picture)

3.1 EAVES, SOFFITS AND FASCIAS

REPAIR OR REPLACE

1. Evidence of water damage at the front of the home. Further deterioration can occur if not corrected. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



3.1 Item 1 (Picture)



3.1 Item 2 (Picture)




3.1 Item 3 (Picture)



3.1 Item 4 (Picture)



3.1 Item 5 (Picture)



3.1 Item 6 (Picture)



3.1 Item 7 (Picture)

3.2 WINDOWS

REPAIR OR REPLACE

1. The steel lintels around the exterior of the home are beginning to rust or have rust present. A lintel is a horizontal architectural member or steel beam support placed over a wall opening to carry the weight of the masonry placed over it. In most situation, the lintel above you windows and doors will be steel angle iron or I beam. Either due to age or improper rust proofing or weep chord and flashing placement during installation, lintels will begin to rust. Rusting lintels can expand to become mush thicker then their original size. The expansive forces of rusting steel can shift entire multi-story elevations. If your lintels are currently rusting, a telltale sign of expansion is diagonal "step" pattern cracks, which can be found on either end of the window or door opening. Repairs are needed to prevent further damage to the structure. Further deterioration may occur if not repaired.

I recommend a qualified contractor inspect and repair as needed.



3.2 Item 1 (Picture)




3.2 Item 2 (Picture)

3.3 DOORS (EXTERIOR)

☐ REPAIR OR REPLACE

1. The sliding glass door lock at the rear of home does not work. Therefore you cannot lock the door. Repairs are needed.

A qualified person should repair or replace as needed.



3.3 Item 1 (Picture)



3.3 Item 2 (Picture)

3.4 DECKS, BALCONIES, STOOPS, STEPS, AREAWAYS, PORCHES, PATIO/COVER AND APPLICABLE RAILINGS

☒ INSPECTED

3.5 VEGETATION, GRADING, DRAINAGE, DRIVEWAYS, PATIO FLOOR, WALKWAYS AND RETAINING WALLS (WITH RESPECT TO THEIR EFFECT ON THE CONDITION OF THE BUILDING)

☐ REPAIR OR REPLACE

(1)

1. The concrete drive at the left side (facing front) uneven, and can be a tripping hazard. Water can

cause further deterioration if not repaired and sealed properly. A fall or injury can occur if not corrected. Further investigation and repair are needed.

A qualified contractor should inspect and repair as needed.



3.5 Item 1 (Picture)



3.5 Item 2 (Picture)



3.5 Item 3 (Picture)



3.5 Item 4 (Picture)



3.5 Item 5 (Picture)


(2)

1. The concrete sidewalk at the front of the home uneven, and can be a tripping hazard. Water can cause further deterioration if not repaired and sealed properly. A fall or injury can occur if not corrected. Further investigation and repair are needed.

A qualified contractor should inspect and repair as needed.



3.5 Item 6 (Picture)



3.5 Item 7 (Picture)



3.5 Item 8 (Picture)



3.5 Item 9 (Picture)



3.5 Item 10 (Picture)

3.6 GARAGE DOOR (S)

✓ INSPECTED

3.7 GARAGE DOOR OPERATORS (REPORT WHETHER OR NOT DOORS WILL REVERSE WHEN MET WITH RESISTANCE)

✓ INSPECTED

3.8 GARAGE WALLS (INCLUDING FIREWALL SEPARATION)

✓ INSPECTED

3.9 OCCUPANT DOOR (FROM GARAGE TO INSIDE OF HOME)

✓ INSPECTED

3.10 GARAGE FLOOR

✓ INSPECTED

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠

4. STRUCTURAL COMPONENTS

📋

DESCRIPTION

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

🔧

STYLES & MATERIALS: STRUCTURAL COMPONENTS

Foundation: Masonry block	Method used to observe Crawlspace: Crawled	Floor Structure: 2 X 10
Wall Structure: Wood	Columns or Piers: Wood piers	Ceiling Structure: 6" or better
Roof Structure: 2 X 6 Rafters		

👁

ITEMS: STRUCTURAL COMPONENTS

4.0 WALLS (STRUCTURAL)

📋


REPAIR OR REPLACE

1. The foundation wall at the right side (facing front) has cracks present. The wall(s) may need reinforcement. Further investigation and repairs are needed.

A qualified licensed general contractor should inspect further and repair as needed.



4.0 Item 1 (Picture)



4.0 Item 2 (Picture)



4.0 Item 3 (Picture)




4.0 Item 4 (Picture)




4.0 Item 5 (Picture)



4.0 Item 6 (Picture)




4.0 Item 7 (Picture)



4.0 Item 8 (Picture)



4.0 Item 9 (Picture)



4.0 Item 10 (Picture)

4.1 COLUMNS OR PIERS

☑ INSPECTED

4.2 FLOORS (STRUCTURAL)

☑ INSPECTED

4.3 CEILINGS (STRUCTURAL)

☑ INSPECTED

4.4 ROOF STRUCTURE AND ATTIC


☑ INSPECTED

4.5 WOOD DETERIORATION

☐ REPAIR OR REPLACE

1. Wood debris is in contact with the crawl space floor in numerous areas. This can attract wood destroying organisms. Removal is needed.
-

A qualified contractor should inspect and repair as needed.



4.5 Item 1 (Picture)

4.6 FOUNDATIONS, BASEMENT AND CRAWLSPACE (REPORT SIGNS OF ABNORMAL OR HARMFUL WATER PENETRATION INTO THE BUILDING OR SIGNS OF ABNORMAL OR HARMFUL CONDENSATION ON BUILDING COMPONENTS.)

☐ REPAIR OR REPLACE

1. Visible signs of water intrusion in the crawlspace (right side of home facing rear) are present from standing water on plastic vapor barrier. Water intrusion can lead to more costly repairs and increase damage if not corrected. Further investigation and repairs are needed.

I recommend further investigation or correction by a qualified licensed contractor or water infiltration specialist.



4.6 Item 1 (Picture)

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 5. PLUMBING SYSTEM

📋 DESCRIPTION

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.



Complimentary photo of the gas water heater

✂️ STYLES & MATERIALS: PLUMBING SYSTEM

Water Source:

Well

Water Filters:

Sediment filter

Plumbing Water Supply (into home):

Black hose

Plumbing Water Distribution (inside home):

Galvanized
Copper
PEX

Washer Drain Size:

2" Diameter

Plumbing Waste:

PVC

Water Heater Power Source:

Gas (quick recovery)

Water Heater Capacity:

Tankless

Manufacturer:

RINNAI

Water Heater Location:

Crawlspace

👁️ ITEMS: PLUMBING SYSTEM

5.0 MAIN WATER SHUT-OFF DEVICE (DESCRIBE LOCATION)

✓ INSPECTED

The main shut off is the green lever located underneath in the crawlspace. This is for your information.



5.0 Item 1 (Picture)

5.1 HOT WATER SYSTEMS, CONTROLS, CHIMNEYS, FLUES AND VENTS

✓ INSPECTED


5.2 PLUMBING WATER SUPPLY, DISTRIBUTION SYSTEM AND FIXTURES

✓ REPAIR OR REPLACE

(1)

1. The control knob leaks at the guest bath tub. Repairs are needed to prevent water damage from occurring to the home. Repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.2 Item 1 (Picture)



5.2 Item 2 (Picture)

(2)

1. The stop-valve is damaged at the master bath sinks. As a result you cannot fill up the tub. Repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.2 Item 3 (Picture)



5.2 Item 4 (Picture)



5.2 Item 5 (Picture)



5.2 Item 6 (Picture)

5.3 PLUMBING DRAIN, WASTE AND VENT SYSTEMS

✓ INSPECTED

5.4 SINKS, FIXTURES, AND TOILETS

✓ INSPECTED

5.5 SHOWER/TUB & TILE WALLS

✓ INSPECTED

5.6 FUEL STORAGE AND DISTRIBUTION SYSTEMS (INTERIOR FUEL STORAGE, PIPING, VENTING, SUPPORTS, LEAKS)

✓ INSPECTED

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 6. ELECTRICAL SYSTEM

☰ DESCRIPTION

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.



Complimentary photo of the electric panel with the cover off

✂ STYLES & MATERIALS: ELECTRICAL SYSTEM

Electrical Service Conductors: Below ground Aluminum	Panel capacity: 200 AMP	Panel Type: Circuit breakers
Electric Panel Manufacturer: SQUARE D	Branch wire 15 and 20 AMP: Copper	Wiring Methods: Romex

👁 ITEMS: ELECTRICAL SYSTEM

6.0 LOCATION OF MAIN AND DISTRIBUTION PANELS

✓ INSPECTED

The main panel box is located at the laundry room.

6.1 SERVICE ENTRANCE CONDUCTORS

✓ INSPECTED

6.2 SERVICE AND GROUNDING EQUIPMENT, MAIN OVERCURRENT DEVICE, MAIN AND DISTRIBUTION PANELS

✓ INSPECTED

6.3 BRANCH CIRCUIT CONDUCTORS, OVERCURRENT DEVICES AND COMPATABILITY OF THEIR AMPERAGE AND VOLTAGE

✓ INSPECTED

6.4 CONNECTED DEVICES AND FIXTURES (OBSERVED FROM A REPRESENTATIVE NUMBER OPERATION OF CEILING FANS, LIGHTING FIXTURES, SWITCHES AND RECEPTACLES LOCATED INSIDE THE HOUSE, GARAGE, AND ON THE DWELLING'S EXTERIOR WALLS)

✗ REPAIR OR REPLACE

(1)

1. The ceiling fan does not work and in the guest bedroom. Electrical issues are considered a hazard until repaired. Repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 1 (Picture)

(2)

1. The ceiling fan is noisy in the guest bedroom and the bonus room. Some fans that wobble can not be corrected without replacement. Repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 2 (Picture)



6.4 Item 3 (Picture)

(3)

1. The control knob dimmer switch is missing at the bonus room. Repairs are needed..

A qualified licensed electrical contractor should correct as needed.



6.4 Item 4 (Picture)

6.5 POLARITY AND GROUNDING OF RECEPTACLES WITHIN 6 FEET OF INTERIOR PLUMBING FIXTURES, ALL RECEPTACLES IN GARAGE, CARPORT AND EXTERIOR WALLS OF INSPECTED STRUCTURE

✓ INSPECTED

6.6 OPERATION OF GFCI (GROUND FAULT CIRCUIT INTERRUPTERS)

✓ INSPECTED

6.7 SMOKE DETECTORS

✓ INSPECTED

6.8 CARBON MONOXIDE DETECTORS

✓ INSPECTED

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection

report.

7. HEATING / CENTRAL AIR CONDITIONING

DESCRIPTION

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.



Complimentary photo of the of the AC unit



Complimentary photo of the gas furnace with the cover off

STYLES & MATERIALS: HEATING / CENTRAL AIR CONDITIONING

Heat Type: Forced Air	Heating Age: 10-15 yrs	Number of Heat Systems (excluding wood): One
Energy Source: Natural gas	Operated: Unit Operated	Heat System Brand: LENNOX
Ductwork: Insulated	Types of Fireplaces: Non-vented gas logs	Operable Fireplaces: One
Number of Woodstoves: None	Cooling Equipment Type: Heat Pump Forced Air (also provides warm air)	Air Conditioning Age: 10-15 yrs
Cooling Equipment Energy Source: Electricity	Central Air Manufacturer: LENNOX	Number of AC Only Units: One

ITEMS: HEATING / CENTRAL AIR CONDITIONING

7.0 HEATING EQUIPMENT

✓ INSPECTED

7.1 NORMAL OPERATING CONTROLS

✓ INSPECTED

7.2 AUTOMATIC SAFETY CONTROLS


✓ INSPECTED

7.3 DISTRIBUTION SYSTEMS (INCLUDING FANS, PUMPS, DUCTS AND PIPING, WITH SUPPORTS, INSULATION, AIR FILTERS, REGISTERS, RADIATORS, FAN COIL UNITS AND CONVECTORS)

✗ REPAIR OR REPLACE

1. The ducts have been repaired improperly with duct tape in the crawlspace. Energy loss is occurring where duct tape has failed. Further investigation and repairs are needed..

I recommend further inspection by a licensed HVAC contractor.



7.3 Item 1 (Picture)



7.3 Item 2 (Picture)



7.3 Item 3 (Picture)

7.4 PRESENCE OF INSTALLED HEAT SOURCE IN EACH ROOM

✓ INSPECTED

7.5 CHIMNEYS, FLUES AND VENTS (FOR FIREPLACES, GAS WATER HEATERS OR HEAT SYSTEMS)

✓ INSPECTED

7.6 SOLID FUEL HEATING DEVICES (FIREPLACES, WOODSTOVE)

✓ NOT PRESENT

7.7 GAS/LP FIRELOGS AND FIREPLACES

✓ INSPECTED

7.8 COOLING AND AIR HANDLER EQUIPMENT

✓ REPAIR OR REPLACE

(1)

1. The foam sleeve on suction line is missing foam sleeve in area(s) at outside unit. Missing foam on suction line can cause energy loss and condensation. I recommend service or repair as needed.

A licensed HVAC contractor should service or repair unit.



7.8 Item 1 (Picture)



7.8 Item 2 (Picture)



7.8 Item 3 (Picture)

(2)

1. The A/C was not tested for proper operation due to the outside air temperature is 65 degrees or less. We did not inspect this unit(s).

7.9 NORMAL OPERATING CONTROLS

☑ INSPECTED

7.10 PRESENCE OF INSTALLED COOLING SOURCE IN EACH ROOM

☑ INSPECTED

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

 8. INTERIORS

 DESCRIPTION

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

 STYLES & MATERIALS: INTERIORS

Ceiling Materials: Drywall	Wall Material: Drywall	Floor Covering(s): Area rug Carpet Hardwood T&G Tile
Interior Doors: Hollow core Raised panel	Window Types: Thermal/Insulated Double-hung Casement Fixed	

 ITEMS: INTERIORS

8.0 CEILINGS

 INSPECTED

8.1 WALLS

 INSPECTED

8.2 FLOORS

 INSPECTED

8.3 STEPS, STAIRWAYS, BALCONIES AND RAILINGS

 INSPECTED

8.4 COUNTERS AND CABINETS (REPRESENTATIVE NUMBER)

 INSPECTED

8.5 DOORS (REPRESENTATIVE NUMBER)

 REPAIR OR REPLACE

(1)

1. The bifold doors rub the floor when opened. The door needs to be trimmed at the bottom by a skilled craftsman at the guest bedrooms. As a result, the door will not close properly. Repairs are needed.

A qualified person should repair or replace as needed.




8.5 Item 1 (Picture)



8.5 Item 2 (Picture)



8.5 Item 3 (Picture)




8.5 Item 4 (Picture)

(2)

1. The privacy door rubs floor when opened at the office. Door needs to be trimmed at bottom by a skilled craftsman at the office. As a result the door will not close properly. A repair or replacement is needed.

A qualified person should repair or replace as needed.



8.5 Item 5 (Picture)

8.6 WINDOWS (REPRESENTATIVE NUMBER)

☐ REPAIR OR REPLACE

(1)

1. The windows at the throughout the home have damaged sash springs. This can allow the window to come down suddenly causing glass breakage and or injury. (Safety Issue) Repairs are needed.

A qualified person should repair or replace as needed.



8.6 Item 1 (Picture)



8.6 Item 2 (Picture)



8.6 Item 3 (Picture)



8.6 Item 4 (Picture)



8.6 Item 5 (Picture)




8.6 Item 6 (Picture)

(2)

1. One window at the guest bedroom has a damaged tilt clip. This can allow the window to come down suddenly causing glass breakage and or injury. (Safety issue). Repairs are needed.

A qualified person should repair or replace as needed.



8.6 Item 7 (Picture)



8.6 Item 8 (Picture)

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 9. INSULATION AND VENTILATION

☰ DESCRIPTION

The home inspector shall observe: Insulation and vapor retarders in unfinished spaces; Ventilation of attics and foundation areas; Kitchen, bathroom, and laundry venting systems; and the operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control. The home inspector shall describe: Insulation in unfinished spaces; and Absence of insulation in unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evidence indicates the need to do so; and Move insulation where chimneys penetrate roofs, where plumbing drain/waste pipes penetrate floors, adjacent to earth filled stoops or porches, and at exterior doors. The home inspector is not required to report on: Concealed insulation and vapor retarders; or Venting equipment that is integral with household appliances.

✂️ STYLES & MATERIALS: INSULATION AND VENTILATION

Attic info: Scuttle hole Attic hatch	Method used to observe attic: From entry	Attic Insulation: Blown Fiberglass
Ventilation: Ridge vents Soffit Vents	Exhaust Fans: Fan with light	Dryer Power Source: 220 Electric
Dryer Vent: Metal	Floor System Insulation: Faced Batts	

👁️ ITEMS: INSULATION AND VENTILATION

9.0 VAPOR RETARDERS (IN CRAWLSPACE OR BASEMENT)

✅ REPAIR OR REPLACE

1. The vapor barrier (plastic) on the crawlspace ground is missing in areas. A vapor barrier provides added protection to the floor system from moisture or dampness that can enter from ground.
Repairs are needed.

A qualified person should repair or replace as needed.



9.1 VENTILATION OF ATTIC AND FOUNDATION AREAS

 REPAIR OR REPLACE

1. Several foundation vents are loose and missing screens at the exterior. Rodents, reptiles or insects could enter into crawlspace. Repairs are needed.

A qualified person should repair or replace as needed.



9.1 Item 1 (Picture)



9.1 Item 2 (Picture)



9.1 Item 3 (Picture)



9.1 Item 4 (Picture)



9.1 Item 5 (Picture)

9.2 INSULATION IN ATTIC

 REPAIR OR REPLACE


(1)

1. Evidence of animal feces in the attic (above Living room). I was unable to determine if this was an active infestation. Sometimes pests can cause damage to home or components. Further investigation is needed.

A pest control company should inspect further and correct as needed.



9.2 Item 1 (Picture)



9.2 Item 2 (Picture)



9.2 Item 3 (Picture)

**9.2 Item 4 (Picture)**

(2)

1. Fiberglass (Batts) insulation in attic is missing in areas. Heat loss can occur more on this home than one that is properly insulated. Repairs are needed..

A qualified person should repair or replace as needed.

**9.2 Item 5 (Picture)****9.2 Item 6 (Picture)****9.2 Item 7 (Picture)****9.2 Item 8 (Picture)**

(3)

1. Fiberglass (Batts) insulation in attic is installed improperly under a roof line. This can Prematurely the shingles. Repairs are needed..

A qualified person should repair or replace as needed.



9.2 Item 9 (Picture)



9.2 Item 10 (Picture)

(4)

1. Fiberglass (loose-fill) insulation is is old and has settled, and less than six inches in thickness remains. in attic. Heat loss can occur more on this home than one that is properly insulated. Repairs are needed..

A qualified person should repair or replace as needed.




9.2 Item 11 (Picture)

9.3 INSULATION UNDER FLOOR SYSTEM

☑ REPAIR OR REPLACE

1. The insulation is loose/fallen in the crawlspace. Heat loss can occur more on this home than one that is properly insulated. Repairs are needed..

A qualified person should repair or replace as needed.



9.3 Item 1 (Picture)

9.4 ATTIC ACCESS

✓ INSPECTED

9.5 VENTING SYSTEMS (KITCHENS, BATHS AND LAUNDRY)

✓ INSPECTED

9.6 VENTILATION FANS AND THERMOSTATIC CONTROLS IN ATTIC

✓ NOT PRESENT

The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 10. BUILT-IN KITCHEN APPLIANCES

📋 DESCRIPTION

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

🔧 STYLES & MATERIALS: BUILT-IN KITCHEN APPLIANCES

Countertop:	Cabinetry:
Granite	Wood

👁️ ITEMS: BUILT-IN KITCHEN APPLIANCES

10.0 DISHWASHER


📋 REPAIR OR REPLACE

- (1)
1. The dishwasher rack is rusted in areas. Further deterioration will occur. I recommend repair as necessary.

I recommend contacting appliance repair company.



10.0 Item 1 (Picture)



10.0 Item 2 (Picture)

(2)

1. The dishwasher drain hose needs to be looped above the level of the kitchen sink drain or an approved air gap installed to prevent back flow of waste water into the water supply. (food safety issue) This can allow waste for the sink to contaminate the dishwasher. This is a small repair.

A qualified licensed plumber should repair or correct as needed.



10.0 Item 3 (Picture)



10.0 Item 4 (Picture)

10.1 RANGES/OVENS/COOKTOPS

REPAIR OR REPLACE

1. The range/oven needs to be properly attached/anchored to the structure as to keep it from tipping over when the oven door is opened and/or oven racks are pulled out during use. This is a safety issue. Repairs are needed.

I recommend contacting appliance repair company.



10.1 Item 1 (Picture)

10.2 RANGE HOOD (S)

REPAIR OR REPLACE

1. The light bulb for fan did not work when tested. I recommend repair or replace as needed.
I recommend contacting appliance repair company.



10.2 Item 1 (Picture)

10.3 FOOD WASTE DISPOSER

☑ INSPECTED

10.4 MICROWAVE COOKING EQUIPMENT

☑ NOT PRESENT

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.