



2023-06-26

Kevin Thomas
113 IVY HOLLOW LANE
MOORESVILLE, NC 28117

RE: Inspection Report for 113 Ivy Hollow Ln Mooresville NC 28117

Dear Kevin Thomas:

We are pleased to submit to you our electronic septic system inspection report for the work completed recently at your property. This report provides a summary of the work performed, a status update on any issues found, and includes recommendations specific to any issues requiring your attention.

The first page provides you with a summary of the inspection performed. Pages 2-6 of the report provides additional information, if applicable, for each section of your wastewater system.

We hope you will find this electronic summary report helpful in understanding the current status of your septic system. Detailed field notes are recorded and maintained in the office should you have any additional questions in regards to your inspection.

We appreciate the opportunity to serve you.

Sincerely,

TCW Wastewater Management, Inc.
5600 Lakeview Road
Charlotte, NC 28269



Summary

Kevin Thomas

113 Ivy Hollow Ln

Moorestville, NC 28117

(704) 799-7709

Inspection Date/Time: **04-28-2023 / 8:26 AM**

Technician: Blake Efird

System Type: LCPM-2/8

Observations


Septic Tank Inspection Results:	No action needed	Septic Tank needs pumping:	Cannot Evaluate
Pump Tank Inspection Results:	Action is needed	Pump Tank needs pumping:	Yes
Pressure Manifold Inspection Results:	No action needed		
Ground Absorption Inspection Results:	Action Recommended	Toilet testing dye strips left at house.	No
Distribution Inspection Results:	N/A	Bacteria packets left at house.	No
Status:	Non-Compliant	Root killer was added today.	No

Note: if "Action is Needed" on any of the above, please refer to the respective details section that follows this page.

Recommendations

Additional Notes:

System not fully evaluated. Please contact the office to schedule a visit. Again, riser needs to be replaced because the screw receivers are broken. Also the post that holds up the control box is rotted and still needs to be replaced. The conduit from the control box to the riser have come separated as well. Contact office for estimate. Recommend root killer. See all details below.



Beginning inspection with dirty filter



Ending Inspection

Septic Tank

Inspection Results: **No action needed**

Does the septic tank need pumping? Cannot Evaluate

Date of last pumping:

Scum level thickness (Inches on top of water): Not Evaluated

Sludge level thickness (Inches on bottom of tank): Not Evaluated

Is there possible storm water infiltrating the tank? Not Evaluated

Emergency tank storage (inches):
Above water level (Optimum 8" – 10") N/A



Filter screen clogging - %: Not Evaluated

Was the filter screen cleaned today? No

Recommendations:

Notes:

System not evaluated due to no response from homeowner



Inlet Sludge Level and Clean Filter


Pump Tank			
Inspection Results:		Action is needed	
Does the pump tank need pumping?		Yes	
Date of last pumping:		Is there possible storm water infiltrating into the tank?	
Daily wastewater dispersed: (if available, calculated through pump run time. Optimum < 250 GPD)		Yes	
Scum level thickness (on top of water):		Is the high water ALARM functioning properly today?	
0		Cannot Evaluate	
Sludge level thickness (on bottom of tank):		Is the effluent pump functioning today?	
5		Yes	
Are the electrical controls in good condition?		N/A	
Is the pump delivery rate within the acceptable range today?		Yes	
Recommendations:			
Notes:			
Again, riser needs to be replaced because the screw receivers are broken. Also the post that holds up the control box is rotted and still needs to be replaced. The conduit fr			
No Entry			

Pressure Manifold Assembly

Inspection Results:	No action needed		Is the vault is in good condition?	Marginal
			Are the valves and pipes in good condition?	Marginal
			Is there evidence of clogging in the discharge lines?	No evidence

Recommendations:

Notes:
Monitoring manifold lid. Vault was full of rain water at today's inspection so we could not see if the valve was still leaking. Will monitor for now



Ground Absorption Field

Inspection Results:

Action Recommended

Is the location of the absorption field On-site or Off-site?

Onsite

Is there evidence of effluent surfacing?

No

Are there low or settled areas in the field that need fill-in?

No

Is the vegetative covering over the field maintained adequately.

Yes

Recommendations:

Notes:

Still recommend starting our preventative root control program. The product is added to the pump tank at each inspection and helps control root intrusion in your drain lines. It can help avoid costly repairs in the future. Product does not harm trees, shrubs or grass. Cost is \$30 for the 2 applications at the regular inspections during the service year. Email or call office to approve. Didn't see any low areas at today's inspection

Low Pressure Distribution

Inspection Results:

N/A

Are the adjustment valves accessible?

N/A

Are the end of the laterals accessible?

N/A

Is each distribution lateral set with the proper pressure today?

N/A

Were all the system laterals flushed today?


N/A

Do the distribution laterals need cleaning or pressure jetting?


N/A

Recommendations

Notes



Panel Block System



Low Pressure Pipe System