



INSPECTION REPORT  
2094 Weldon Smith Rd  
Lawsonville NC 27022

INSPECTED BY  
Alex Parr 3692  
Above Parr Home  
Inspections

INSPECTION DATE  
📅 9/6/2024  
🕒 09:00:00 AM

*Michael A Parr*  
3692

INVOICE

Above Parr Home Inspections

Inspected By: Alex Parr 3692

Inspection Date: 9/6/2024  
Report ID: 090624AP1

| Customer Info:                                                                | Inspection Property:                         |
|-------------------------------------------------------------------------------|----------------------------------------------|
| Ronnie Rowe                                                                   | 2094 Weldon Smith Rd<br>Lawsonville NC 27022 |
| Customer's Real Estate Professional:<br>Will Sheppard<br>Will Sheppard Realty |                                              |

Inspection Fee:

| Service                   | Price  | Amount | Sub-Total |
|---------------------------|--------|--------|-----------|
| Inspection Fee            | 560.00 | 1      | 560.00    |
| WDI/Termite               | 75.00  | 1      | 75.00     |
| Radon – Ancillary Service | 150.00 | 1      | 150.00    |

Tax \$0.00

Total Price \$785.00

Payment Method: Check

Payment Status: Paid

Note:

## GENERAL INFO

**Property Address**

2094 Weldon Smith Rd  
Lawsonville NC 27022

**Date of Inspection**

9/6/2024

**Report ID**

090624AP1

**Customer(s)**

Ronnie Rowe

**Time of Inspection**

09:00:00 AM

**Real Estate Agent**

Will Sheppard  
Will Sheppard Realty

## INSPECTION DETAILS

**Approximate age of building:**

Over 10 Years

**In Attendance:**

Customer and their agent

**Radon Test:**

Yes

**Water Test:**

No

**Mold/Fungal Testing:**

No

**Wood Destroying Insect Report:**

No

**Type of building:**

Single Family (2 story)

## COMMENT KEY & DEFINITIONS

### Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

**Inspected (IN)** = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

**Not Inspected (NI)** = I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

**Not Present (NP)** = This item, component or unit is not in this home or building.

**Repair or Replace (RR)** = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

TABLE OF CONTENTS

---

Cover Page .....1

Invoice ..... 2

Intro Page ..... 3

Table of Contents ..... 4

General Summary ..... 5

1 Property Overview ..... 11

2 Roofing .....13

3 Exterior .....16

4 Structural Components ..... 21

5 Plumbing System ..... 23

6 Electrical System .....27

7 Heating / Central Air Conditioning ..... 30

8 Interiors ..... 33

9 Insulation and Ventilation ..... 35

10 Built-In Kitchen Appliances .....37

## GENERAL SUMMARY

---

### Above Parr Home Inspections

#### Customer

Ronnie Rowe

#### Address

2094 Weldon Smith Rd  
Lawsonville NC 27022

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling**; or **warrants further investigation by a specialist**, or **requires subsequent observation**. This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

**"This summary page is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your North Carolina real estate agent or an attorney."**

The summary page must describe any system or component of the home that does not function as intended, allowing for normal wear and tear that does not prevent the system or component from functioning as intended. The summary page must also describe any system or component that appears not to function as intended, based upon documented tangible evidence, and that requires either subsequent examination or further investigation by a specialist. The summary page may describe any system or component that poses a safety concern.

## 1. PROPERTY OVERVIEW

---

### 1.1 INSPECTION LIMITATIONS

#### REPAIR OR REPLACE

The home inspection was limited, one or more areas were not accessible due to the following conditions:

1. Furniture, storage and or personal items in the garage and throughout the house. As a result the areas were not inspected. Hidden damage may be present. Further investigation and repairs are needed.

We recommend having all personal items removed and these areas inspected prior to closing.

## 2. ROOFING

---

### 2.0 ROOF COVERINGS

#### REPAIR OR REPLACE

1. The roof shingles are damage and lose in areas. This damage should be repaired or replaced. Further investigation and repairs are needed.



A qualified contractor should inspect and repair as needed.



2.0 Item 1 (Picture)



2.0 Item 2 (Picture)




2.0 Item 3 (Picture)




2.0 Item 4 (Picture)




2.0 Item 5 (Picture)



2.0 Item 6 (Picture)



2.0 Item 7 (Picture)



2.0 Item 8 (Picture)



2.0 Item 9 (Picture)



2.0 Item 10 (Picture)



2.0 Item 11 (Picture)



2.0 Item 12 (Picture)

### 3. EXTERIOR

#### 3.4 DECKS, BALCONIES, STOOPS, STEPS, AREAWAYS, PORCHES, PATIO/COVER AND APPLICABLE RAILINGS

##### ☐ REPAIR OR REPLACE


1. The exterior girders for the wood deck appear to sag in the middle. I recommend having the deck evaluated to ensure that it is structurally sound. Further investigation and repairs are needed.



A qualified contractor should perform the work.



3.4 Item 1 (Picture)



3.4 Item 2 (Picture)


## 5. PLUMBING SYSTEM

### 5.2 PLUMBING WATER SUPPLY, DISTRIBUTION SYSTEM AND FIXTURES


#### ☐ REPAIR OR REPLACE

1. The shower at the guest bath in the basement has little to no water pressure. Therefore it did not function as intended. Further investigation and repairs are needed..

A qualified licensed plumber should repair or correct as needed.



5.2 Item 1 (Picture)



5.2 Item 2 (Picture)


### 5.3 PLUMBING DRAIN, WASTE AND VENT SYSTEMS

#### ☐ REPAIR OR REPLACE

(1)

1. The plumbing waste line leaks at the guest bath sink. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.3 Item 1 (Picture)



5.3 Item 2 (Picture)

(2)

1. The plumbing waste line is a S trap at the guest bath sink. A s-trap can gurgle struggling for air when draining water and sewer gases into the home. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.3 Item 3 (Picture)

(3)

1. The plumbing waste line drains slowly at the guest bath sink. A cause of a slow drain can range from a simple cleaning at stop valve or at the trap under sink. Sometimes the drain can be partially clogged down line. Further investigation and repairs are needed.

I am unable to determine the cause of the slow drain. A qualified licensed plumber should repair or correct as needed.



5.3 Item 4 (Picture)

## 6. ELECTRICAL SYSTEM

### 6.2 SERVICE AND GROUNDING EQUIPMENT, MAIN OVERCURRENT DEVICE, MAIN AND DISTRIBUTION PANELS



 REPAIR OR REPLACE

1. A generator hookup has been temporarily wired in the main electrical panel. There was not a dead man switch present. This is a safety issue. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.




6.2 Item 1 (Picture)



6.2 Item 2 (Picture)



6.2 Item 3 (Picture)




6.2 Item 4 (Picture)

#### 6.4 CONNECTED DEVICES AND FIXTURES (OBSERVED FROM A REPRESENTATIVE NUMBER OPERATION OF CEILING FANS, LIGHTING FIXTURES, SWITCHES AND RECEPTACLES LOCATED INSIDE THE HOUSE, GARAGE, AND ON THE DWELLING'S EXTERIOR WALLS)

 REPAIR OR REPLACE

1. At least one "three-prong" outlet is damaged in the living room. This is a safety issue. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 1 (Picture)



6.4 Item 2 (Picture)

#### 6.8 CARBON MONOXIDE DETECTORS

### ☐ REPAIR OR REPLACE

1. There is no carbon monoxide detector found in home. It is recommended that one be installed according to the manufacturer's instructions.

A qualified person should repair or replace as needed.

## 7. HEATING / CENTRAL AIR CONDITIONING

### 7.6 SOLID FUEL HEATING DEVICES (FIREPLACES, WOODSTOVE)

#### ☐ REPAIR OR REPLACE

1. The (Burn Area) for the woodstove at the basement living room is damage. This burn area should be fireproof. Any repairs should be performed according to the manufacturer's specifications. Repairs should be made so unit works properly. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



7.6 Item 1 (Picture)



7.6 Item 2 (Picture)



7.6 Item 3 (Picture)



7.6 Item 4 (Picture)

## 9. INSULATION AND VENTILATION

### 9.5 VENTING SYSTEMS (KITCHENS, BATHS AND LAUNDRY)

#### ☐ REPAIR OR REPLACE

1. The exhaust fan has a damaged vent cover outside at the master bath. This may allow water intrusion to occur. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



9.5 Item 1 (Picture)



9.5 Item 2 (Picture)

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge <http://www.HomeGauge.com> : Licensed To Alex Parr 3692

## ✓ RESULTS AT A GLANCE

74

✓ ITEMS INSPECTED

Total number in report.

12

📄 SUMMARY COMMENTS

Total number in report.

61

📷 PHOTOS

Total number in report.

## 🏠 1. PROPERTY OVERVIEW



## STYLES & MATERIALS: PROPERTY OVERVIEW

**Temperature:**

Over 65 (F) = 18 (C)

**Weather:**

Clear

**Rain in last 3 days:**

No

## ITEMS: PROPERTY OVERVIEW

### 1.0 SUBJECT PROPERTY PROSPECTIVE

 INSPECTED

### 1.1 INSPECTION LIMITATIONS

 REPAIR OR REPLACE

The home inspection was limited, one or more areas were not accessible due to the following conditions:

1. Furniture, storage and or personal items in the garage and throughout the house. As a result the areas were not inspected. Hidden damage may be present. Further investigation and repairs are needed.

We recommend having all personal items removed and these areas inspected prior to closing.

### 1.2 RADON TESTING

 INSPECTED



🏠 2. ROOFING

📋 DESCRIPTION

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

🔧 STYLES & MATERIALS: ROOFING

|                                        |                                     |                                                  |
|----------------------------------------|-------------------------------------|--------------------------------------------------|
| <b>Roof Covering:</b><br>Architectural | <b>Age:</b><br>Original             | <b>Viewed roof covering from:</b><br>Walked roof |
| <b>Sky Light(s):</b><br>None           | <b>Chimney (exterior):</b><br>Brick | <b>Roof-Type:</b><br>Gable                       |


👁️ ITEMS: ROOFING

2.0 ROOF COVERINGS

📋 REPAIR OR REPLACE

1. The roof shingles are damage and lose in areas. This damage should be repaired or replaced.  
Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



2.0 Item 1 (Picture)




2.0 Item 2 (Picture)



2.0 Item 3 (Picture)




2.0 Item 4 (Picture)




2.0 Item 5 (Picture)



2.0 Item 6 (Picture)



2.0 Item 7 (Picture)



2.0 Item 8 (Picture)



2.0 Item 9 (Picture)



2.0 Item 10 (Picture)



2.0 Item 11 (Picture)



2.0 Item 12 (Picture)

## 2.1 FLASHINGS

✓ INSPECTED

## 2.2 SKYLIGHTS, CHIMNEYS AND ROOF PENETRATIONS

✓ REPAIR OR REPLACE

1. The chimney crown is crack and deteriorate. This can cause deterioration of mortar, loose bricks, other structural problems and water intrusion to occur. Further investigation and repairs are needed.

I recommend a chimney sweep inspect and repairs what is deemed necessary.



2.2 Item 1 (Picture)



2.2 Item 2 (Picture)



2.2 Item 3 (Picture)

## 2.3 ROOF DRAINAGE SYSTEMS

✓ INSPECTED

*The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but*



*sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*

 3. EXTERIOR



 DESCRIPTION

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

 STYLES & MATERIALS: EXTERIOR

|                                                                                 |                                         |                                                                  |
|---------------------------------------------------------------------------------|-----------------------------------------|------------------------------------------------------------------|
| <b>Siding Style:</b><br>Brick                                                   | <b>Siding Material:</b><br>Brick veneer | <b>Exterior Entry Doors:</b><br>Wood<br>Steel<br>Insulated glass |
| <b>Appurtenance:</b><br>Deck with steps<br>Balcony<br>Covered porch<br>Sidewalk | <b>Driveway:</b><br>Concrete<br>Gravel  |                                                                  |

 ITEMS: EXTERIOR


3.0 WALL CLADDING FLASHING AND TRIM

 REPAIR OR REPLACE




1. I observed small cracks in the brick veneer at the exterior. These are typical in nature due to age and normal masonry shrinkage. Although the cracks in the brick veneer are typical, these areas should be re sealed to prevent any water penetration or damage. Further evaluation by a qualified masonry contractor is recommended for this entire condition.

I recommend repair or replace using a qualified contractor.



3.0 Item 1 (Picture)



3.0 Item 2 (Picture)



3.0 Item 3 (Picture)

### 3.1 EAVES, SOFFITS AND FASCIAS

✓ INSPECTED

### 3.2 WINDOWS


✓ INSPECTED

### 3.3 DOORS (EXTERIOR)

✓ REPAIR OR REPLACE

1. The side entry door deadbolt does not latch properly. As a result the door will not lock properly. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



3.3 Item 1 (Picture)

### 3.4 DECKS, BALCONIES, STOOPS, STEPS, AREAWAYS, PORCHES, PATIO/COVER AND APPLICABLE RAILINGS


✗ REPAIR OR REPLACE

1. The exterior girders for the wood deck appear to sag in the middle. I recommend having the deck evaluated to ensure that it is structurally sound. Further investigation and repairs are needed.

A qualified contractor should perform the work.



3.4 Item 1 (Picture)



3.4 Item 2 (Picture)

### 3.5 VEGETATION, GRADING, DRAINAGE, DRIVEWAYS, PATIO FLOOR, WALKWAYS AND RETAINING WALLS (WITH RESPECT TO THEIR EFFECT ON THE CONDITION OF THE BUILDING)

#### ✓ REPAIR OR REPLACE

(1)

1. The retaining wall at the front of the home has evidence of movement. There was not a drain located at the time of inspection. Further deterioration may occur. Repairs are recommended.

A qualified contractor should inspect and repair as needed.



3.5 Item 1 (Picture)



3.5 Item 2 (Picture)



3.5 Item 3 (Picture)



3.5 Item 4 (Picture)



3.5 Item 5 (Picture)

(2)

1. The concrete driveway has cracks that should be sealed to prevent further damage, which is part of ongoing maintenance of a concrete driveway that will need to be performed on a regular basis. Repairs are recommended.

A qualified contractor should inspect and repair as needed.




**3.5 Item 6 (Picture)**

(3)

1. There is a negative slope at the front of home and can cause or contribute to water intrusion or deterioration. I recommend correcting landscape to drain water away from home. Repairs are recommended.

A qualified contractor should inspect and repair as needed.



**3.5 Item 7 (Picture)**

---

### 3.6 GARAGE DOOR (S)

☑ INSPECTED

---

### 3.7 GARAGE DOOR OPERATORS (REPORT WHETHER OR NOT DOORS WILL REVERSE WHEN MET WITH RESISTANCE)

☑ INSPECTED

---

### 3.8 GARAGE WALLS (INCLUDING FIREWALL SEPARATION)

☑ INSPECTED

---

### 3.9 OCCUPANT DOOR (FROM GARAGE TO INSIDE OF HOME)

☑ INSPECTED

---

### 3.10 GARAGE FLOOR

---



 INSPECTED

---

*The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*

## 4. STRUCTURAL COMPONENTS

### DESCRIPTION

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

### STYLES & MATERIALS: STRUCTURAL COMPONENTS

**Foundation:**

Poured concrete

**Method used to observe**
**Crawlspace:**

No crawlspace

**Floor Structure:**

Slab

**Wall Structure:**

Wood

**Columns or Piers:**

Supporting walls

**Ceiling Structure:**

2X4

**Roof Structure:**

Engineered wood trusses

### ITEMS: STRUCTURAL COMPONENTS

#### 4.0 WALLS (STRUCTURAL)

 INSPECTED

#### 4.1 COLUMNS OR PIERS

 INSPECTED

#### 4.2 FLOORS (STRUCTURAL)

 INSPECTED

#### 4.3 CEILINGS (STRUCTURAL)


 INSPECTED

#### 4.4 ROOF STRUCTURE AND ATTIC

 REPAIR OR REPLACE

1. The attic stairs is missing insulation. This can cause some heat loss in winter and loss of cool air in summer if not corrected. Repairs are needed.

A qualified person should repair or replace as needed.



4.4 Item 1 (Picture)

#### 4.5 WOOD DETERIORATION

✓ INSPECTED

#### 4.6 FOUNDATIONS, BASEMENT AND CRAWLSPACE (REPORT SIGNS OF ABNORMAL OR HARMFUL WATER PENETRATION INTO THE BUILDING OR SIGNS OF ABNORMAL OR HARMFUL CONDENSATION ON BUILDING COMPONENTS.)

✓ REPAIR OR REPLACE

1. White efflorescence (powder substance) on block wall indicates moisture is in contact with the masonry. This does not necessarily indicate that intrusion will occur. I recommend checking the gutters and the downspout drain lines for proper operation. Also, a water proofing paint could be applied to the interior side of the block if necessary. Efflorescence is found on many homes without water intrusion occurring inside the home. But, it should alert you to the possibility that future steps may be needed.



4.6 Item 1 (Picture)



4.6 Item 2 (Picture)

*The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*



## 🏠 5. PLUMBING SYSTEM

### 📋 DESCRIPTION

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.



Complimentary photo of the water heater



Complimentary photo of the water heater

### ✂️ STYLES & MATERIALS: PLUMBING SYSTEM

#### Water Source:

Well

#### Water Filters:

None

#### Plumbing Water Supply (into home):

Pex

#### Plumbing Water Distribution (inside home):

PEX

#### Washer Drain Size:

2" Diameter

#### Plumbing Waste:

PVC

#### Water Heater Power Source:

Electric

#### Water Heater Capacity:

50 Gallon (2-3 people)  
Two units

#### Manufacturer:

RHEEM

#### Water Heater Location:

Basement

### 👁️ ITEMS: PLUMBING SYSTEM

## 5.0 MAIN WATER SHUT-OFF DEVICE (DESCRIBE LOCATION)

✓ INSPECTED

The main shut off is the black knob located in the basement. This is for your information.



5.0 Item 1 (Picture)

---

## 5.1 HOT WATER SYSTEMS, CONTROLS, CHIMNEYS, FLUES AND VENTS

✓ INSPECTED


---

## 5.2 PLUMBING WATER SUPPLY, DISTRIBUTION SYSTEM AND FIXTURES

📋 REPAIR OR REPLACE

1. The shower at the guest bath in the basement has little to no water pressure. Therefore it did not function as intended. Further investigation and repairs are needed..

A qualified licensed plumber should repair or correct as needed.



5.2 Item 1 (Picture)



5.2 Item 2 (Picture)

---

## 5.3 PLUMBING DRAIN, WASTE AND VENT SYSTEMS

📋 REPAIR OR REPLACE

(1)

1. The plumbing waste line leaks at the guest bath sink. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.3 Item 1 (Picture)



5.3 Item 2 (Picture)

(2)

1. The plumbing waste line is a S trap at the guest bath sink. A s-trap can gurgle struggling for air when draining water and sewer gases into the home. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.




5.3 Item 3 (Picture)

(3)

1. The plumbing waste line drains slowly at the guest bath sink. A cause of a slow drain can range from a simple cleaning at stop valve or at the trap under sink. Sometimes the drain can be partially clogged down line. Further investigation and repairs are needed.

I am unable to determine the cause of the slow drain. A qualified licensed plumber should repair or correct as needed.



5.3 Item 4 (Picture)

#### 5.4 SINKS, FIXTURES, AND TOILETS

✓ INSPECTED

---

#### 5.5 SHOWER/TUB & TILE WALLS

✓ INSPECTED

---

#### 5.6 FUEL STORAGE AND DISTRIBUTION SYSTEMS (INTERIOR FUEL STORAGE, PIPING, VENTING, SUPPORTS, LEAKS)

✓ INSPECTED

---

*The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*




🏠 6. ELECTRICAL SYSTEM

☰ DESCRIPTION

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.



Complimentary photo of the electric panel with the cover off



Complimentary photo of the sub panel with the cover off

✂ STYLES & MATERIALS: ELECTRICAL SYSTEM

|                                                                             |                                             |                                        |
|-----------------------------------------------------------------------------|---------------------------------------------|----------------------------------------|
| <b>Electrical Service</b><br><b>Conductors:</b><br>Below ground<br>Aluminum | <b>Panel capacity:</b><br>200 AMP           | <b>Panel Type:</b><br>Circuit breakers |
| <b>Electric Panel Manufacturer:</b><br>SIEMENS                              | <b>Branch wire 15 and 20 AMP:</b><br>Copper | <b>Wiring Methods:</b><br>Romex        |

🔍 ITEMS: ELECTRICAL SYSTEM

## 6.0 LOCATION OF MAIN AND DISTRIBUTION PANELS

✓ INSPECTED

The main panel box is located at the outside.

## 6.1 SERVICE ENTRANCE CONDUCTORS

✓ INSPECTED

## 6.2 SERVICE AND GROUNDING EQUIPMENT, MAIN OVERCURRENT DEVICE, MAIN AND DISTRIBUTION PANELS


📋 REPAIR OR REPLACE

1. A generator hookup has been temporarily wired in the main electrical panel. There was not a dead man switch present. This is a safety issue. Further investigation and repairs are needed.


A qualified licensed electrical contractor should correct as needed.




6.2 Item 1 (Picture)



6.2 Item 2 (Picture)



6.2 Item 3 (Picture)



6.2 Item 4 (Picture)

## 6.3 BRANCH CIRCUIT CONDUCTORS, OVERCURRENT DEVICES AND COMPATABILITY OF THEIR AMPERAGE AND VOLTAGE

✓ INSPECTED

## 6.4 CONNECTED DEVICES AND FIXTURES (OBSERVED FROM A REPRESENTATIVE NUMBER OPERATION OF CEILING FANS, LIGHTING FIXTURES, SWITCHES AND RECEPTACLES LOCATED INSIDE THE HOUSE, GARAGE, AND ON THE DWELLING'S EXTERIOR WALLS)

📋 REPAIR OR REPLACE

1. At least one "three-prong" outlet is damaged in the living room. This is a safety issue. Further

investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 1 (Picture)



6.4 Item 2 (Picture)

## 6.5 POLARITY AND GROUNDING OF RECEPTACLES WITHIN 6 FEET OF INTERIOR PLUMBING FIXTURES, ALL RECEPTACLES IN GARAGE, CARPORT AND EXTERIOR WALLS OF INSPECTED STRUCTURE

✓ INSPECTED

## 6.6 OPERATION OF GFCI (GROUND FAULT CIRCUIT INTERRUPTERS)

✓ INSPECTED

## 6.7 SMOKE DETECTORS

✓ INSPECTED

## 6.8 CARBON MONOXIDE DETECTORS

✗ REPAIR OR REPLACE

1. There is no carbon monoxide detector found in home. It is recommended that one be installed according to the manufacturer's instructions.


A qualified person should repair or replace as needed.

*The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*



🏠 7. HEATING / CENTRAL AIR CONDITIONING

📋 DESCRIPTION

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.



Complimentary photo of the heat pump



Complimentary photo of the heat pump



Complimentary photo of the heat pump

✂ STYLES & MATERIALS: HEATING / CENTRAL AIR CONDITIONING

**Heat Type:**

Heat Pump Forced Air (also provides cool air)

**Energy Source:**

Electric

**Ductwork:**

Insulated

**Number of Woodstoves:**

**Heating Age:**

Original  
10-15 yrs

**Operated:**

Units Operated

**Types of Fireplaces:**

Vented gas logs

**Cooling Equipment Type:**

**Number of Heat Systems (excluding wood):**

Two

**Heat System Brand:**

PAYNE

**Operable Fireplaces:**

One

**Air Conditioning Age:**



One

Heat Pump Forced Air (also  
provides warm air)Original  
10–15 yrs**Cooling Equipment Energy  
Source:**  
Electricity**Central Air Manufacturer:**  
PAYNE**Number of AC Only Units:**  
Two ITEMS: HEATING / CENTRAL AIR CONDITIONING

## 7.0 HEATING EQUIPMENT

 INSPECTED

## 7.1 NORMAL OPERATING CONTROLS

 INSPECTED

## 7.2 AUTOMATIC SAFETY CONTROLS

 INSPECTED7.3 DISTRIBUTION SYSTEMS (INCLUDING FANS, PUMPS, DUCTS AND PIPING, WITH SUPPORTS,  
INSULATION, AIR FILTERS, REGISTERS, RADIATORS, FAN COIL UNITS AND CONVECTORS) INSPECTED

## 7.4 PRESENCE OF INSTALLED HEAT SOURCE IN EACH ROOM

 INSPECTED

## 7.5 CHIMNEYS, FLUES AND VENTS (FOR FIREPLACES, GAS WATER HEATERS OR HEAT SYSTEMS)

 INSPECTED

## 7.6 SOLID FUEL HEATING DEVICES (FIREPLACES, WOODSTOVE)

 REPAIR OR REPLACE

1. The (Burn Area) for the woodstove at the basement living room is damage. This burn area should be fireproof. Any repairs should be performed according to the manufacturer's specifications. Repairs should be made so unit works properly. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



7.6 Item 1 (Picture)



7.6 Item 2 (Picture)



7.6 Item 3 (Picture)



7.6 Item 4 (Picture)

---

## 7.7 GAS/LP FIRELOGS AND FIREPLACES

☑ INSPECTED

---

## 7.8 COOLING AND AIR HANDLER EQUIPMENT

☑ INSPECTED

---

## 7.9 NORMAL OPERATING CONTROLS

☑ INSPECTED

---

## 7.10 PRESENCE OF INSTALLED COOLING SOURCE IN EACH ROOM

☑ INSPECTED

*The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*

 8. INTERIORS

 DESCRIPTION

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

 STYLES & MATERIALS: INTERIORS

|                                                |                                                    |                                                                                |
|------------------------------------------------|----------------------------------------------------|--------------------------------------------------------------------------------|
| <b>Ceiling Materials:</b><br>Drywall           | <b>Wall Material:</b><br>Drywall                   | <b>Floor Covering(s):</b><br>Area rug<br>Carpet<br>Vinyl Plank<br>Tile<br>Wood |
| <b>Interior Doors:</b><br>Raised panel<br>Wood | <b>Window Types:</b><br>Thermal/Insulated<br>Fixed |                                                                                |

 ITEMS: INTERIORS

8.0 CEILINGS

 INSPECTED

8.1 WALLS

 INSPECTED

8.2 FLOORS

 INSPECTED

8.3 STEPS, STAIRWAYS, BALCONIES AND RAILINGS

 INSPECTED

8.4 COUNTERS AND CABINETS (REPRESENTATIVE NUMBER)

 INSPECTED

8.5 DOORS (REPRESENTATIVE NUMBER)


 REPAIR OR REPLACE

1.

The privacy door rubs floor when opened. Door needs to be trimmed at bottom by a skilled

craftsman at the master bath. As a result the door will not close properly. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



8.5 Item 1 (Picture)

---

## 8.6 WINDOWS (REPRESENTATIVE NUMBER)

☑ INSPECTED

*The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*



## 9. INSULATION AND VENTILATION

### DESCRIPTION

The home inspector shall observe: Insulation and vapor retarders in unfinished spaces; Ventilation of attics and foundation areas; Kitchen, bathroom, and laundry venting systems; and the operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control. The home inspector shall describe: Insulation in unfinished spaces; and Absence of insulation in unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evidence indicates the need to do so; and Move insulation where chimneys penetrate roofs, where plumbing drain/waste pipes penetrate floors, adjacent to earth filled stoops or porches, and at exterior doors. The home inspector is not required to report on: Concealed insulation and vapor retarders; or Venting equipment that is integral with household appliances.

### STYLES & MATERIALS: INSULATION AND VENTILATION

**Attic info:**

Scuttle hole  
Pull Down stairs

**Method used to observe attic:**

From entry

**Attic Insulation:**

Blown  
Batt  
Fiberglass

**Ventilation:**

Ridge vents  
Soffit Vents

**Exhaust Fans:**

Fan

**Dryer Power Source:**

220 Electric

**Dryer Vent:**

Metal

**Floor System Insulation:**

NONE

### ITEMS: INSULATION AND VENTILATION

#### 9.0 VAPOR RETARDERS (IN CRAWLSPACE OR BASEMENT)

 NOT PRESENT

#### 9.1 VENTILATION OF ATTIC AND FOUNDATION AREAS

 INSPECTED

#### 9.2 INSULATION IN ATTIC

 INSPECTED

#### 9.3 INSULATION UNDER FLOOR SYSTEM

 NOT PRESENT

#### 9.4 ATTIC ACCESS

 INSPECTED

#### 9.5 VENTING SYSTEMS (KITCHENS, BATHS AND LAUNDRY)


 REPAIR OR REPLACE

1. The exhaust fan has a damaged vent cover outside at the master bath. This may allow water intrusion to occur. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



9.5 Item 1 (Picture)



9.5 Item 2 (Picture)

---

## 9.6 VENTILATION FANS AND THERMOSTATIC CONTROLS IN ATTIC

 NOT PRESENT

*The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*

## 🏠 10. BUILT-IN KITCHEN APPLIANCES

### 📋 DESCRIPTION

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

### 🔧 STYLES & MATERIALS: BUILT-IN KITCHEN APPLIANCES

#### Countertop:

Wood

#### Cabinetry:

Wood

### 👁️ ITEMS: BUILT-IN KITCHEN APPLIANCES

#### 10.0 DISHWASHER

##### ✅ REPAIR OR REPLACE

1. The dishwasher drain hose needs to be looped above the level of the kitchen sink drain or an approved air gap installed to prevent back flow of waste water into the water supply. (food safety issue) This can allow waste for the sink to contaminate the dishwasher. This is a small repair.

A qualified licensed plumber should repair or correct as needed.



10.0 Item 1 (Picture)

#### 10.1 RANGES/OVENS/COOKTOPS

##### ✅ INSPECTED

#### 10.2 RANGE HOOD (S)

##### ✅ INSPECTED

#### 10.3 MICROWAVE COOKING EQUIPMENT

##### ✅ INSPECTED

*The built-in appliances of the home were inspected and reported on with the above information. While the*

*inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.*