



INSPECTION REPORT
215 Bethesda Rd
Statesville NC 28677

INSPECTED BY
Alex Parr 3692
Above Parr Home
Inspections

INSPECTION DATE
📅 4/25/2025
🕒 09:00:00 AM

Michael A Parr
3692

INVOICE

Above Parr Home Inspections

Inspected By: Alex Parr 3692

Inspection Date: 4/25/2025
Report ID: 042525AP1

Customer Info:	Inspection Property:
Gail Burton Customer's Real Estate Professional: Will Sheppard Will Sheppard Realty	215 Bethesda Rd Statesville NC 28677

Inspection Fee:

Service	Price	Amount	Sub-Total
Inspection Fee	625.00	1	625.00
WDI/Termite	75.00	1	75.00
Inspection Discount	-75.00	1	-75.00

Tax \$0.00

Total Price \$625.00

Payment Method: Credit Card

Payment Status: Paid

Note:

GENERAL INFO

Property Address

215 Bethesda Rd
Statesville NC 28677

Date of Inspection

4/25/2025

Report ID

O42525AP1

Customer(s)

Gail Burton

Time of Inspection

09:00:00 AM

Real Estate Agent

Will Sheppard
Will Sheppard Realty

INSPECTION DETAILS

Approximate age of building:

Over 25 Years

In Attendance:

Customer representative

Radon Test:

No

Water Test:

No

Mold/Fungal Testing:

No

Wood Destroying Insect Report:

Yes

Type of building:

Single Family (1 story)

COMMENT KEY & DEFINITIONS

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

Inspected (IN) = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI) = I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

TABLE OF CONTENTS

Cover Page1

Invoice 2

Intro Page 3

Table of Contents 4

General Summary 5

1 Property Overview 24

2 Roofing27

3 Exterior 30

4 Structural Components37

5 Plumbing System41

6 Electrical System 46

7 Heating / Central Air Conditioning50

8 Interiors 54

9 Insulation and Ventilation 58

10 Built-In Kitchen Appliances 62

GENERAL SUMMARY

Above Parr Home Inspections

Customer

Gail Burton

Address

215 Bethesda Rd
Statesville NC 28677

The following items or discoveries indicate that these systems or components **do not function as intended or adversely affects the habitability of the dwelling; or warrants further investigation by a specialist, or requires subsequent observation.** This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

"This summary page is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your North Carolina real estate agent or an attorney."

The summary page must describe any system or component of the home that does not function as intended, allowing for normal wear and tear that does not prevent the system or component from functioning as intended. The summary page must also describe any system or component that appears not to function as intended, based upon documented tangible evidence, and that requires either subsequent examination or further investigation by a specialist. The summary page may describe any system or component that poses a safety concern.

1. PROPERTY OVERVIEW

1.0 SUBJECT PROPERTY PROSPECTIVE

REPAIR OR REPLACE

(1)

1. The home is in distressed condition. We make every attempt to find major issues with the home. Due to the extent of the damage not all items may be found during the inspection this no destructive testing was performed during the inspection. Additional damage to the structure may be found during renovations of the property. Further investigation is needed.

We recommend contacting a licensed contractor regarding these conditions and having repairs made as deemed appropriate.


(2)

1. Discoloration in some type of fungal growth (wood destroying fungus) is present in the structure at several areas including but not limited to the crawl space and or interior spaces. This type of substance commonly results in the building and finish type materials becoming weakened and or compromised. Evidence suggests that this condition is from a past or present elevated moisture

conditions. The extent of the damage cannot be determined until the moisture issue is corrected. We did not inspect, test or determine if this type of substance is or is not a health hazard as this is above the scope of a home inspection. We recommend contacting a licensed expert for testing, investigation and or correction as deemed appropriate




1.0 Item 1 (Picture)



1.0 Item 2 (Picture)



1.0 Item 3 (Picture)



1.0 Item 4 (Picture)




1.0 Item 5 (Picture)

1.1 INSPECTION LIMITATIONS


REPAIR OR REPLACE

1. The panel cover was not removed because the panel cover was painted to sheetrock. Removal would have damaged sheetrock. Further investigation is needed.

A qualified licensed electrical contractor should correct as needed.



1.1 Item 1 (Picture)



1.1 Item 2 (Picture)

2. ROOFING

2.2 SKYLIGHTS, CHIMNEYS AND ROOF PENETRATIONS


REPAIR OR REPLACE

1. The plumbing boot has signs of temporary repair. This may allow water intrusion to occur. Further investigation and repairs are needed..

A qualified contractor should repair or replace as needed.



2.2 Item 1 (Picture)



2.2 Item 2 (Picture)

2.3 ROOF DRAINAGE SYSTEMS

REPAIR OR REPLACE

(1)

1. The gutter at the front (left of main entry) has been installed improperly behind the siding. This may allow water damage to occur to the home. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



2.3 Item 1 (Picture)



2.3 Item 2 (Picture)

(2)

1. The gutter is loose at the front (left of main entry). Gutters that drain poorly or clogged can lead to many costly problems such as deterioration of fascia, soffit or roof edge. It can also cause gutters to pull loose and lead to possible water intrusion. Repairs are needed.

A qualified contractor should inspect and repair as needed.



2.3 Item 3 (Picture)



2.3 Item 4 (Picture)

3. EXTERIOR

3.0 WALL CLADDING FLASHING AND TRIM

☐ REPAIR OR REPLACE

(1)


1. The vinyl siding at the exterior in areas is damaged. Further deterioration can occur if not corrected.

Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.




3.0 Item 1 (Picture)



3.0 Item 2 (Picture)



3.0 Item 3 (Picture)



3.0 Item 4 (Picture)



3.0 Item 5 (Picture)




3.0 Item 6 (Picture)



3.0 Item 7 (Picture)



3.0 Item 8 (Picture)



3.0 Item 9 (Picture)



3.0 Item 10 (Picture)



3.0 Item 11 (Picture)



3.0 Item 12 (Picture)



3.0 Item 13 (Picture)



3.0 Item 14 (Picture)




3.0 Item 15 (Picture)

(2)

1. Siding in contact with ground at front of home. Because the siding is in contact with ground it is possible for framing to be deteriorated. We did not inspect behind this siding. Recommend a ground clearance of six to eight inches where possible. Repairs are needed.

A qualified contractor should inspect and repair as needed.



3.0 Item 16 (Picture)


3.3 DOORS (EXTERIOR)

☐ REPAIR OR REPLACE

(1)

1. The right side (facing front) entry door dead bolt is keyed. (Safety issue) All exterior doors should not be keyed type locks, as this can impede exiting the home should a fire occur. Repairs are needed.

A qualified person should repair or replace as needed.



3.3 Item 1 (Picture)

(2)

1. The entry door at front of home is deteriorated at bottom of jamb (s) and at the door. Further


deterioration may occur if not repaired. Repairs are needed.
A qualified contractor should inspect and repair as needed.

**3.3 Item 2 (Picture)****3.3 Item 3 (Picture)****3.3 Item 4 (Picture)****3.3 Item 5 (Picture)**

(5)

1. The access door to the crawlspace has damaged hinged hardware. Therefore the door does not function as intended. Repairs are needed.

A qualified contractor should inspect and repair as needed.

**3.3 Item 8 (Picture)****3.3 Item 9 (Picture)**

3.4 DECKS, BALCONIES, STOOPS, STEPS, AREAWAYS, PORCHES, PATIO/COVER AND APPLICABLE RAILINGS

REPAIR OR REPLACE

(1)

1. The brick steps at front entry are damaged and missing bricks. A fall or injury could occur if not corrected. A repair or replacement is needed.

A qualified contractor should repair or replace as needed.



3.4 Item 1 (Picture)



3.4 Item 2 (Picture)

3.5 VEGETATION, GRADING, DRAINAGE, DRIVEWAYS, PATIO FLOOR, WALKWAYS AND RETAINING WALLS (WITH RESPECT TO THEIR EFFECT ON THE CONDITION OF THE BUILDING)

☐ REPAIR OR REPLACE

1. There is a negative slope at the left side (facing front) and rear, this can cause or contribute to water intrusion or deterioration. I recommend correcting landscape to drain water away from home. Further investigation and repairs are needed.

A qualified contractor should repair or replace as needed.



3.5 Item 1 (Picture)



3.5 Item 2 (Picture)

4. STRUCTURAL COMPONENTS

4.2 FLOORS (STRUCTURAL)

☐ REPAIR OR REPLACE

1. The slab foundation at the rear of the home is damaged. Further damaged/deterioration could occur. Further investigation and repairs are needed.

A qualified licensed general contractor should inspect further and repair as needed.



4.2 Item 1 (Picture)



4.2 Item 2 (Picture)

4.4 ROOF STRUCTURE AND ATTIC

☐ REPAIR OR REPLACE

(1)

1. The roof sheathing bowed. Repairs are needed to maintain the stability of roof. This may allow water intrusion to occur. Further investigation and repairs are needed.


A qualified contractor should repair as needed.



4.4 Item 1 (Picture)



4.4 Item 2 (Picture)




4.4 Item 3 (Picture)

(2)

1. The truss system installed in the attic have been damage during or before installation of the truss. All truss repairs should be repaired via an approved method specified b the manufacture and or approved and stamped by licensed structural engineer. Further evaluation and repairs are needed.

A qualified licensed structural engineer/design professional is recommended to evaluate the trusses for any repairs. This should include a site specific letter from the registered design professional/engineer stating what repairs (if any) are needed approval of performed repairs, signature, state license number, and state registered stamp of the engineer.



4.4 Item 4 (Picture)



4.4 Item 5 (Picture)

4.5 WOOD DETERIORATION

☐ REPAIR OR REPLACE

1. Wood debris is in contact with the crawl space floor in numerous areas. This can attract wood destroying organisms. Removal is needed.

A qualified contractor should inspect and repair as needed.



4.5 Item 1 (Picture)




4.5 Item 2 (Picture)

4.6 FOUNDATIONS, BASEMENT AND CRAWLSPACE (REPORT SIGNS OF ABNORMAL OR HARMFUL WATER PENETRATION INTO THE BUILDING OR SIGNS OF ABNORMAL OR HARMFUL CONDENSATION ON BUILDING COMPONENTS.)

☐ REPAIR OR REPLACE

1. Visible signs of water intrusion in the crawl space are present from standing water on ground. Water intrusion if not corrected can lead to other problems including mold and cause excessive moisture to floor system that can lead to deterioration and increased repair cost. Further investigation and repairs are needed.

I recommend further investigation or correction by a qualified licensed contractor or water infiltration specialist.



4.6 Item 1 (Picture)



4.6 Item 2 (Picture)

5. PLUMBING SYSTEM


5.1 HOT WATER SYSTEMS, CONTROLS, CHIMNEYS, FLUES AND VENTS

☐ REPAIR OR REPLACE

(1)

1. The water heater does not appear to have proper fresh air supply. This is a safety issue. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



5.1 Item 1 (Picture)



5.1 Item 2 (Picture)



5.1 Item 3 (Picture)



5.1 Item 4 (Picture)

(2)

1. The draft hood connection to flue vent connector: provide at least 12" vertical inches of the flue vent between the draft hood outlet and the first elbow. This is a safety issue and should be repaired. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.1 Item 5 (Picture)

5.2 PLUMBING WATER SUPPLY, DISTRIBUTION SYSTEM AND FIXTURES

☐ REPAIR OR REPLACE

(1)

1. The tub faucets and hot/cold control loose in wall at the guest bath. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed..

A qualified licensed plumber should repair or correct as needed.



5.2 Item 1 (Picture)



5.2 Item 2 (Picture)

(2)

1. The toilet tank is loose at the master bathroom. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed..

A qualified licensed plumber should repair or correct as needed.



5.2 Item 3 (Picture)

(3)

1. Polybutylene plastic plumbing supply lines (PB) are installed in the subject house. Polybutylene has been used in this area for many years, but has had a higher than normal failure rate, and is no longer being widely used. Copper and Brass fittings used in later years have apparently reduced the failure rate. This subject house has copper fittings. For further details contact the Consumer Plumbing Recovery center at 1-800-392-7591 or the web at <http://www.pbpipe.com>



5.2 Item 4 (Picture)


5.3 PLUMBING DRAIN, WASTE AND VENT SYSTEMS

📋 REPAIR OR REPLACE

(1)

1. The plumbing waste line leaks under the kitchen sink. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.3 Item 1 (Picture)



5.3 Item 2 (Picture)

6. ELECTRICAL SYSTEM

6.1 SERVICE ENTRANCE CONDUCTORS


☐ REPAIR OR REPLACE

1. The electrical service meter has an opening at the bottom. This is a safety issue. Further investigation and repairs are needed.

I recommend a licensed electrical contractor inspect further and correct as needed.



6.1 Item 1 (Picture)



6.1 Item 2 (Picture)

6.4 CONNECTED DEVICES AND FIXTURES (OBSERVED FROM A REPRESENTATIVE NUMBER OPERATION OF CEILING FANS, LIGHTING FIXTURES, SWITCHES AND RECEPTACLES LOCATED INSIDE THE HOUSE, GARAGE, AND ON THE DWELLING'S EXTERIOR WALLS)

☐ REPAIR OR REPLACE


(1)

1. Several open splices needs placing inside a box with a cover-plate in the attic space. Electrical issues are considered a hazard until repaired. Further investigation and repair are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 1 (Picture)



6.4 Item 2 (Picture)

(2)

1. At least one "three-prong" outlet is loose in wall in the living room. Electrical issues are considered a hazard until repaired. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 3 (Picture)




6.4 Item 4 (Picture)

(3)

1. One or more "three-prong" outlet is wired incorrectly "hot / neutral reversed" in the bedroom. Electrical issues are considered a hazard until repaired. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 5 (Picture)




6.4 Item 6 (Picture)

6.6 OPERATION OF GFCI (GROUND FAULT CIRCUIT INTERRUPTERS)

REPAIR OR REPLACE

1. The GFCI (Ground Fault Circuit Interrupter) outlet at the Washer/Dryer room was trip and would not reset. Electrical issues are considered a hazard until repaired. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.6 Item 1 (Picture)



6.6 Item 2 (Picture)



6.6 Item 3 (Picture)

6.8 CARBON MONOXIDE DETECTORS

REPAIR OR REPLACE

1. There is no carbon monoxide detector found in home. It is recommended that one be installed according to the manufacturer's instructions.

A qualified person should repair or replace as needed.

7. HEATING / CENTRAL AIR CONDITIONING

7.3 DISTRIBUTION SYSTEMS (INCLUDING FANS, PUMPS, DUCTS AND PIPING, WITH SUPPORTS, INSULATION, AIR FILTERS, REGISTERS, RADIATORS, FAN COIL UNITS AND CONVECTORS)

REPAIR OR REPLACE

1. The supply duct pipe is disconnected and is damaged in the crawlspace. Energy loss is occurring. Further investigation and repairs are needed.


A qualified HVAC person should inspect further and repair or replace as needed.



7.3 Item 1 (Picture)



7.3 Item 2 (Picture)



7.3 Item 3 (Picture)



7.3 Item 4 (Picture)

7.5 CHIMNEYS, FLUES AND VENTS (FOR FIREPLACES, GAS WATER HEATERS OR HEAT SYSTEMS)

REPAIR OR REPLACE

1. The vent pipe for gas water heater needs a 1 inch clearance from combustibles. This is a safety issue and should be repaired. Further investigation and repairs are needed.

I recommend a qualified licensed heat contractor inspect further and repair as needed.



7.5 Item 1 (Picture)



7.5 Item 2 (Picture)


8. INTERIORS

8.1 WALLS

REPAIR OR REPLACE

1. The sheetrock has grass growing through the wall at the Den. The extent of damage cannot be realized until the covering is removed. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



8.1 Item 1 (Picture)



8.1 Item 2 (Picture)

8.2 FLOORS

☐ REPAIR OR REPLACE

(1)

1. The linoleum was not installed according to standard workmanlike practices at the throughout the home. Further deterioration can occur. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



8.2 Item 1 (Picture)



8.2 Item 2 (Picture)



8.2 Item 3 (Picture)

(2)

1. The carpet was not installed according to standard workmanlike practices at the throughout the home. This can be a tripping hazard. Repairs are needed.

A qualified person should repair or replace as needed.



8.2 Item 4 (Picture)



8.2 Item 5 (Picture)



8.2 Item 6 (Picture)

8.5 DOORS (REPRESENTATIVE NUMBER)

☐ REPAIR OR REPLACE

(1)

1. Multiple doors throughout the home are missing. This is for your information.

A qualified person should repair or replace as needed.



8.5 Item 1 (Picture)



8.5 Item 2 (Picture)

8.6 WINDOWS (REPRESENTATIVE NUMBER)


REPAIR OR REPLACE

1. Numerous windows stuck or painted shut at the throughout the home. As a result no means of egress is present. One window per bedroom must open as means of egress out of the home should a fire occur. (Safety issue) Repairs are needed..

A qualified person should repair or replace as needed.



8.6 Item 1 (Picture)



8.6 Item 2 (Picture)

9. INSULATION AND VENTILATION

9.1 VENTILATION OF ATTIC AND FOUNDATION AREAS

REPAIR OR REPLACE

1. The foundation vents are damaged and missing screens at the exterior. Rodents, reptiles or insects could enter into crawlspace. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



9.1 Item 1 (Picture)




9.1 Item 2 (Picture)

9.3 INSULATION UNDER FLOOR SYSTEM


☐ REPAIR OR REPLACE

1. The insulation is loose/fallen in the crawlspace. Heat loss can occur more on this home than one that is properly insulated. Repairs are needed.


A qualified contractor should inspect and repair as needed.



9.3 Item 1 (Picture)



9.3 Item 2 (Picture)



9.3 Item 3 (Picture)



9.3 Item 4 (Picture)

9.5 VENTING SYSTEMS (KITCHENS, BATHS AND LAUNDRY)

☐ REPAIR OR REPLACE

(1)

1. The exhaust fan has a damaged vent pipe in attic at the guest bath. Vent pipes that terminate in attic space can sometimes cause moisture that can lead to mold or cause condensation. Repairs are needed.

A qualified person should repair or replace as needed.



9.5 Item 1 (Picture)



9.5 Item 2 (Picture)

10. BUILT-IN KITCHEN APPLIANCES

10.0 DISHWASHER

REPAIR OR REPLACE

(1)

1. The dishwasher door would not open or close properly. Evidence suggests the dishwasher was not installed properly. I recommend repair as necessary.

I recommend contacting appliance repair company.



10.0 Item 1 (Picture)

10.1 RANGES/OVENS/COOKTOPS

REPAIR OR REPLACE

1. The range/oven needs to be properly attached/anchored to the structure as to keep it from tipping over when the oven door is opened and oven racks are pulled out during use. This is a safety issue. Repairs are needed.

I recommend contacting appliance repair company.




10.1 Item 1 (Picture)

10.4 MICROWAVE COOKING EQUIPMENT

REPAIR OR REPLACE

1. The microwave plate is missing. Therefore the microwave cannot function as intended. I recommend repair as needed.

I recommend contacting appliance repair company.

**10.4 Item 1 (Picture)**

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge <http://www.HomeGauge.com> : Licensed To Alex Parr 3692

✓ RESULTS AT A GLANCE

87

✓ ITEMS INSPECTED

Total number in report.

43

📋 SUMMARY COMMENTS

Total number in report.

138

📷 PHOTOS

Total number in report.

🏠 1. PROPERTY OVERVIEW

✂ STYLES & MATERIALS: PROPERTY OVERVIEW

Temperature:

Over 60 (F) = 15.5 (C)

Weather:

Light Rain

Rain in last 3 days:

Yes

👁 ITEMS: PROPERTY OVERVIEW

1.0 SUBJECT PROPERTY PROSPECTIVE

📋 REPAIR OR REPLACE

(1)

1. The home is in distressed condition. We make every attempt to find major issues with the home. Due to the extent of the damage not all items may be found during the inspection this no destructive testing was performed during the inspection. Additional damage to the structure may be found during renovations of the property. Further investigation is needed.


We recommend contacting a licensed contractor regarding these conditions and having repairs made as deemed appropriate.

(2)

1. Discoloration in some type of fungal growth (wood destroying fungus) is present in the structure at several areas including but not limited to the crawl space and or interior spaces. This type of substance commonly results in the building and finish type materials becoming weakened and or compromised. Evidence suggests that this condition is from a past or present elevated moisture conditions. The extent of the damage cannot be determined until the moisture issue is corrected. We did not inspect, test or determine if this type of substance is or is not a health hazard as this is above the scope of a home inspection. We recommend contacting a licensed expert for testing, investigation and or correction as deemed appropriate




1.0 Item 1 (Picture)



1.0 Item 2 (Picture)



1.0 Item 3 (Picture)



1.0 Item 4 (Picture)




1.0 Item 5 (Picture)

1.1 INSPECTION LIMITATIONS


REPAIR OR REPLACE

1. The panel cover was not removed because the panel cover was painted to sheetrock. Removal would have damaged sheetrock. Further investigation is needed.

A qualified licensed electrical contractor should correct as needed.



1.1 Item 1 (Picture)



1.1 Item 2 (Picture)

1.2 RADON TESTING

NOT INSPECTED

🏠 2. ROOFING

📋 DESCRIPTION

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

🔧 STYLES & MATERIALS: ROOFING

Roof Covering: Architectural	Age: 15–20 Yrs	Viewed roof covering from: Ground Ladder Camera Optical Zoom
Sky Light(s): None	Chimney (exterior): N/A	Roof-Type: Gable

👁️ ITEMS: ROOFING

2.0 ROOF COVERINGS

✔️ INSPECTED

2.1 FLASHINGS

✔️ INSPECTED

2.2 SKYLIGHTS, CHIMNEYS AND ROOF PENETRATIONS

📋 REPAIR OR REPLACE

1. The plumbing boot has signs of temporary repair. This may allow water intrusion to occur. Further investigation and repairs are needed..

A qualified contractor should repair or replace as needed.



2.2 Item 1 (Picture)



2.2 Item 2 (Picture)

2.3 ROOF DRAINAGE SYSTEMS

📁 REPAIR OR REPLACE

(1)

1. The gutter at the front (left of main entry) has been installed improperly behind the siding. This may allow water damage to occur to the home. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



2.3 Item 1 (Picture)



2.3 Item 2 (Picture)

(2)

1. The gutter is loose at the front (left of main entry). Gutters that drain poorly or clogged can lead to many costly problems such as deterioration of fascia, soffit or roof edge. It can also cause gutters to pull loose and lead to possible water intrusion. Repairs are needed.

A qualified contractor should inspect and repair as needed.



2.3 Item 3 (Picture)



2.3 Item 4 (Picture)


(3)

1. The gutter leaks at seam (s) at the rear of the home. Gutters that drain poorly or clogged can lead to many costly problems such as deterioration of fascia, soffit or roof edge. It can also cause gutters to pull loose and lead to possible water intrusion. Repairs are needed.

A qualified person should repair or replace as needed.



2.3 Item 5 (Picture)



2.3 Item 6 (Picture)

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 3. EXTERIOR



📋 DESCRIPTION

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

✂️ STYLES & MATERIALS: EXTERIOR

Siding Style:

Lap

Siding Material:

Vinyl

Exterior Entry Doors:

Steel

Insulated glass

Appurtenance:

Covered porch

Driveway:

Gravel

Dirt

👁️ ITEMS: EXTERIOR


3.0 WALL CLADDING FLASHING AND TRIM

📋 REPAIR OR REPLACE


(1)

1. The vinyl siding at the exterior in areas is damaged. Further deterioration can occur if not corrected. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.




3.0 Item 1 (Picture)



3.0 Item 2 (Picture)



3.0 Item 3 (Picture)



3.0 Item 4 (Picture)



3.0 Item 5 (Picture)




3.0 Item 6 (Picture)



3.0 Item 7 (Picture)



3.0 Item 8 (Picture)



3.0 Item 9 (Picture)



3.0 Item 10 (Picture)



3.0 Item 11 (Picture)



3.0 Item 12 (Picture)



3.0 Item 13 (Picture)



3.0 Item 14 (Picture)




3.0 Item 15 (Picture)

(2)

1. Siding in contact with ground at front of home. Because the siding is in contact with ground it is possible for framing to be deteriorated. We did not inspect behind this siding. Recommend a ground clearance of six to eight inches where possible. Repairs are needed.

A qualified contractor should inspect and repair as needed.



3.0 Item 16 (Picture)

3.1 EAVES, SOFFITS AND FASCIAS

✓ REPAIR OR REPLACE

1. The metal fascia wrap at eave on the front of home is missing. Further deterioration may occur if not repaired. Repairs are needed.

A qualified person should repair or replace as needed.



3.1 Item 1 (Picture)



3.1 Item 2 (Picture)



3.1 Item 3 (Picture)



3.1 Item 4 (Picture)

3.2 WINDOWS

✓ INSPECTED


3.3 DOORS (EXTERIOR)

 REPAIR OR REPLACE

(1)

1. The right side (facing front) entry door dead bolt is keyed. (Safety issue) All exterior doors should not be keyed type locks, as this can impede exiting the home should a fire occur. Repairs are needed.


A qualified person should repair or replace as needed.

**3.3 Item 1 (Picture)**

(2)

1. The entry door at front of home is deteriorated at bottom of jamb (s) and at the door. Further deterioration may occur if not repaired. Repairs are needed.

A qualified contractor should inspect and repair as needed.

**3.3 Item 2 (Picture)****3.3 Item 3 (Picture)****3.3 Item 4 (Picture)****3.3 Item 5 (Picture)**

(3)

1. The entry door at rear of home rubs at jamb when closing. As a result the door will not close properly. Repairs are needed.

A qualified person should repair or replace as needed.



3.3 Item 6 (Picture)

(4)

1. The dead bolt does not latch properly at the side entry. Repairs are needed.

A qualified person should repair or replace as needed.



3.3 Item 7 (Picture)

(5)

1. The access door to the crawlspace has damaged hinged hardware. Therefore the door does not function as intended. Repairs are needed.

A qualified contractor should inspect and repair as needed.



3.3 Item 8 (Picture)



3.3 Item 9 (Picture)

3.4 DECKS, BALCONIES, STOOPS, STEPS, AREAWAYS, PORCHES, PATIO/COVER AND APPLICABLE RAILINGS

☐ REPAIR OR REPLACE

(1)

1. The brick steps at front entry are damaged and missing bricks. A fall or injury could occur if not corrected. A repair or replacement is needed.

A qualified contractor should repair or replace as needed.



3.4 Item 1 (Picture)



3.4 Item 2 (Picture)


(2)

1. The concrete floor on the covered porch at the front of home has settled. Further deterioration can occur if not repaired. Repairs are needed.

A qualified person should repair or replace as needed.



3.4 Item 3 (Picture)



3.4 Item 4 (Picture)



3.4 Item 5 (Picture)



3.4 Item 6 (Picture)

3.5 VEGETATION, GRADING, DRAINAGE, DRIVEWAYS, PATIO FLOOR, WALKWAYS AND RETAINING WALLS (WITH RESPECT TO THEIR EFFECT ON THE CONDITION OF THE BUILDING)

☐ REPAIR OR REPLACE

1. There is a negative slope at the left side (facing front) and rear, this can cause or contribute to water intrusion or deterioration. I recommend correcting landscape to drain water away from home.

Further investigation and repairs are needed.

A qualified contractor should repair or replace as needed.



3.5 Item 1 (Picture)



3.5 Item 2 (Picture)

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4. STRUCTURAL COMPONENTS

DESCRIPTION

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

STYLES & MATERIALS: STRUCTURAL COMPONENTS

Foundation:

Masonry block

Method used to observe
Crawlspace:

Standing water

Limited access

Floor Structure:

8" or better

Wall Structure:

2 X 4 Wood

Columns or Piers:

Masonry block

Ceiling Structure:

2X4

Roof Structure:

Engineered wood trusses

ITEMS: STRUCTURAL COMPONENTS

4.0 WALLS (STRUCTURAL)

 INSPECTED

4.1 COLUMNS OR PIERS

 INSPECTED

4.2 FLOORS (STRUCTURAL)

 REPAIR OR REPLACE

1. The slab foundation at the rear of the home is damaged. Further damaged/deterioration could occur. Further investigation and repairs are needed.

A qualified licensed general contractor should inspect further and repair as needed.



4.2 Item 1 (Picture)



4.2 Item 2 (Picture)

4.3 CEILINGS (STRUCTURAL)

✓ INSPECTED

4.4 ROOF STRUCTURE AND ATTIC

📋 REPAIR OR REPLACE

(1)

1. The roof sheathing bowed. Repairs are needed to maintain the stability of roof. This may allow water intrusion to occur. Further investigation and repairs are needed.


A qualified contractor should repair as needed.



4.4 Item 1 (Picture)



4.4 Item 2 (Picture)



4.4 Item 3 (Picture)

(2)

1. The truss system installed in the attic have been damage during or before installation of the truss. All truss repairs should be repaired via an approved method specified b the manufacture and or approved and stamped by licensed structural engineer. Further evaluation and repairs are needed.

A qualified licensed structural engineer/design professional is recommended to evaluate the trusses for any repairs. This should include a site specific letter from the registered design professional/engineer stating what repairs (if any) are needed approval of performed repairs, signature, state license number, and state registered stamp of the engineer.

**4.4 Item 4 (Picture)****4.4 Item 5 (Picture)**

4.5 WOOD DETERIORATION

☐ REPAIR OR REPLACE

1. Wood debris is in contact with the crawl space floor in numerous areas. This can attract wood destroying organisms. Removal is needed.

A qualified contractor should inspect and repair as needed.


**4.5 Item 1 (Picture)****4.5 Item 2 (Picture)**

4.6 FOUNDATIONS, BASEMENT AND CRAWLSPACE (REPORT SIGNS OF ABNORMAL OR HARMFUL WATER PENETRATION INTO THE BUILDING OR SIGNS OF ABNORMAL OR HARMFUL CONDENSATION ON BUILDING COMPONENTS.)

☐ REPAIR OR REPLACE

1. Visible signs of water intrusion in the crawlspace are present from standing water on ground. Water intrusion if not corrected can lead to other problems including mold and cause excessive moisture to floor system that can lead to deterioration and increased repair cost. Further investigation and repairs are needed.

I recommend further investigation or correction by a qualified licensed contractor or water infiltration specialist.



4.6 Item 1 (Picture)



4.6 Item 2 (Picture)

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 5. PLUMBING SYSTEM

📋 DESCRIPTION

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.



Complimentary photo of the water heater

✂️ STYLES & MATERIALS: PLUMBING SYSTEM

Water Source:

Well

Water Filters:

None

Plumbing Water Supply (into home):

Copper
Pex

Plumbing Water Distribution (inside home):

Copper
PEX
POLY

Washer Drain Size:

2" Diameter

Plumbing Waste:

PVC

Water Heater Power Source:

Gas (quick recovery)

Water Heater Capacity:

40 Gallon (1-2 people)

Manufacturer:

ENVIROTEMP

👁️ ITEMS: PLUMBING SYSTEM

5.0 MAIN WATER SHUT-OFF DEVICE (DESCRIBE LOCATION)

✓ INSPECTED

The main shut off is the white lever located underneath in the crawlspace. This is for your information.



5.0 Item 1 (Picture)


5.1 HOT WATER SYSTEMS, CONTROLS, CHIMNEYS, FLUES AND VENTS

📋 REPAIR OR REPLACE

(1)

1. The water heater does not appear to have proper fresh air supply. This is a safety issue. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



5.1 Item 1 (Picture)



5.1 Item 2 (Picture)



5.1 Item 3 (Picture)



5.1 Item 4 (Picture)

(2)

1. The draft hood connection to flue vent connector: provide at least 12" vertical inches of the flue vent between the draft hood outlet and the first elbow. This is a safety issue and should be repaired. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.1 Item 5 (Picture)

5.2 PLUMBING WATER SUPPLY, DISTRIBUTION SYSTEM AND FIXTURES

☐ REPAIR OR REPLACE

(1)

1. The tub faucets and hot/cold control loose in wall at the guest bath. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed..

A qualified licensed plumber should repair or correct as needed.



5.2 Item 1 (Picture)



5.2 Item 2 (Picture)

(2)

1. The toilet tank is loose at the master bathroom. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed..

A qualified licensed plumber should repair or correct as needed.



5.2 Item 3 (Picture)

(3)

1. Polybutylene plastic plumbing supply lines (PB) are installed in the subject house. Polybutylene has been used in this area for many years, but has had a higher than normal failure rate, and is no longer being widely used. Copper and Brass fittings used in later years have apparently reduced the failure rate. This subject house has copper fittings. For further details contact the Consumer Plumbing Recovery center at 1-800-392-7591 or the web at <http://www.pbpipe.com>



5.2 Item 4 (Picture)

5.3 PLUMBING DRAIN, WASTE AND VENT SYSTEMS

☐ REPAIR OR REPLACE

(1)

1. The plumbing waste line leaks under the kitchen sink. Repairs are needed to prevent water damage from occurring to the home. Further investigation and repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.3 Item 1 (Picture)



5.3 Item 2 (Picture)

(2)

1. The stop-valve is missing at the Hall Bath sink and Master Bath sink. As a result you cannot fill up the tub. Repairs are needed.

A qualified licensed plumber should repair or correct as needed.



5.3 Item 3 (Picture)

5.4 SHOWER/TUB & TILE WALLS

✓ INSPECTED

5.5 FUEL STORAGE AND DISTRIBUTION SYSTEMS (INTERIOR FUEL STORAGE, PIPING, VENTING, SUPPORTS, LEAKS)

✓ INSPECTED

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 6. ELECTRICAL SYSTEM

📋 DESCRIPTION

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.

🔧 STYLES & MATERIALS: ELECTRICAL SYSTEM

Electrical Service	Panel Type:
Conductors:	Circuit breakers
Below ground	
Aluminum	

👁️ ITEMS: ELECTRICAL SYSTEM

6.0 LOCATION OF MAIN AND DISTRIBUTION PANELS

✔ INSPECTED

The main panel box is located at the den.

6.1 SERVICE ENTRANCE CONDUCTORS


📋 REPAIR OR REPLACE

1. The electrical service meter has an opening at the bottom. This is a safety issue. Further investigation and repairs are needed.

I recommend a licensed electrical contractor inspect further and correct as needed.



6.1 Item 1 (Picture)



6.1 Item 2 (Picture)

6.2 SERVICE AND GROUNDING EQUIPMENT, MAIN OVERCURRENT DEVICE, MAIN AND DISTRIBUTION PANELS

✓ NOT INSPECTED

6.3 BRANCH CIRCUIT CONDUCTORS, OVERCURRENT DEVICES AND COMPATABILITY OF THEIR AMPERAGE AND VOLTAGE

✓ NOT INSPECTED


6.4 CONNECTED DEVICES AND FIXTURES (OBSERVED FROM A REPRESENTATIVE NUMBER OPERATION OF CEILING FANS, LIGHTING FIXTURES, SWITCHES AND RECEPTACLES LOCATED INSIDE THE HOUSE, GARAGE, AND ON THE DWELLING'S EXTERIOR WALLS)

📋 REPAIR OR REPLACE


(1)

1. Several open splices needs placing inside a box with a cover-plate in the attic space. Electrical issues are considered a hazard until repaired. Further investigation and repair are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 1 (Picture)



6.4 Item 2 (Picture)

(2)

1. At least one "three-prong" outlet is loose in wall in the living room. Electrical issues are considered a hazard until repaired. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 3 (Picture)



6.4 Item 4 (Picture)

(3)

1. One or more "three-prong" outlet is wired incorrectly "hot / neutral reversed" in the bedroom. Electrical issues are considered a hazard until repaired. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.4 Item 5 (Picture)



6.4 Item 6 (Picture)

6.5 POLARITY AND GROUNDING OF RECEPTACLES WITHIN 6 FEET OF INTERIOR PLUMBING FIXTURES, ALL RECEPTACLES IN GARAGE, CARPORT AND EXTERIOR WALLS OF INSPECTED STRUCTURE


✓ INSPECTED

6.6 OPERATION OF GFCI (GROUND FAULT CIRCUIT INTERRUPTERS)

☐ REPAIR OR REPLACE

1. The GFCI (Ground Fault Circuit Interrupter) outlet at the Washer/Dryer room was trip and would not reset. Electrical issues are considered a hazard until repaired. Further investigation and repairs are needed.

A qualified licensed electrical contractor should correct as needed.



6.6 Item 1 (Picture)



6.6 Item 2 (Picture)



6.6 Item 3 (Picture)

6.7 SMOKE DETECTORS

✓ INSPECTED

6.8 CARBON MONOXIDE DETECTORS

📋 REPAIR OR REPLACE

1. There is no carbon monoxide detector found in home. It is recommended that one be installed according to the manufacturer's instructions.

A qualified person should repair or replace as needed.

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.


🏠 7. HEATING / CENTRAL AIR CONDITIONING

📋 DESCRIPTION


The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.



Complimentary photo of the package unit



Complimentary photo of the gas furnace with the cover off



✂️ STYLES & MATERIALS: HEATING / CENTRAL AIR CONDITIONING

Heat Type:

Package Unit

Heating Age:

1-5 yrs

Number of Heat Systems

(excluding wood):

One

Energy Source:

Natural gas

Operated:

Unit Operated

Heat System Brand:

GOODMAN

Ductwork:

Insulated

Types of Fireplaces:

None

Operable Fireplaces:

None

Number of Woodstoves:

None

Cooling Equipment Type:

Air conditioner unit

Air Conditioning Age:

1-5 yrs

Cooling Equipment Energy

Source:

Electricity

Central Air Manufacturer:

GOODMAN

Number of AC Only Units:

One

👁️ ITEMS: HEATING / CENTRAL AIR CONDITIONING

7.0 HEATING EQUIPMENT

☑ REPAIR OR REPLACE

1. Metal flashing in between the house and a packaged unit is holding water. Further deterioration can occur. Further investigation and repairs are needed.

I recommend further inspection by a licensed HVAC contractor.



7.0 Item 1 (Picture)

7.1 NORMAL OPERATING CONTROLS

☑ INSPECTED

7.2 AUTOMATIC SAFETY CONTROLS

☑ INSPECTED

7.3 DISTRIBUTION SYSTEMS (INCLUDING FANS, PUMPS, DUCTS AND PIPING, WITH SUPPORTS, INSULATION, AIR FILTERS, REGISTERS, RADIATORS, FAN COIL UNITS AND CONVECTORS)

📋 REPAIR OR REPLACE

1. The supply duct pipe is disconnected and is damaged in the crawlspace. Energy loss is occurring. Further investigation and repairs are needed.


A qualified HVAC person should inspect further and repair or replace as needed.



7.3 Item 1 (Picture)



7.3 Item 2 (Picture)



7.3 Item 3 (Picture)



7.3 Item 4 (Picture)

7.4 PRESENCE OF INSTALLED HEAT SOURCE IN EACH ROOM

☑ INSPECTED

7.5 CHIMNEYS, FLUES AND VENTS (FOR FIREPLACES, GAS WATER HEATERS OR HEAT SYSTEMS)

📋 REPAIR OR REPLACE

1. The vent pipe for gas water heater needs a 1 inch clearance from combustibles. This is a safety issue and should be repaired. Further investigation and repairs are needed.

I recommend a qualified licensed heat contractor inspect further and repair as needed.



7.5 Item 1 (Picture)



7.5 Item 2 (Picture)

7.6 SOLID FUEL HEATING DEVICES (FIREPLACES, WOODSTOVE)

☑ NOT PRESENT

7.7 GAS/LP FIRELOGS AND FIREPLACES

☑ NOT PRESENT

7.8 COOLING AND AIR HANDLER EQUIPMENT

☑ INSPECTED

7.9 NORMAL OPERATING CONTROLS

☑ INSPECTED

7.10 PRESENCE OF INSTALLED COOLING SOURCE IN EACH ROOM

☑ INSPECTED

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 8. INTERIORS

📋 DESCRIPTION

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

🔧 STYLES & MATERIALS: INTERIORS

Ceiling Materials: Drywall	Wall Material: Drywall	Floor Covering(s): Carpet Vinyl Plank Linoleum
Interior Doors: Hollow core Raised panel	Window Types: Thermal/Insulated	

👁️ ITEMS: INTERIORS

8.0 CEILINGS

✔️ INSPECTED

8.1 WALLS


📋 REPAIR OR REPLACE

1. The sheetrock has grass growing through the wall at the Den. The extent of damage cannot be realized until the covering is removed. Further investigation and repairs are needed.

A qualified contractor should inspect and repair as needed.



8.1 Item 1 (Picture)



8.1 Item 2 (Picture)

8.2 FLOORS

📋 REPAIR OR REPLACE

(1)

1. The linoleum was not installed according to standard workmanlike practices at the throughout the home. Further deterioration can occur. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



8.2 Item 1 (Picture)



8.2 Item 2 (Picture)



8.2 Item 3 (Picture)

(2)

1. The carpet was not installed according to standard workmanlike practices at the throughout the home. This can be a tripping hazard. Repairs are needed.

A qualified person should repair or replace as needed.



8.2 Item 4 (Picture)



8.2 Item 5 (Picture)



8.2 Item 6 (Picture)

8.3 STEPS, STAIRWAYS, BALCONIES AND RAILINGS

☑ INSPECTED

8.4 COUNTERS AND CABINETS (REPRESENTATIVE NUMBER)

☑ REPAIR OR REPLACE

(1)

1. The corner cabinet does not shut properly. Therefore it does not function as intended. Repairs are needed.

A qualified person should repair or replace as needed.



8.4 Item 1 (Picture)



8.4 Item 2 (Picture)

(2)

1. Drawer track does not work smoothly in the kitchen. Recommend repair or replace as necessary.

A qualified person should repair or replace as needed



8.4 Item 3 (Picture)

8.5 DOORS (REPRESENTATIVE NUMBER)

☐ REPAIR OR REPLACE


(1)

1. Multiple doors throughout the home are missing. This is for your information.

A qualified person should repair or replace as needed.



8.5 Item 1 (Picture)




8.5 Item 2 (Picture)


(2)

1. The door throughout the home will not latch properly. Evidence suggest that the door needs strike and latch adjustment to shut properly. This is a small repair.

A qualified person should repair or replace as needed.



8.5 Item 3 (Picture)



8.5 Item 4 (Picture)

8.6 WINDOWS (REPRESENTATIVE NUMBER)


REPAIR OR REPLACE

1. Numerous windows stuck or painted shut at the throughout the home. As a result no means of egress is present. One window per bedroom must open as means of egress out of the home should a fire occur. (Safety issue) Repairs are needed..

A qualified person should repair or replace as needed.



8.6 Item 1 (Picture)



8.6 Item 2 (Picture)

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

🏠 9. INSULATION AND VENTILATION

📋 DESCRIPTION

The home inspector shall observe: Insulation and vapor retarders in unfinished spaces; Ventilation of attics and foundation areas; Kitchen, bathroom, and laundry venting systems; and the operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control. The home inspector shall describe: Insulation in unfinished spaces; and Absence of insulation in unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evidence indicates the need to do so; and Move insulation where chimneys penetrate roofs, where plumbing drain/waste pipes penetrate floors, adjacent to earth filled stoops or porches, and at exterior doors. The home inspector is not required to report on: Concealed insulation and vapor retarders; or Venting equipment that is integral with household appliances.

🔧 STYLES & MATERIALS: INSULATION AND VENTILATION

Attic info: Scuttle hole	Method used to observe attic: From entry	Attic Insulation: Batt Cellulose
Ventilation: Ridge vents Soffit Vents	Exhaust Fans: Fan	Dryer Power Source: 220 Electric
Dryer Vent: Metal	Floor System Insulation: Faced Batts	

👁️ ITEMS: INSULATION AND VENTILATION

9.0 VAPOR RETARDERS (IN CRAWLSPACE OR BASEMENT)

✅ REPAIR OR REPLACE

1. The vapor barrier (plastic) on the crawlspace ground is missing in areas. A vapor barrier provides added protection to the floor system from moisture or dampness that can enter from ground.
Repairs are needed.

A qualified person should repair or replace as needed.



9.0 Item 1 (Picture)



9.0 Item 2 (Picture)

9.1 VENTILATION OF ATTIC AND FOUNDATION AREAS

 REPAIR OR REPLACE

1. The foundation vents are damaged and missing screens at the exterior. Rodents, reptiles or insects could enter into crawlspace. Further investigation and repairs are needed.

A qualified person should repair or replace as needed.



9.1 Item 1 (Picture)



9.1 Item 2 (Picture)

9.2 INSULATION IN ATTIC

 REPAIR OR REPLACE

1. Insulation is missing in areas in attic. Heat loss can occur more on this home than one that is properly insulated. Repairs are needed.

A qualified person should repair or replace as needed.



9.2 Item 1 (Picture)



9.2 Item 2 (Picture)




9.2 Item 3 (Picture)

9.3 INSULATION UNDER FLOOR SYSTEM


 REPAIR OR REPLACE

1. The insulation is loose/fallen in the crawlspace. Heat loss can occur more on this home than one that is properly insulated. Repairs are needed.


A qualified contractor should inspect and repair as needed.



9.3 Item 1 (Picture)



9.3 Item 2 (Picture)



9.3 Item 3 (Picture)



9.3 Item 4 (Picture)

9.4 ATTIC ACCESS

✓ INSPECTED


9.5 VENTING SYSTEMS (KITCHENS, BATHS AND LAUNDRY)

📦 REPAIR OR REPLACE

(1)

1. The exhaust fan has a damaged vent pipe in attic at the guest bath. Vent pipes that terminate in attic space can sometimes cause moisture that can lead to mold or cause condensation. Repairs are needed.

A qualified person should repair or replace as needed.



9.5 Item 1 (Picture)



9.5 Item 2 (Picture)

(2)

1. The dryer vent cover is damaged outside at the rear of the home. Repairs are recommended

A qualified person should repair or replace as needed.



9.5 Item 3 (Picture)



9.5 Item 4 (Picture)



9.5 Item 5 (Picture)

9.6 VENTILATION FANS AND THERMOSTATIC CONTROLS IN ATTIC

✓ NOT PRESENT

The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

10. BUILT-IN KITCHEN APPLIANCES

DESCRIPTION

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

STYLES & MATERIALS: BUILT-IN KITCHEN APPLIANCES

Countertop:

Laminate

Cabinetry:

Wood

ITEMS: BUILT-IN KITCHEN APPLIANCES

10.0 DISHWASHER

REPAIR OR REPLACE

(1)

1. The dishwasher door would not open or close properly. Evidence suggests the dishwasher was not installed properly. I recommend repair as necessary.

I recommend contacting appliance repair company.



10.0 Item 1 (Picture)

(2)

1. The dishwasher is loose and needs securing to underside of countertop (using a proper length screw). I recommend repair as necessary.

I recommend contacting appliance repair company.



10.0 Item 2 (Picture)



10.0 Item 3 (Picture)

(3)

1. The dishwasher drain hose needs to be looped above the level of the kitchen sink drain or an approved air gap installed to prevent back flow of waste water into the water supply. (food safety issue) This can allow waste for the sink to contaminate the dishwasher. This is a small repair.

A qualified licensed plumber should repair or correct as needed.




10.0 Item 4 (Picture)

10.1 RANGES/OVENS/COOKTOPS

☐ REPAIR OR REPLACE

1. The range/oven needs to be properly attached/anchored to the structure as to keep it from tipping over when the oven door is opened and/or oven racks are pulled out during use. This is a safety issue. Repairs are needed.

I recommend contacting appliance repair company.



10.1 Item 1 (Picture)

10.2 RANGE HOOD (S)

☑ REPAIR OR REPLACE

1. The light bulb for fan did not work when tested. I recommend repair or replace as needed.
I recommend contacting appliance repair company.



10.2 Item 1 (Picture)

10.3 FOOD WASTE DISPOSER


☑ NOT PRESENT

10.4 MICROWAVE COOKING EQUIPMENT

☐ REPAIR OR REPLACE

1. The microwave plate is missing. Therefore the microwave cannot function as intended. I recommend repair as needed.

I recommend contacting appliance repair company.



10.4 Item 1 (Picture)

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.