



2023-12-20

Kevin Thomas
113 IVY HOLLOW LANE
MOORESVILLE, NC 28117

RE: Inspection Report for 113 Ivy Hollow Ln Mooresville NC 28117

Dear Kevin Thomas:

We are pleased to submit to you our electronic septic system inspection report for the work completed recently at your property. This report provides a summary of the work performed, a status update on any issues found, and includes recommendations specific to any issues requiring your attention.

The first page provides you with a summary of the inspection performed. Pages 2-6 of the report provides additional information, if applicable, for each section of your wastewater system.

We hope you will find this electronic summary report helpful in understanding the current status of your septic system. Detailed field notes are recorded and maintained in the office should you have any additional questions in regards to your inspection.

We appreciate the opportunity to serve you.

Sincerely,

TCW Wastewater Management, Inc.
5600 Lakeview Road
Charlotte, NC 28269



Summary

Kevin Thomas

113 Ivy Hollow Ln

Moorestville, NC 28117

(704) 799-7709

Inspection Date/Time: **12-20-2023 / 10:44 AM**

Technician: Blake Efird

System Type: LCPM-2/8

Observations

Septic Tank Inspection Results: **No action needed**

Pump Tank Inspection Results: **No action needed**

Pressure Manifold Inspection Results: **No action needed**

Ground Absorption Inspection Results: **No action needed**

Distribution Inspection Results: **N/A**

Status: **Compliant**

Septic Tank needs pumping: No

Pump Tank needs pumping: No

Toilet testing dye strips left at house. No

Bacteria packets left at house. No

Root killer was added today. No

Note: if "Action is Needed" on any of the above, please refer to the respective details section that follows this page.

Recommendations

Additional Notes:

Please read the following individual component pages for more information



Beginning inspection with dirty filter





Ending Inspection

Septic Tank

Inspection Results:	No action needed	Is there possible storm water infiltrating the tank?	No
Does the septic tank need pumping?	No	Emergency tank storage (inches): Above water level (Optimum 8" – 10")	N/A
Date of last pumping:		Filter screen clogging - %:	10
Scum level thickness (Inches on top of water):	0	Was the filter screen cleaned today?	Yes
Sludge level thickness (Inches on bottom of tank):	0		

Recommendations:

Notes:
Homeowner has repaired riser and lid. He has fiberglassed the lid and reinforced the riser with metal and brackets so lids will seal correctly. Tanks have also been pumped. Also a brush filter has been added. Inlet pipe is marginal and we will monitor for now.



Inlet Sludge Level and Clean Filter

Pump Tank

Inspection Results:

No action needed

Does the pump tank need pumping?

No

Date of last pumping:

Daily wastewater dispersed:
(if available, calculated through pump run time.
Optimum < 250 GPD)

Scum level thickness (on top of water):

0

Sludge level thickness (on bottom of tank):

0

Is there possible storm water infiltrating into the tank?

No

Is the high water ALARM functioning properly today?

Cannot Evaluate

Is the effluent pump functioning today?

Yes

Are the electrical controls in good condition?

N/A

Is the pump delivery rate within the acceptable range today?

Not Evaluated

Recommendations:

Notes:

Riser and lid have been repaired the same way as the other. Conduit and post for control box has been fixed as well. Not enough water to evaluate gpm due to setting mai



No Entry


Pressure Manifold Assembly

Inspection Results:	No action needed	Is the vault is in good condition?	Yes
		Are the valves and pipes in good condition?	Yes
		Is there evidence of clogging in the discharge lines?	No evidence

Recommendations:

Notes:

Everything looks good inside the manifold



Ground Absorption Field			
Inspection Results:		No action needed	
Is the location of the absorption field On-site or Off-site?	Onsite	Is there evidence of effluent surfacing?	No
		Are there low or settled areas in the field that need fill-in?	No
		Is the vegetative covering over the field maintained adequately.	Yes
Recommendations:			
Notes:			

Low Pressure Distribution

Inspection Results:

N/A

Are the adjustment valves accessible?

N/A

Are the end of the laterals accessible?

N/A

Is each distribution lateral set with the proper pressure today?

N/A

Were all the system laterals flushed today?


N/A

Do the distribution laterals need cleaning or pressure jetting?


N/A

Recommendations

Notes



Panel Block System



Low Pressure Pipe System