Questions to ask the inspector: see page 4

SYNTHETIC SAMPLE REPORT - made up for testing, not a real inspection

Mold and Moisture Assessment, Example Property, 100 Sample Lane
Assessment date: sample date. Prepared for: sample client.

1. Scope of assessment

The assessment covered the interior living areas, the attic access, and the crawl space. Areas behind locked doors and the detached garage were not accessed. Visual observation and a moisture meter were used. No destructive testing was performed during this assessment.

1. What was the cause of the stain based on?

2. Observations

Staining was observed on the ceiling of the hall bathroom, approximately 2 feet by 3 feet. The stain is consistent with a long-standing moisture source above the ceiling plane.

2 Moisture meter readings in the hall bathroom ceiling were elevated relative to adjacent areas.

The closet humidity was persistently elevated during the visit, with no dehumidifier present.

3 Visible growth was noted on the north wall of the primary bedroom closet near the baseboard.

2. Moisture readings are documented

3. Which closet reading applies?

3. Sampling

Two air samples and one outdoor control sample were collected. Sample locations are listed in the laboratory appendix. The laboratory reported elevated spore counts in the primary bedroom. The duration of the moisture condition was estimated at more than six months.

4. What was the six month estimate based on?

4. Conclusions

The mold growth is caused by a roof leak above the hall bathroom. The condition poses a health risk to occupants and is the reason for the symptoms described by the client.

5. What supports linking the symptoms to the mold?

5. Recommendations

Remove all affected drywall in the hall bathroom and the primary bedroom closet. Replace the roof flashing above the hall bathroom. Remediation should be completed by a licensed contractor. The attic was not entered because of limited headroom, and no photographs of the attic exist.

6. Can the attic be reviewed another way?

7. Can a readable copy of page 3 be supplied? (see this page; no readable text to mark)

Summary of items to clarify

Questions to ask the inspector

1. What was the cause of the stain based on?
2. What was the six month estimate based on?
3. What supports linking the symptoms to the mold?

Items that bear on your decision

No.	Item	Report page	Evidence	Possible next step
1	Cause of the staining stated without a source	1	limited	Ask for the supporting history.
4	Duration estimate has no stated basis	2	limited	Ask for the supporting history.
5	Health statement goes beyond a mold assessment	2	limited	Ask for the supporting history.

Other items worth knowing

No.	Item	Report page	Evidence	Possible next step
3	Statements about the closet differ	1	limited	Ask for the supporting history.
6	Attic not entered, no photographs	2	limited	Ask for the supporting history.
7	Scanned page cannot be read	3	limited	Ask for the supporting history.

What the report supports

No.	Item	Report page	Evidence	Possible next step
2	Moisture readings are documented	1	limited	Ask for the supporting history.

Limits of this review

- This is a document review within the supplied evidence.

Document review within the supplied evidence. This is not an inspection of the building and not an expert opinion.