Answers to Selected Exercises

CHAPTER 3

- **3.1.** (a) $\overline{x} = 16.029$. (b) s = 0.0202.
- **3.3.** (a) $\overline{x} = 952.9$. (b) s = 3.7.
- **3.5.** (a) $\overline{x} = 121.25$. (b) s = 22.63.
- **3.13.** Both the normal and lognormal distributions appear to be reasonable models for the data.
- **3.15.** The lognormal distribution appears to be a reasonable model for the concentration data.
- **3.19.** (a) $\overline{x} = 89.476$. (b) s = 4.158.
- **3.23.** *sample space*: {2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12}

$$p(x) = \begin{cases} 1/36; x = 2 & 2/36; x = 3\\ 3/36; x = 4 & 4/36; x = 5\\ 5/36; x = 6 & 6/36; x = 7\\ 5/36; x = 8 & 4/36; x = 9\\ 3/36; x = 10 & 2/36; x = 11\\ 1/36; x = 12 & 0; \text{ otherwise} \end{cases}$$

- **3.25.** (a) 0.0196. (b) 0.0198. (c) Cutting occurrence rate reduces
 - probability from 0.0198 to 0.0100. 27. (a) k = 0.05. (b) $\mu = 1.867$, $\sigma^2 = 0.615$.
- **3.27.** (a) k = 0.05. (b) $\mu = 1.867$, $\sigma^2 = 0.615$ (c) $F(x) = \{0.383; x = 1 \ 0.750; x = 2 \ 1.000; x = 3 \}$
- **3.29.** (a) Approximately 11.8%. (b) Decrease profit by \$5.90/calculator.
- **3.31.** Decision rule means 22% of samples will have one or more nonconforming units.
- **3.33.** 0.921
- 3.35. (a) 0.633. (b) 0.659. Approximation is not satisfactory.(c) n/N = 0.033. Approximation is satisfactory. (d) n = 11
- **3.37.** $Pr\{x = 0\} = 0.364, Pr\{x \ge 2\} = 0.264$
- **3.39.** $Pr\{x \ge 1\} = 0.00001$

- **3.41.** $\mu = 1/p$
- 3.43. Pr $\{x \le 35\}$ = 0.159. Number failing minimum spec is 7950. Pr $\{x > 48\}$ = 0.055. Number failing maximum spec is 2750.
- **3.45.** Process is centered at target, so shifting process mean in either direction increases nonconformities. Process variance must be reduced to 0.015^2 to have at least 999 of 1000 conform to specification.
- **3.47.** $Pr\{x > 1000\} = 0.0021$
- **3.49.** If $c_2 > c_1 + 0.0620$, then choose process 1.

- **4.1.** (a) $Z_0 = 6.78$. Reject H_0 . (b) P = 0. (c) $8.2525 \le \mu \le 8.2545$.
- **4.3.** (a) $t_0 = 1.952$. Reject H_0 . (b) $25.06 \le \mu \le 26.94$.
- **4.5.** (a) $t_0 = -3.089$. Reject H_0 . (b) $13.39216 \le \mu \le 13.40020$.
- **4.7.** n = 246
- **4.9.** (a) $t_0 = -6.971$. Reject H_0 . (b) $9.727 \le \mu \le 10.792$ (c) $\chi_0^2 = 14.970$. Do not reject H_0 . (d) $0.738 \le \sigma \le 1.546$ (e) $\sigma \le 1.436$
- **4.11.** (a) $t_0 = 0.11$. Do not reject H_0 . (c) $-0.127 \le (\mu_1 - \mu_2) \le 0.141$ (d) $F_0 = 0.8464$. Do not reject H_0 . (e) $0.165 \le \sigma_1^2/\sigma_2^2 \le 4.821$ (f) $0.007 \le \sigma^2 \le 0.065$
- **4.13.** (a) $t_0 = -0.77$. Do not reject H_0 . (b) $-6.7 \le (\mu_1 - \mu_2) \le 3.1$. (c) $0.21 \le \sigma_1^2/\sigma_2^2 \le 3.34$
- **4.15.** (a) $Z_0 = 4.0387$. Reject H_0 . (b) P = 0.00006. (c) $p \le 0.155$.

- **4.17.** (a) $F_0 = 1.0987$. Do not reject H_0 . (b) $t_0 = 1.461$. Do not reject H_0 .
- **4.19.** $t_0 = -1.10$. There is no difference between mean measurements.
- **4.21.** (a) $\chi_0^2 = 42.75$. Do not reject H_0 . (b) $1.14 \le \sigma \le 2.19$.
- **4.23.** $n = [(Z_{\alpha/2} + Z_{\beta})\sigma/\delta]^2$
- **4.27.** $Z_0 = 0.3162$. Do not reject H_0 .
- **4.29.** (a) $F_0 = 3.59$, P = 0.053.
- **4.31.** (a) $F_0 = 1.87$, P = 0.214.
- **4.33.** (a) $F_0 = 1.45$, P = 0.258.
- **4.35.** (a) $F_0 = 30.85$, P = 0.000.

- **5.17.** Pattern is random.
- **5.19.** There is a nonrandom, cyclic pattern.
- **5.21.** Points 17, 18, 19, and 20 are outside lower 1-sigma area.
- **5.23.** Points 16, 17, and 18 are 2 of 3 beyond 2 sigma of centerline. Points 5, 6, 7, 8, and 9 are of 5 at 1 sigma or beyond of centerline.

- **6.1.** (a) Samples 12 and 15 exceed \bar{x} UCL. (b) $\bar{p} = 0.00050$.
- **6.3.** (a) \bar{x} chart: CL = 10.9, UCL = 50.35, LCL = -28.55 R chart: CL = 54.1, UCL = 123.5, LCL = 0 Process is in statistical control. (b) $\bar{\sigma}_x = 23.3$. (c) $\hat{C}_p = 1.43$.
- 6.5. (a) \bar{x} chart: CL = -0.003, UCL = 1.037, LCL = -1.043 s chart: CL = 1.066, UCL = 1.830, LCL = 0.302 (b) R chart: CL = 3.2, UCL = 5.686, LCL = 0.714 (c) s^2 chart: CL = 1.2057, UCL = 3.6297, LCL = 0.1663
- 6.7. \bar{x} chart: CL = 10.33, UCL = 14.73, LCL = 5.92 s chart: CL = 2.703, UCL = 6.125, LCL = 0
- 6.9. (a) chart: CL = 74.00118, UCL = 74.01458, LCL = 73.98777 R chart: CL = 0.02324, UCL = 0.04914, LCL = 0 (b) No. (c) \hat{C}_P = 1.668.
- **6.11.** \bar{x} chart: CL = 80, UCL = 89.49, LCL = 70.51 s chart: CL = 9.727, UCL = 16.69, LCL = 2.76

- **6.13.** (a) \bar{x} chart: CL = 20, UCL = 22.34, LCL = 17.66 s chart: CL = 1.44, UCL = 3.26, LCL = 0 (b) LNTL = 15.3, UNTL = 24.7 (c) $\hat{C}_{p} = 0.85$ (d) $\hat{p}_{\text{rework}} = 0.0275$, $\hat{p}_{\text{scrap}} = 0.00069$, Total = 2.949% (e) $\hat{p}_{\text{rework}} = 0.00523$, $\hat{p}_{\text{scrap}} = 0.00523$, Total = 1.046%
- 6.15. (a) x̄ chart: CL = 79.53, UCL = 84.58, LCL = 74.49
 R chart: CL = 8.75, UCL = 18.49, LCL = 0 Process is in statistical control.
 (b) Several subgroups exceed UCL on R chart.
- 6.17. (a) \bar{x} chart: CL = 34.00, UCL = 37.50, LCL = 30.50 R chart: CL = 3.42, UCL = 8.81, LCL = 0 (b) Detect shift more quickly. (c) \bar{x} chart: CL = 34.00, UCL = 36.14, LCL = 31.86 R chart: CL = 5.75, UCL = 10.72, LCL = 0.78
- **6.19.** (a) \bar{x} chart: CL = 223, UCL = 237.37, LCL = 208.63 R chart: CL = 34.29, UCL = 65.97, LCL = 2.61 (b) $\hat{\mu} = 223$; $\hat{\sigma}_x = 12.68$ (c) $\hat{C}_P = 0.92$. (d) $\hat{p} = 0.00578$
- **6.21.** (a) $\hat{\sigma}_x = 1.60$ (b) \bar{x} chart: UCL = 22.14, LCL = 17.86 s chart: UCL = 3.13, LCL = 0 (c) Pr{in control} = 0.57926
- **6.23.** $\hat{C}_P = 0.8338$
- **6.25.** (a) \bar{x} chart: UCL = 22.63, LCL = 17.37 R chart: UCL = 9.64, LCL = 0 (b) $\hat{\sigma}_x = 1.96$. (c) $\hat{C}_P = 0.85$. (d) Pr{not detect} = 0.05938
- **6.27.** The process continues to be in a state of statistical control.
- **6.29.** (a) \bar{x} chart: CL = 449.68, UCL = 462.22, LCL = 437.15 s chart: CL = 17.44, UCL = 7.70, LCL = 0
- **6.31.** Pr{detecting shift on 1st sample} = 0.37
- **6.33.** (a) $\overline{\overline{x}} = 20.26$, $UCL_{\overline{x}} = 23.03$, $LCL_{\overline{x}} = 17.49$; $\overline{R} = 4.8$, $UCL_{R} = 10.152$, $LCL_{R} = 0$ (b) $\hat{p} = 0.0195$

- **6.35.** (a) \bar{x} Recalculating limits without samples 1, 12, and 13: \bar{x} chart: CL = 1.45, UCL = 5.46, LCL = (2.57 R chart: CL = 6.95, UCL = 14.71, LCL = 0 (b) Samples 1, 12, 13, 16, 17, 18, and 20 are out-of-control, for a total 7 of the 25 samples, with runs of points both above and below the centerline. This suggests that the process is inherently unstable, and that the sources of variation need to be identified and removed.
- **6.37.** (a) $\overline{R} = 45.0$, UCL_R = 90.18, LCL_R = 0 (b) $\hat{\mu} = 429.0$, $\hat{\sigma}_x = 17.758$ (c) $\hat{C}_p = 0.751$; $\hat{p} = 0.0533$ (d) To minimize fraction nonconforming the mean should be located at the nominal dimension (440) for a constant variance.
- **6.39.** (a) $UCL_{\bar{x}} = 108, LCL_{\bar{x}} = 92$. (b) $UCL_{\bar{x}} = 111.228, LCL_{\bar{x}} = 88.772$.
- **6.41.** ARL₁ = 2.986
- **6.43.** (a) $CL_s = 9.213, UCL_s = 20.88, LCL_s = 0.$ (b) $UCL_{\bar{x}} = 209.8, LCL_{\bar{x}} = 190.2.$
- **6.45.** (a) $\overline{x} = 90$, UCL $_{\overline{x}} = 91.676$, LCL $_{\overline{x}} = 88.324$; $\overline{R} = 4$, UCL $_{R} = 7.696$, LCL $_{R} = 0.304$ (b) $\hat{\sigma}_{x} = 1.479$. (c) $\overline{s} = 1.419$, UCL $_{s} = 2.671$, LCL $_{s} = 0.167$.
- **6.47.** Pr{detect shift on 1st sample} = 0.1587
- **6.49.** (a) $\alpha = 0.0026$. (b) $\hat{C}_P = 0.667$. (c) Pr{not detect on 1st sample} = 0.5000. (d) UCL $_{\bar{x}} = 362.576$, LCL $_{\bar{x}} = 357.424$.
- **6.51.** (a) $\hat{\mu}$ = 706.00; $\hat{\sigma}_x$ = 1.827. (b) UNTL = 711.48, LNTL = 700.52. (c) \hat{p} = 0.1006. (d) Pr{detect on 1st sample} = 0.9920

(e) Pr{detect by 3rd sample}

- **6.53.** $\overline{\overline{x}} = 16.1052$; $\hat{\sigma}_x = 0.021055$; $\overline{\text{MR2}} = 0.02375$ Assumption of normally distributed coffee can weights is valid. %underfilled = 0.0003%.
- **6.55.** (a) Viscosity measurements appear to follow a normal distribution. (b) The process appears to be in statistical control, with no out-of-control points, runs, trends, or other patterns. (c) $\hat{\mu} = 2928.9$; $\hat{\sigma}_x = 131.346$; $\overline{\text{MR2}} = 148.158$

- 6.57. (a) The process is in statistical control. The normality assumption is reasonable.(b) It is clear that the process is out of control during this period of operation.(c) The process has been returned to a state of statistical control.
- 6.59. The measurements are approximately normally distributed. The out-of-control signal on the moving range chart indicates a significantly large difference between successive measurements (7 and 8).

 Consider the process to be in a state of statistical process control.
- (a) The data are not normally distributed. The distribution of the natural-log transformed uniformity measurements is approximately normally distributed.
 (b) x̄ chart: CL = 2.653, UCL = 3.586, LCL = 1.720
 R chart: CL = 0.351, UCL = 1.146, LCL = 0
- **6.63.** x chart: $\bar{x} = 16.11$, $UCL_x = 16.17$, $LCL_x = 16.04$ MR chart: $\overline{MR2} = 0.02365$, $UCL_{MR2} = 0.07726$, $LCL_{MR2} = 0$
- **6.65.** x chart: $\overline{x} = 2929$, UCL $_x = 3338$, LCL $_x = 2520$ MR chart: $\overline{MR2} = 153.7$, UCL $_{MR2} = 502.2$, LCL $_{MR2} = 0$
- **6.67.** (a) $\hat{\sigma}_x = 1.157$. (b) $\hat{\sigma}_x = 1.682$. (c) $\hat{\sigma}_x = 1.137$ (d) $\hat{\sigma}_{x, \text{span } 3} = 1.210$, $\hat{\sigma}_{x, \text{span } 4} = 1.262$, ..., $\hat{\sigma}_{x, \text{span } 19} = 1.406$, $\hat{\sigma}_{x, \text{span } 20} = 1.435$
- **6.69.** (a) \bar{x} chart: CL = 11.76, UCL = 11.79, LCL = 11.72 R chart (within): CL = 0.06109, UCL = 0.1292, LCL = 0 (c) I chart: CL = 11.76, UCL = 11.87, LCL = 11.65 MR2 chart (between): CL = 0.04161, UCL = 0.1360, LCL = 0
- 6.71. (b) R chart (within): CL = 0.06725, UCL = 0.1422, LCL = 0
 (c) I chart: CL = 2.074, UCL = 2.159, LCL = 1.989
 MR2 chart (between): CL = 0.03210, UCL = 0.1049, LCL = 0
 (d) Need lot average, moving range between lot averages, and range within a lot. I chart: CL = 2.074, UCL = 2.133, LCL = 2.015

MR2 chart (between): CL = 0.02205, UCL = 0.07205, LCL = 0 R chart (within): CL = 0.1335, UCL = 0.2372, LCL = 0.02978

CHAPTER 7

- **7.1.** $\bar{p} = 0.0585$, UCL = 0.1289, LCL = 0. Sample 12 exceeds UCL. Without sample 12: $\bar{p} = 0.0537$, UCL = 0.1213, LCL = 0.
- **7.3.** For n = 80, $UCL_i = 0.1397$, $LCL_i = 0$. Process is in statistical control.
- **7.5.** (a) $\overline{p} = 0.1228$, UCL = 0.1425, LCL = 0.1031 (b) Data should not be used since many subgroups are out of control.
- 7.7. Pr{detect shift on 1st sample} = 0.278, Pr{detect shift by 3rd sample} = 0.624
- **7.9.** $\bar{p} = 0.10$, UCL = 0.2125, LCL = 0 p = 0.212 to make $\beta = 0.50$. $n \ge 82$ to give positive LCL.
- **7.11.** n = 81
- **7.13.** (a) $\bar{p} = 0.07$, UCL = 0.108, LCL = 0.032 (b) Pr{detect shift on 1st sample} = 0.297 (c) Pr{detect shift on 1st or 2nd sample} = 0.506
- **7.15.** (a) Less sample 3: $n\bar{p} = 14.78$, UCL = 27.421, LCL = 4.13 (b) Pr{detect shift on 1st sample} = 0.813
- **7.17.** (a) $n\overline{p} = 40$, UCL = 58, LCL = 22. (b) Pr{detect shift on 1st sample} = 0.583.
- **7.19.** ARL1 = $1.715 \approx -2$
- 7.21. (a) CL = 0.0221 for n = 100: UCL = 0.0622, LCL = 0 for n = 150: UCL = 0.0581, LCL = 0 for n = 200: UCL = 0.0533, LCL = 0 for n = 250: UCL = 0.0500, LCL = 0 (b) $Z_i = (\hat{p}_i - 0.0221) / \sqrt{0.0221(1 - 0.0221)/n_i}$
- **7.23.** $Z_i = (\hat{p}_i 0.0221) / \sqrt{0.0216 / n_i}$
- 7.25. $n \ge 892$
- **7.27.** (a) L = 2.83. (b) $n\bar{p} = 20$, UCL = 32.36, LCL = 7.64. (c) Pr{detect shift on 1st sample} = 0.140.
- **7.29.** (a) $n \ge 397$. (b) n = 44.
- **7.31.** (a) $\bar{p} = 0.02$, UCL = 0.062, LCL = 0.
 - (b) Process has shifted to $\overline{p} = 0.038$.

- **7.33.** $n\bar{p} = 2.505$, UCL = 7.213, LCL = 0
- **7.35.** $Z_i = (\hat{p}_i 0.06) / \sqrt{0.0564 / n_i}$
- **7.37.** Variable u: CL = 0.7007; UCL $_i$ = 0.7007 + $3\sqrt{0.7007/n_i}$; LCL $_i$ = 0.7007 $3\sqrt{0.7007/n_i}$ Averaged u: CL = 0.701, UCL = 1.249, LCL = 0.1527
- **7.39.** $Z_i = (u_i 0.7007) / \sqrt{0.7007 / n_i}$
- **7.41.** \bar{c} = 8.59, UCL = 17.384, LCL = 0. Process is not in statistical control.
- **7.43.** (a) *c* chart: CL = 15.43, UCL = 27.21, LCL = 3.65 (b) *u* chart: CL = 15.42, UCL = 27.20, LCL = 3.64
- **7.45.** (a) c chart: CL = 4, UCL = 10, LCL = 0 (b) u chart: CL = 1, UCL = 2.5, LCL = 0
- **7.47.** (a) *c* chart: CL = 9, UCL = 18, LCL = 0 (b) *u* chart: CL = 4, UCL = 7, LCL = 1
- **7.49.** $\bar{c} = 7.6$, UCL = 13.00, LCL = 2.20
- **7.51.** $\overline{u} = 7$; $UCL_i = 7 + 3\sqrt{7/n_i}$; $LCL_i = 7 3\sqrt{7/n_i}$
- **7.53.** $\bar{c} = 8.5$, UCL = 13.98, LCL = 3.02
- **7.55.** $\overline{u} = 4$, UCL = 9
- **7.57.** (a) $\bar{c} = 0.533$, UCL = 1.993, LCL = 0. (b) $\alpha = 0.104$. (c) $\beta = 0.271$. (d) ARL₁ = 1.372 ≈ 2 .
- **7.59.** (a) $\bar{c} = 4$, UCL = 10, LCL = 0. (b) $\alpha = 0.03$.
- **7.61.** $n > L^2 / \bar{c}$
- **7.65.** The variable NYRSB can be thought of as an "inspection unit," representing an identical "area of opportunity" for each "sample." The "process characteristic" to be controlled is the rate of CAT scans. A *u* chart which monitors the average number of CAT scans per NYRSB is appropriate.

- **8.1.** $\hat{C}_p = 1.17, \ \hat{C}_{pk} = 1.13$
- **8.3.** $\hat{C}_p = 5.48, \ \hat{C}_{pk} = 4.34, \ \hat{C}_{pkm} = 0.43$
- **8.5.** (a) $\hat{C}_p = 2.98$. (b) $\hat{C}_{pk} = 1.49$. (c) $\hat{p}_{\text{actual}} = 0.000004$, $\hat{p}_{\text{potential}} = 0.000000$.
- **8.7.** (a) $\hat{C}_p = 0.75$. (b) $\hat{C}_{pk} = 0.71$.

- (c) $\hat{C}_{pkm} = 0.70$. (d) $\hat{p}_{\text{Actual}} = 0.025348$, $\hat{p}_{\text{Potential}} = 0.024220$
- **8.9.** Process A: $\hat{C}_p = \hat{C}_{pk} = \hat{C}_{pm} = 1.045$, = 0.001726 Process B: $\hat{C}_p = 3.133$, $\hat{C}_{pk} = 1.566$, $\hat{C}_{pm} = 0.652$, $\hat{p} = 0.000001$
- **8.11.** $6\hat{\sigma} = 0.1350$
- **8.13.** $6\hat{\sigma} = 0.05514$
- **8.15.** (a) $6\hat{\sigma} = 73.2$. (b) $C_{pu} = 0.58$, $\hat{p} = 0.041047$.
- **8.17.** No. Data is not normally distributed.
- **8.19.** $1.26 \le C_p$, $\alpha = 0.12$
- **8.21.** (a) $\hat{C}_{pk} = 0.42$ (b) $0.2957 \le C_{pk} \le 0.5443$
- 8.23. $\hat{\sigma}_{\text{process}} = 4$
- **8.25.** (a) *R* chart indicates operator has no difficulty making consistent measurements. (b) $\hat{\sigma}_{\text{total}}^2 = 4.717$, $\hat{\sigma}_{\text{product}}^2 = 1.695$. (c) 62.5%. (d) P/T = 0.272.
- **8.27.** (a) $6\hat{\sigma}_{\text{gage}} = 8.154$. (b) R chart indicates operator has difficulty using gage.
- **8.31.** $\hat{p} = 0.4330$
- **8.33.** $\hat{\mu}_{\text{Weight}} = 48$, $\hat{\sigma}_{\text{Weight}} = 0.04252$
- **8.35.** $\mu_I \cong \mu_E / (\mu_{R_1} + \mu_{R_2})$ $\sigma_I^2 \cong \sigma_E^2 / (\mu_{R_1} + \mu_{R_2})^2 + (\mu_E^2 / (\mu_{R_1} + \mu_{R_2})^2)$ $(\sigma_{R_1}^2 + \sigma_{R_2}^2)$
- **8.37.** $C \sim N(0.006, 0.000005)$. Pr{positive clearance} = 0.9964.
- **8.39.** UTL = 323.55
- **8.41.** UTL = 372.08
- **8.43.** (a) $0.1257 \le x \le 0.1271$. (b) $0.1263 \le \overline{x} \le 0.1265$.

- **9.1.** (a) K = 12.5, H = 125. Process is out of control on upper side after observation 7. (b) $\hat{\sigma} = 34.43$
- 9.3. (a) K = 12.5, H = 62.5. Process is out of control on upper side after observation 7.(b) Process is out of control on lower side at sample 6 and upper at sample 15.
- **9.5.** Process is in control. $ARL_0 = 370.84$

- **9.7.** (a) $\hat{\sigma} = 12.16$. (b) Process is out of control on upper side after reading 2.
- **9.9.** (a) $\hat{\sigma} = 5.95$. (b) Process is out of control on lower side at start, then upper after observation 9.
- **9.11.** Process is out of control on upper side after observation 7.
- **9.13.** ARL₀ = 215.23, ARL₁ = 25.02
- **9.15.** K = 54.35, H = 543.5. Process is out of control virtually from the first sample.
- 9.17. EWMA chart: CL = 1050, UCL = 1065.49, LCL = 1034.51.Process exceeds upper control limit at sample 10.
- **9.19.** EWMA chart: CL = 8.02, UCL = 8.07, LCL = 7.97. Process is in control.
- **9.21.** EWMA chart: CL = 950, UCL = 957.53, LCL = 942.47. Process is out of control at samples 8, 12, and 13.
- **9.23.** EWMA chart: CL = 175, UCL = 177.3, LCL = 172.70. Process is out of control.
- 9.25. EWMA chart: CL = 3200, UCL = 3203.69, LCL = 3196.31.Process is out of control from the first sample.
- **9.27.** MA chart: CL = 8.02, UCL = 8.087, LCL = 7.953. Process is in control.
- **9.29.** MA chart: CL = 1050, UCL = 1080.62, LCL = 1019.38.

 Process is out of control at sample 10.
- **9.35.** k = 0.5L

- **10.1.** \bar{x} chart: CL = 0.55, UCL = 4.44, LCL = -3.34 R chart: CL = 3.8, UCL = 9.78, LCL = 0
- **10.5.** \bar{x} chart: CL = 52.988, UCL = 55.379, LCL = 50.596 R chart: CL = 2.338, UCL = 6.017, LCL = 0
- 10.7. (a) \bar{x} chart: CL = 52.988, UCL = 58.727, LCL = 47.248 R chart: CL = 2.158, UCL = 7.050, LCL = 0 (c) \bar{x} chart: CL = 52.988, UCL = 55.159, LCL = 49.816 s chart: CL = 1.948, UCL = 4.415, LCL = 0
- **10.9.** (a) UCL = 44.503, LCL = 35.497 (b) UCL = 43.609, LCL = 36.391 (c) UCL = 43.239, LCL = 36.761

- **10.13.** \bar{x} chart: CL = 50, UCL = 65.848, LCL = 34.152
- **10.15.** (a) $\hat{\sigma} = 4.000$. (b) $\hat{p} = 0.1056$. (c) UCL = 619.35, LCL = 600.65.
- **10.17.** $\mu_0 = 0$, $\delta = 1\sigma$, k = 0.5, h = 5, UCL = 97.9, LCL = (97.9, no FIR. No observations exceed the control limit.
- **10.19.** $\alpha = 0.1$, $\lambda = 0.9238$, $\hat{\sigma} = 15.93$. Observation 16 exceeds UCL.
- **10.21.** $\mu_0 = 0$, $\delta = 1\sigma$, k = 0.5, h = 5, UCL = 22.79, LCL = (22.79, no FIR. No observations exceed the control limits.
- **10.23.** $\alpha = 0.1$, $\lambda = 0.7055$, = 3.227. Observations 8, 56 and 90 exceed control limits.
- **10.25.** $\mu_0 = 0$, $\delta = 1\sigma$, k = 0.5, h = 5, UCL = 36.69, LCL = (36.69, no FIR. No observations exceed the control limit.
- **10.27.** $\alpha = 0.1$, $\lambda = 0.150$, $\hat{\sigma} = 7.349$. Several observations exceed the control limits.
- 10.29. (a) $r_1 = 0.49$ (b) I chart: CL = 28.57, UCL = 37.11, LCL = 20.03 (c) $\mu_0 = 28.569$, $\delta = 1\sigma$, k = 0.5, h = 5, UCL = 14.24, LCL = (14.24, no FIR. Several observations are out of control on both lower and upper sides. (d) EWMA chart: $\lambda = 0.15$, L = 2.7, CL = 28.569, UCL = 30.759, LCL = 26.380 (e) Moving CL EWMA chart: $\alpha = 0.1$, $\lambda = 0.150$, = 2.85. A few observations are beyond the lower

A few observations are beyond the lower control limit.

- (f) $\xi = 20.5017$, $\phi_1 = 0.7193$, $\phi_2 = -0.4349$. Set up an *I* and MR chart for residuals. *I* chart: CL = -0.04, UCL = 9.60, LCL = -9.68
- **10.31.** (a) E(L) = \$4.12/hr. (b) E(L) = \$4.98/hr. (c) n = 5, $k_{\text{opt}} = 3.080$, $h_{\text{opt}} = 1.368$, $\alpha = 0.00207$, $1 \beta = 0.918$, E(L) = \$4.01392/hr
- **10.33.** (a) E(L) = \$16.17/hr. (b) E(L) = \$10.39762/hr.

CHAPTER 11

- **11.1.** UCL_{Phase 2} = 14.186, LCL_{Phase 2} = 0
- **11.3.** UCL_{Phase 2} = 13.186
- 11.5. (a) $UCL_{Phase\ 2} = 23.882$, $LCL_{Phase\ 2} = 0$. (b) $UCL_{chi-square} = 18.548$.
- 11.7. (a) UCL_{Phase 2} = 39.326. (b) UCL_{chi-square} = 25.188. (c) m = 988.

- **11.9.** Assume $\alpha = 0.01$. UCL_{Phase 1} = 32.638, UCL_{Phase 2} = 35.360
- 11.11. $(a) \mathbf{\Sigma} = \begin{bmatrix} 1 & 0.8 & 0.8 \\ 0.8 & 1 & 0.8 \\ 0.8 & 0.8 & 1 \end{bmatrix}$
 - (b) $UCL_{chi-square} = 7.815$.
 - (c) $T^2 = 11.154$. (d) $d_1 = 0.043$, $d_2 = 8.376$, $d_3 = 6.154$.
 - (e) $T^2 = 21.800$. (f) $d_1 = 16.800$, $d_2 = 16.800$, $d_3 = 17.356$.
- 11.13. $\Sigma = \begin{bmatrix} 4.440 & -0.016 & 5.395 \\ -0.016 & 0.001 & -0.014 \\ 5.395 & -0.014 & 27.599 \end{bmatrix}$
- **11.15.** $\lambda = 0.1$ with UCL = H = 12.73, ARL₁ is between 7.22 and 12.17.
- **11.17.** $\lambda = 0.2$ with UCL = H = 9.65. ARL₁ is between 5.49 and 10.20.
- 11.19. Significant variables for y_1 are x_1 , x_3 , x_4 , x_8 , and x_9 .

 Control limits for y_1 model I chart: CL = 0, UCL = 2.105, LCL = -2.105Control limits for y_1 model MR chart: CL = 0.791, UCL = 2.586, LCL = 0Significant variables for y_2 are x_1 , x_3 , x_4 , x_8 , and x_9 .

 Control limits for y_2 model I chart: CL = 0, UCL = 6.52, LCL = -6.52Control limits for y_2 model MR chart: CL = 0
- **11.21.** (a) $\mathbf{z}_1 = \{0.29168, 0.29428, 0.19734, 0.83902, 3.20488, 0.20327, -0.99211, -1.70241, -0.14246, -0.99498, 0.94470, -1.21950, 2.60867, -0.12378, -1.10423, -0.27825, -2.65608, 2.36528, 0.41131, -2.14662<math>\}$

2.45, UCL = 8.02, LCL = 0

- **12.3.** Process is adjusted at observations 3, 4, 7, and 29.
- 12.5. m = 1, $Var_1 = 147.11$, $Var_1/Var_1 = 1.000$ m = 2, $Var_2 = 175.72$, $Var_2/Var_1 = 1.195$ m = 3, $Var_3 = 147.47$, $Var_3/Var_1 = 1.002$ m = 4, $Var_4 = 179.02$, $Var_4/Var_1 = 1.217$ m = 5, $Var_5 = 136.60$, $Var_5/Var_1 = 0.929$, . . . Variogram stabilizes near 1.5 $r_1 = 0.44$, $r_2 = 0.33$, $r_3 = 0.44$, $r_4 = 0.32$, $r_5 = 0.30$, . . . Sample ACF slowly decays.

- 12.7. In each control scheme, adjustments are made after each observation following observation2. There is no difference in results; variance for each procedure is the same.
- **12.9.** (b) Average is closer to target (44.4 vs. 46.262), and variance is smaller (223.51 vs. 78.32).
 - (c) Average is closer to target (47.833) and variance is smaller (56.40).

- **13.1.** Glass effect: $F_0 = 273.79$, P value = 0.000 Phosphor effect: $F_0 = 8.84$, P value = 0.004 Glass × Phosphor interaction: $F_0 = 1.26$, P value = 0.318
- **13.3.** Normality assumption is reasonable. Constant variance assumption is reasonable.
- **13.5.** Plots of residuals versus factors A and C show unequal scatter. Residuals versus predicted indicates that variance not constant. Residuals are approximately normally distributed.
- **13.7.** Largest effect is factor A.
- **13.9.** Block 1: (1), ab, ac, bc, ad, bd, cd, ae, be, ce, de, abcd, abce, abde, acde, bcde
 Block 2: a, b, c, d, e, abc, abd, acd, bcd, abe, ace, bce, ade, bde, cde, abcde
- **13.11.** (b) I = ACE = BDE = ABCD, A = CE = BCD = ABDE, B = DE = ACD = ABCE, C = AE = ABD = BCDE, D = BE = ABC = ACDE, E = AC = BD = BCDE, AB = CD = ADE = BCE, AD = BC = ABE = CDE(c) A = -1.525, B = -5.175, C = 2.275, D = -0.675, E = 2.275, AB = 1.825, AD = -1.275(d) With only main effect B: $F_0 = 8.88$, P value = 0.025.
- **13.13.** (a) Main Effects: $F_0 = 1.70$, P value = 0.234 2-Way Interactions: $F_0 = 0.46$, P value = 0.822 Curvature: $F_0 = 16.60$, P value = 0.004 Lack of fit: $F_0 = 0.25$, P value = 0.915

(e) Residuals plots are satisfactory.

13.15. (a) A = 47.7, B = -0.50, C = 80.6, D = -2.40, AB = 1.10, AC = 72.80, AD = -2.00 (b) Model with C, AC, A: Main Effects: $F_0 = 1710.43$, P value = 0.000 2-Way Interactions: $F_0 = 2066.89$, P value = 0.000 Curvature: $F_0 = 1.11$, P value = 0.327

CHAPTER 14

- **14.1.** (b) $\Delta x = 1$, $\Delta x_2 = 0.6$
- **14.3.** (a) CCD with k = 2 and $\alpha = 1.5$. The design is not rotatable.

(b)
$$y = 160.868 - 58.294x_1 + 2.412x_2$$

$$-10.855x_1^2 + 6.923x_2^2 - 0.750x_1x_2$$

(c)
$$x_1 = +1.5$$
, $x_2 = -0.22$

(d) Temp =
$$825$$
, Time = 26.7

14.5. (a) CCD with k = 2 and $\alpha = 1.4$. The design is rotatable.

(b)
$$y = 13.727 + 0.298x_1 - 0.407x_2$$

- $0.125x_1^2 - 0.079x_2^2 + 0.055x_1x_2$

From the plots and the optimizer, setting x_1 in a range from 0 to +1.4 and setting x_2 between -1 and -1.4 will maximize viscosity.

- (a) The design is resolution IV with A = BCD, B = ACD, C = ABD, D = ABC, E = ABCDE, AB = CD, AC = BD, AD = BC, AE = BCDE, BE = ACDE, CE = ABDE, DE = ABCE, ABE = CDE, ACE = BDE, ADE = BCE.
 (b) Factors A, B, D, E and interaction BE affect mean free height.
 (c) Factors A, B, D and interactions CE and ADE affect standard deviation of free height.
 (e) A 2⁵⁻¹, resolution V design can be generated with E = ± ABCD.
- 14.9. Mean Free Height = 7.63 + 0.12A 0.081BVariance of Free Height = $(0.046)^2 + (-0.12 + 0.077B)^2 + 0.02$ One solution with mean Free Height ≈ 7.50 and minimum standard deviation of Free Height is A = -0.42 and B = 0.99.
- 14.11. (a) Recommended operating conditions are temperature = +1.4109 and pressure = (1.4142, to achieve predicted filtration time of 36.7.
 (b) Recommended operating conditions are temperature = +1.3415 and pressure = (0.0785, to achieve predicted filtration time

CHAPTER 15

of 46.0.

- **15.1.** Two points on OC curve are $P_a\{p = 0.007\} = 0.95190$ and $P_a\{p = 0.080\} = 0.08271$.
- **15.3.** (a) Two points on OC curve are $P_a\{d=35\} = 0.95271$ and $P_a\{d=375\} = 0.10133$.

- (b) Two points on OC curve are $P_a\{p = 0.0070\} = 0.9519$ and $P_a\{p = 0.0750\} = 0.1025$.
- (c) Difference in curves is small. Either is appropriate.
- **15.5.** n = 80, c = 7
- **15.7.** Different sample sizes offer different levels of protection. Consumer is protected from an LTPD = 0.05 by $P_a\{N = 5000\} = 0.00046$ or $P_a\{N = 10,000\} = 0.00000$, but pays for high probability of rejecting acceptable lots (i.e., for p = 0.025, $P_a\{N = 5000\} = 0.294$ while $P_a\{N = 10,000\} = 0.182$).
- **15.9.** AOQL = 0.0234
- **15.11.** (a) Two points on OC curve are $P_a\{p=0.016\}=0.95397$ and $P_a\{p=0.105\}=0.09255$.
 - (b) p = 0.103
 - (d) n = 20, c = 0. This OC curve is much steeper.
 - (e) For c = 2, $Pr\{reject\} = 0.00206$, ATI = 60. For c = 0, $Pr\{reject\} = 0.09539$, ATI = 495
- **15.13.** (a) Constants for limit lines are: k = 1.0414, $h_1 = 0.9389$, $h_2 = 1.2054$, and s = 0.0397. (b) Three points on OC curve are $P_a\{p_1 = 0.01\} = 1 \alpha = 0.95$, $P_a\{p_2 = 0.10\} = \beta = 0.10$, and $P_a\{p = s = 0.0397\} = 0.5621$.
- **15.15.** AOQ = $[P_a \times p \times (N-n)] / [N-P_a \times (n p) (1-P_a) \times (N p)]$
- **15.17.** Normal: sample size code letter = H, n = 50, Ac = 1, Re = 2 Tightened: sample size code letter = J, n = 80, Ac = 1, Re = 2 Reduced: sample size code letter = H, n = 20, Ac = 0, Re = 2
- **15.19.** (a) Sample size code letter = L Normal: n = 200, Ac = 3, Re = 4 Tightened: n = 200, Ac = 2, Re = 3 Reduced: n = 80, Ac = 1, Re = 4
- **15.21.** (a) Minimum cost sampling effort that meets quality requirements is $50,001 \le N \le 100,000$, n = 65, c = 3. (b) ATI = 82

- **16.1.** (a) n = 35, k = 1.7. (b) $Z_{LSL} = 2.857 > 1.7$, so accept lot. (c) From nomograph, $P_a\{p = 0.05\} \approx 0.38$
- **16.3.** AOQ = $P_a \times p \times (N-n) / N$, \rightarrow ATI = $n + (1 P_a) \times (N-n)$

- **16.5.** From MIL-STD-105E, n = 200 for normal and tightened and n = 80 for reduced. Sample sizes required by MIL-STD-414 are considerably smaller than those for MIL-STD-105E.
- **16.7.** Assume inspection level IV. Sample size code letter = O, n = 100, $k_{\text{normal}} = 2.00$, $k_{\text{tightened}} = 2.14$. $Z_{\text{LSL}} = 3.000 > 2.00$, so accept lot.
- **16.9.** (a) From nomograph for variables: n = 30, k = 1.8
 - (b) Assume inspection level IV. Sample size code letter = M

Normal: n = 50, M = 1.00

Tightened: n = 50, M = 1.71

Reduced: n = 20, M = 4.09

- σ known permits smaller sample sizes than σ unknown.
- (c) From nomograph for attributes: n = 60, c = 2

Variables sampling is more economic when σ is known.

(d) Assume inspection level II. Sample size code letter = L

Normal: n = 200, Ac = 5, Re = 6

Tightened: n = 200, Ac = 3, Re = 4

Reduced: n = 80, Ac = 2, Re = 5

Much larger samples are required for this plan than others.

- **16.11.** (a) Three points on OC curve are $P_a\{p=0.001\}=0.9685$, $P_a\{p=0.015\}=0.9531$, and $P_a\{p=0.070\}=0.0981$.
 - (b) ATI = 976
 - (c) $P_a\{p = 0.001\} = 0.9967$, ATI = 131
 - (d) $P_a{p = 0.001} = 0.9958$, ATI = 158
- **16.13.** i = 4, $P_a\{p = 0.02\} = 0.9526$
- **16.15.** For f = 1/2, i = 140: u = 155.915, v = 1333.3, AFI = 0.5523, $P_a\{p = 0.0015\} = 0.8953$

For f = 1/10, i = 550: u = 855.530, v = 6666.7, AFI = 0.2024, $P_a\{p$ = 0.0015 $\}$ = 0.8863

For f = 1/100, i = 1302: u = 4040.00, v = 66666.7, AFI = 0.0666, $P_a\{p$ = 0.0015 $\}$ = 0.9429

- **16.17.** For f = 1/5, i = 38: AFI = 0.5165, $P_a \{ p = 0.0375 \} = 0.6043$
 - For f = 1/25, i = 86: AFI = 0.5272, $P_a \{ p = 0.0375 \} = 0.4925$

Index

100% inspection, 633 Autocorrelation function, 448 2² factorial design, 564 Autoregressive integrated moving average model, 453 2³ design, 570, 573 Average outgoing quality (AOQ), 644 2^{k-1} design, 587 Average outgoing quality limit (AOQL), 645, 664, 667 2^{k-p} design, 592 Average run length, 191, 248, 249, 262, 306, 438, 444 2^k factorial design, 564, 569, 578 Average sample number, 649, 654, 688 Average time to signal, 192, 250 Average total inspection, 645 Acceptable quality level (AQL), 640, 655 В Acceptance control charts, 442 Acceptance sampling, 13, 15, 631, 655, 663, 671, 681, Batch means control charts, 458 683, 686 Bernoulli distribution, 108 Bernoulli trials, 77, 80, 108 Action limits, 189 Actual process capability, 356 Between/within control charts, 271 Adaptive control charts, 462 Bias in a gauge, 369 Adjustment chart, 534 Binomial approximation to the hypergeometric Aesthetics, 5 distribution, 96 Aliases, 588 Binomial distribution, 77, 640 Alternate fraction, 589 Bins in a histogram, see histogram Alternative hypothesis, 112 Bivariate normal distribution, 498 American Society for Quality (Control), 12 Blocking, 585 Analysis of quality costs, 39 Bounded adjustment chart, 536 Analysis of variance (ANOVA), 140, 143, 146, 373, 558 Box plot, 71 Analysis procedure for factorial experiments, 569 Brook and Evans method, 444 Analyze, 52 Appraisal costs, 37 Armond V. Feigenbaum, 22 c chart, 309 Assignable causes, 52, 181 Cause-and-effect diagram, 202, 207, 312 Attribute data, 8, 289, 367 Cautions about process performance indices, 363 Attribute gauge capability, 381 Center line on a Shewhart control chart, 182 Attributes control charts, 187 Center points in 2^k designs, 582 Attributes sampling plans, 634, 637 Central composite design, 607, 610 Central limit theorem, 85, 106 Autocorrelated process data, 188, 446

Chain sampling, 641, 681	Crossed array design, 612
Chance cause of variation, 52, 181	Curtailment in double sampling, 650
Changepoint model, 475	Cuscore charts, 473
Check sheet, 199, 208, 217	Cusum, 400, 403, 408, 410, 413, 417, 437
Chi-square distribution, 106, 259	Cusum status chart, 406
Class intervals in a histogram, see histogram	· · · · · · · · · · · · · · · · · · ·
Combined array design, 613	D
Combined Shewhart-cusum procedure, 410	Defect, 9
Common cause of variation, see chance cause of	Defect concentration diagram, 204
variation	Defective, 9
Completely randomized design, 143, 559	Define, 49
Concurrent engineering, 9	Defining relation, 587, 593
Confidence interval, 114, 115, 119, 121, 130, 134, 138,	Definitions of quality, 6
140, 163, 359, 376	Delta method, 387
Confidence interval on a single proportion, 123	Demerit systems, 321
Confidence interval on the difference in two means,	Deming's 14 points, 14
variances known, 130	Deming's deadly diseases, 20
Confidence interval on the difference in two means,	Deming's obstacles to success, 21
variances unknown, 134	Design for six sigma (DFSS), 32
Confidence interval on the difference in two	Design generators, 587, 593
proportions, 140	Design matrix, 564
Confidence interval on the mean with known variance,	Design of a cusum, 408
115	Design resolution, 589
Confidence interval on the mean with unknown variance, 119	Designed experiment, 14, 59, 211, 297, 366, 547, 550, 564, 587, 602, 610, 611, 613
Confidence interval on the ratio of variances of two	Deviation from nominal (DNOM) control chart, 435
normal distributions, 138	Difference control chart, 483
Confidence interval on the variance of a normal	Dimensions of quality, 4, 42
distribution, 121	Discrete distribution, 73
Confidence intervals in gauge R&R studies, 376	Discrimination ratio, 372
Confidence intervals in regression, 163	DMAIC, 29, 45, 206
Confidence intervals on process capability ratios, 359	Dodge-Romig sampling plans, 663
Conformance to standards, 5	Double-sampling plan, 634, 646
Confounding, 585	Durability, 5
Consumer's risk, 113, 379	
Continuous distribution, 73	E
Continuous sampling plans, 683	Economically optimal \bar{x} charts, 469
Contour plot, 577	Elements of a successful SPC program, 206
Contrasts, 565	Engineering (process) control, 15, 188, 527, 540
Control, 54	Estimator, 110
Control chart, 13, 226, 251, 259, 260, 261, 271, 288, 300,	Evolutionary operation (EVOP), 603, 619
304, 308, 315, 318, 399, 400, 419, 428, 434, 435, 439,	EVOP cycle, 620
443, 445, 455, 458, 462, 473, 476, 485, 486, 499, 502,	EVOP phase, 621
509	EWMA for correlated data, 453, 457
Control chart for a six-sigma process, 441	Exponential distribution, 88, 90, 324
Control chart for fraction nonconforming, 289, 291, 301	Exponentially weighted moving average (EWMA)
Control chart for individuals, 259	control chart, 419, 421, 422, 437, 453
Control chart for nonconformities (defects) per unit, 315	External failure costs, 38
Control chart for nonconformities, 308	
Control chart for time between events, 324	F
Control charts for censored data, 486	Factorial design, 14, 373, 547, 552, 564
Control ellipse, 499	Failure modes and effects analysis (FEMA), 52
Control limits, 182, 189, 198, 237, 242	Failure rate, 89
Controllable process variables, 550, 611, 619	False defectives in gauge R&R studies, 377
Covariance matrix, 154, 497, 498, 507	Fast initial response cusum, 410
C _p , 351	Fast initial response on the EWMA control chart, 425
C_{pk}^{P} , 355	F-distribution, 107
$\binom{p_k}{p_l}$, 352	Features, 5
C_{pu}^{pr} , 352	Feedback control, see engineering control
Critical region for a statistical test, 113	Financial systems integration in six-sigma, 47
Critical-to-quality characteristics (CTQs), 8	First quartile, 65
ended to quarty enductoristics (C1 Q3), 0	quittie, 00

First-order autoregressive model, 451	Internal failure costs, 38
First-order integrated moving average mode, 453	Interquartile range 66
First-order mixed model, 453	ISO 9000, 23
First-order moving average model, 453	150 7000, 25
First-order response surface model, 577, 604	J
Fixed effects model ANOVA, 143	Joseph M. Juran, 22
Flow charts, 213	Juran trilogy, 22
· · · · · · · · · · · · · · · · · · ·	
Fraction nonconforming (defective), 289	Just-in-time, 34
Fractional factorial design, 211, 547, 587, 589	T/
F-test in ANOVA, 145	K
	Key process input variable (KPIV), 50
G	Key process output variable (KPOV), 50
g control chart, 318	Kurtosis, 350
Gamma distribution, 89	
Gauge accuracy, 372	L
Gauge capability, 368, also see measurement systems	Latent structure methods, 518
capability	Lean systems, 32
Gauge precision, 372	Least squares estimation of model parameters, 151
Gauge R&R studies, 373, 376	Least squares normal equations, 152
General model for a Shewhart control chart, 185	Leverage from quality costs, 39
Geometric distribution, 81	Limiting quality level (LQL), 640
Goodness-of-fit tests, 95	Linear combinations of random variables, 85, 106
Group control charts, 443	Linear regression models, 150
Guidelines for designing experiments, 554	Linear statistical model, 142
	Linearity of a gauge, 368
Н	Little's law, 34
h control chart, 318	Logistic regression, 223
Headstart, 410	Lognormal distribution, 86
Histogram, 66, 67, 68, 347	Lot disposition, 632
Hotelling T^2 control chart, 499, 501, 502, 506	Lot sentencing, 632
Hypergeometric distribution, 76, 640	Lot tolerance percent defective (LTPD), 640, 663
Hypothesis testing, 112	Lower specification limit, 9
Hypothesis testing about process capability ratios, 362	
Hypothesis testing and control charts, 183	M
Hypothesis testing in regression, 157	Main effect, 556
Hypothesis tests on a single proportion, 122	Malcolm Baldrige National Quality Award, 26
Hypothesis tests on the difference in two means,	Manipulatable process variable, 528
variances known, 128	Markov chain, 444, 464
Hypothesis tests on the difference in two means,	Mean of a distribution, 74
variances unknown, 130, 133	Mean squares, 145
Hypothesis tests on the mean of a single sample,	Mean time to failure, 89
variance known, 113	Measure, 50
Hypothesis tests on the mean of a single sample, variance unknown, 117	Measurement systems capability, 51, 368, 371, 373, 376, 381
Hypothesis tests on the variance of a normal	Median of a distribution, 75
distribution, 120	Median, 65
Hypothesis tests on the variances of two normal distributions, 137	Military standard sampling plans, 655, 676 Minimum variance estimator, 111
Hypothesis tests on two proportions, 139	Mode of a distribution, 75
* *	Model fitting, 151, also see linear regression models
I	Modified control chart, 439
Ideal OC curve, 639	Monitoring multivariate variability, 516
Improve, 53	Moving average control chart, 428
Incoming inspection, 15	Moving center line EWMA control chart, 455
Inertia effect of the EWMA, 423	Moving range control chart, 261
Influence diagnostics in regression, 168	Moving range, 260, 266
Inner array design, 612	Multiple stream processes, 443
Inspection unit, 309	Multiple-sampling, 634, 651
Integral control, 530	Multivariate EWMA (MEWMA) control chart, 509
Integrating SPC and EPC, 540	Multivariate normal distribution, 497
Interaction, 556	Multivariate quality control, 497, 506, 509, 513, 516, 518

	D 11 (DED 250	
N	Precision to tolerance ratio (P/T), 370	
Natural tolerance limits, 237, 346, 388 Negative binomial distribution, 81	Precontrol, 484	
Noise variables, 550, 611	Prediction intervals in regression, 164	
Nonconformities (defects), 308	Predictor variables, 150 Pre-experimental planning, 555	
Nonparametric control charts, 487	PRESS, 166	
Nonparametric statistics, 222	Prevention costs, 36	
Non-value-added operations, 213	Principal components, 518	
Normal approximation to the binomial distribution, 97	Principal fraction, 589	
Normal approximation to the Poisson distribution, 97	Probability distributions, 64, 72	
Normal distribution, 81, 86, 105, 246, 356	Probability limits on control charts, 242	
Normal probability plots of residuals, 149	Probability models for count data, 316	
Normal probability plotting, 93, 264, 349	Probability plots, 93, 95, 349	
Normality and control charts, 246, 263, 424	Process, 13	
Normality and process capability ratios, 356	Process capability analysis, 178, 186, 233, 344, 345,	
np control chart, 300	346, 347, 364, 366, 367	
Null hypothesis, 112	Process capability ratios, 233, 351, 358, 362	
	Process characterization, 552, 602	
O	Process cycle efficiency, 34 Process disturbance, 529	
Off-line quality control, 15 One-half fraction, 587	Process failure mechanism, 464	
One-sample <i>t</i> -test, 117	Process gain, 529	
One-sample Z-test, 113, 122	Process monitoring, 14	
One-sided cusum, 413	Process optimization, 602	
On-line quality control, 15	Process performance indices, 363	
Operating characteristic curve, 125, 246, 306, 322, 637,	Process robustness study, 547	
640, 642, 648, 654, 673	Producer's risk, 113, 379,	
Operation process chart symbols, 214	Product characterization, 346	
Ordered stem-and-leaf display, 65	Product liability, 41	
Orthogonal design, 577	Profile monitoring, 476	
Outer array design, 612	Profiles, 476	
Outgoing inspection, 15	Project charter, 49	
Outliers, 165	Projection of 2^k designs, 578	
Out-of-control action plans, 312	Projection of fractional factorials, 591	
D.	Projects in six-sigma, 48, 49	
P	Proportional control, 427	
<i>p</i> chart, 288 Paired <i>t</i> -test, 136	Proportional integral (PI) control, 539 Proportional integral derivative (PID) control, 540	
Pareto analysis, 39, 312	Pure quadratic curvature, 583	
Pareto chart, 200, 209, 218, 312	P-values, 116	
Partial least squares, 523	1 values, 110	
Pascal distribution, 80	Q	
Passed defectives in gauge R&R studies, 377	Quality, 3, 4, 6, 17, 35, 36, 42	
Patterns on control charts, 195, 231, 243, 244	Quality and variability, 6	
Perceived quality, 5	Quality assurance, 17, 43	
Percentiles, 65	Quality characteristics, 8	
Performance, 4	Quality control and improvement, 17, 43	
Performance of a control chart, 183, 191	Quality costs, 36, 39	
Phase I use of a control chart, 198, 230, 502	Quality engineering, 8	
Phase II use of a control chart, 198, 235, 261, 400, 477,	Quality improvement, 7	
503	Quality is free, 23	
Plan, do, check, act (PDCA), 21	Quality planning, 17, 43	
Point estimate, 110	Quality systems and standards, 23	
Poisson approximation to the binomial distribution, 96	Quartiles, 65, 71	
Poisson distribution, 79, 109, 324, 426	R	
Pooled <i>t</i> -test, 131 Population, 72	R chart, 227, 229, 238, 243	
Potential process capability, 356	Random effects ANOVA, 373	
Power of a test, 113, 126	Random sample, 104, 635	
P_{p} , 363	Random variable, 72	
P_{pk}^{p} , 363	Randomization in designed experiments, 141, 143	
$p\kappa$		

Range estimate of the standard deviation, 112, 227, 229 Signal resistance of a control chart, 423 Rational subgroups, 193, 238, 414, 425 Signal-to-noise ratio, 371, 612 Rectifying inspection, 16, 643, 651 Significance level of a test, 116 Reference distribution for a test statistic, 114 Simulation models, 221 Regression adjustment, 513 Single replicate of a 2^k design, 579 Regression coefficients, 150 Single-sampling plan, 634, 637, 642 Regressor variables, 150 SIPOC diagram, 49 Rejectable quality level (RQL), 640 Six-sigma, 28, 30, 32, 45 Relative efficiency of the range, 112 Skewness, 350 Skip-lot sampling plans, 686 Relative range, 111 Reliability, 5 Span of a moving range, 266 Reliability engineering, 89, 92 Sparsity of effects, 579 Repeatability, 368 Special cause of variation, see assignable cause of Reproducibility, 368 variation Residual analysis, 148, 165, 553 Specification limits, 8, 9, 237 Residual control charts, 445, 456, 513 Specifications, 8, 9, 237 Residuals, 563 Standard deviation of a distribution, 75 Resolution III design, 591 Standard normal distribution, 83 Resolution IV design, 592 Standardization, 83 Resolution V design, 592 Standardized \bar{x} and R charts, 436, 437 Response model, 613 Standardized control chart, 304, 321, 436 Response surface experiment, 553, 603 Standardized cusum, 410 Response surface methods, 547, 602 Standardized residuals, 165 Response surface plot, 577 Stationary process behavior, 188 Response surface, 603 Statistic, 105 Response variable, 150 Statistical hypotheses, 112 Rework, 7 Statistical methods, 8 Robust parameter design (RPD), 611 Statistical process control (SPC), 13, 177 Statistical process monitoring, 540 Robust process, 551 Rotatable design, 610 Statistics, 61, 64 Steepest ascent, 605 Stem-and-leaf display, 64 s chart, 227, 251, 255 Strategic management of quality, 42 s² control chart, 259 Strict liability, 41 Sample, 63, 72, 104 Studentized residuals, 166 Sample autocorrelation function, 448 Supply chain management, 42 Sample average, 69, 110 Switching rules in MIL STD 105E, 656 Sample size and sampling frequency on control charts, 191, 238, 240, 298, 314 Sample size determination in statistical inference, 124, Tabular cusum, 403, 404 126 Target value for a CTQ, 9 Sample standard deviation, 70, 110 *t*-distribution, 106 Sample variance, 69, 110 Test matrix, 564 Sampling distribution, 105 Testing significance of regression, 157 Sampling plans, 631, 646 Tests on individual regression coefficients, 160 Scale cusum, 413 The "magnificent seven", 180, 199 Third quartile, 66 Scan methods, 481 Three-sigma control limits, 184 Scatter diagram, 204 Screening experiment, 552, 602 Tier chart, 236 Second-order autoregressive model, 453 Time between events, 324 Second-order effects, 582 Time series models, 450, 453 Second-order response surface model, 582, 604 Time series, 66 Self-starting cusum, 417 Time series plot, 66 Sequential experimentation, 556, 589, 604 Tolerance diagram, 210, 236 Sequential sampling plan, 634, 652, 681 Tolerance interval control charts, 485 Serviceability, 5 Tolerance limits, 389 Setpoint, 530 Tolerance stack, 383 Shewhart control charts, 177, 180, 185 Tolerances, 553 Shewhart cycle, 21 Tollgates in DMAIC, 46, 49, 51, 53, 54 Tool wear, 482 Shewhart process model, 446 Short production runs, 435, 437 Total quality management (TQM), 23

734 Index

Tracking signals, 456
Transformations of data, 149, 221, 356
Transmission of error formula, 387
Trial control limits, 198, 230, 292
Type A and B OC curves, 640
Type I error. 113
Type II error, 113, 124

U

u chart, 314 Unbiased estimator, 111 Uncontrollable process variables, 550, 611 Upper specification limit, 9

V

Value engineering, 23 Value stream mapping, 213, 219, 220 Variability, 8 Variables control charts, 187 Variables data, 8 Variables sampling plans, 634, 671 Variance components, 374 Variance of a distribution, 75 Variation, 64 V-mask cusum, 403, 415 Voice of the customer, 32

W

W. Edwards Deming, 18 Walter A. Shewhart, 12 Warning limits, 189 Waste and quality, 7 Weibull distribution, 91 Western Electric rules, 196 White noise, 188

X

 \bar{x} control chart, 227, 229, 238, 243, 251, 255, 364

Z

Zero defects, 23 Zone rules, 197

SPC Calculations for Control Limits

Notation:	UCL—Upper Control Limit
-----------	-------------------------

LCL—Lower Control Limit

CL —Center Line

n —Sample Size

PCR—Process Capability Ratio

 $\hat{\sigma}$ —Process Standard Deviation

 \overline{x} —Average of Measurements

 $\overline{\overline{x}}$ —Average of Averages

R —Range

 \bar{R} —Average of Ranges

USL—Upper Specification Limit

LSL—Lower Specification Limit

Variables Data (\overline{x} and R Control Charts)

\overline{x} Control Chart	
$UCL = \overline{\overline{x}} + A_2 \overline{R}$	
$LCL = \overline{\overline{x}} - A_2 \overline{R}$	
$CL = \overline{\overline{x}}$	
R Control Chart	
$UCL = \overline{R} D_4$	

 $LCL = \overline{R} D_3$

 $\mathrm{CL}=\overline{R}$

Capability Study

 $C_p = (\text{USL} - \text{LSL})/(6\,\hat{\boldsymbol{\sigma}}); \text{ where } \hat{\boldsymbol{\sigma}} = \overline{R}/d_2$

n	A_2	D_3	D_4	d_2
2	1.880	0.000	3.267	1.128
3	1.023	0.000	2.574	1.693
4	0.729	0.000	2.282	2.059
5	0.577	0.000	2.114	2.326
6	0.483	0.000	2.004	2.534
7	0.419	0.076	1.924	2.704
8	0.373	0.136	1.864	2.847
9	0.337	0.184	1.816	2.970
10	0.308	0.223	1.777	3.078

Attribute Data (p, np, c, and u Control Charts)

Control Chart Formulas

	p (fraction)	np (number of nonconforming)	c (count of nonconformances)	u (count of nonconformances/unit)
CL	\overline{p}	$n\overline{p}$	\overline{c}	\overline{u}
UCL	$\overline{p} + 3\sqrt{\frac{\overline{p}(1-\overline{p})}{n}}$	$n\overline{p} + 3\sqrt{n\overline{p}(1-\overline{p})}$	$\overline{c} + 3\sqrt{\overline{c}}$	$\overline{u} + 3\sqrt{\frac{\overline{u}}{n}}$
LCL	$\overline{p} - 3\sqrt{\frac{\overline{p}(1-\overline{p})}{n}}$	$n\overline{p} - 3\sqrt{n\overline{p}(1-\overline{p})}$	$\overline{c} - 3\sqrt{\overline{c}}$	$\overline{u} - 3\sqrt{\frac{\overline{u}}{n}}$
Notes	If n varies, use \overline{n} or individual n_i	n must be a constant	n must be a constant	If n varies, use \overline{n} or individual n_i

Guide to Univariate Process Monitoring and Control Is process data autocorrelated? YES NO Is there an adjustment Variables or attributes? variable? Variables Attributes NO YES Fit ARIMA; apply Sample size Data type standard control charts (EWMA, Use feedback control n > 1n = 1Fraction Defects (counts) with an Cusum, x, MR) to either residuals or adjustment original data chart or or Shift size Shift size Shift size Shift size another EPC use moving centerline **EWMA** procedure Large Small or EPC/SPC Large Small Large Small Large Small use a model-free approach Cusum Cusum Cusum x (Individuals) Cusum \overline{x} , R **EWMA** EWMA using \overline{x} , S **EWMA** MR EWMA using pc, u; time between events Define Measure Analyze Improve Control Define Measure Analyze Improve Control Performance Performance Opportunities Performance Opportunity **Objectives Objectives Objectives Objectives Objectives** Identify and/or • Determine what • Analyze data to · Generate and Develop validate the to measure ongoing process understand reasons Quantify for variation and identify potential business Manage potential solutions management measurement improvement Evaluate and plans Mistake-proof select final opportunity data collection root causes Define critical Develop and Determine process solution process validate capability, throughput, Verify and gain Monitor and customer requirements cycle time approval for control critical

The DMAIC Process

final solution

process

plans

. characteristics

Develop out of

control action

· Formulate,

hypotheses.

investigate, and

verify root cause

measurement

• Determine sigma

performance

systems

level

• Document (map)

charter, build

processes Establish project

team




Other Wiley books by Douglas C. Montgomery

Website: www.wiley.com/college/montgomery



Engineering Statistics, Fourth Edition

by D.C. Montgomery, G.C. Runger, and N.F. Hubele





Applied Statistics and Probability for Engineers, Fourth Edition

by D.C. Montgomery and G.C. Runger

Introduction to engineering statistics, with topical coverage appropriate for either a one- or twosemester course. An applied approach to solving real-world engineering problems.



Probability and Statistics in Engineering, Fourth Edition

by W.W. Hines, D.C. Montgomery, D.M. Goldsman, and C.M. Borror

Website: www.wiley.com/college/hines

For a first two-semester course in applied probability and statistics for undergraduate students, or a one-semester refresher for graduate students, covering probability from the start.



Design and Analysis of Experiments, Sixth Edition

by Douglas C. Montgomery

An introduction to the design and analysis of experiments, with the modest prerequisite of a first course in statistical methods.



Introduction to Linear Regression Analysis, Fourth Edition

by D.C. Montgomery, E.A. Peck, and G.G. Vining

A comprehensive and thoroughly up-to-date look at regression analysis, still the most widely used technique in statistics today.



Response Surface Methodology: Process and Product Optimization Using Designed **Experiments, Second Edition**

by R.H. Myers and D.C. Montgomery

Website: www.wiley.com/college/myers

The exploration and optimization of response surfaces, for graduate courses in experimental design, and for applied statisticians, engineers, and chemical and physical scientists.



Generalized Linear Models: With Applications in Engineering and the Sciences

by R.H. Myers, D.C. Montgomery, and G.G. Vining

Website: www.wiley.com/college/myers

An introductory text or reference on Generalized Linear Models (GLMs). The range of theoretical topics and applications appeals both to students and practicing professionals.




Introduction to Time Series Analysis and Forecasting


by Douglas C. Montgomery, Cheryl L. Jennings, Murat Kulahci

Methods for modeling and analyzing time series data, to draw inferences about the data and generate forecasts useful to the decision maker. Minitab and SAS are used to illustrate how the methods are implemented in practice. For advanced undergrad/first-year graduate, with a prerequisite of basic statistical methods. Portions of the book require calculus and matrix algebra.


Quality Improvement Tools




- Expresses detailed knowledge of the process
- Identifies process flow and interaction among the process steps
- Identifies potential control points




- All contributing factors and their relationships are displayed
- Identifies problem areas where data can be collected and analyzed




- · Helps reduce variability
- Monitors performance over time
- Allows process corrections to prevent rejections
- Trends and out-of-control conditions are immediately detected



- · Simplifies data collection and analysis
- Spots problem areas by frequency of location, type, or cause



- Identifies most significant problems to be worked first
- Historically 80% of the problems are due to 20% of the factors
- · Shows the vital few




- Identifies the relationship between two variables
- A positive, negative, or no relationship can be easily detected

Design of Experiments (DOX)

- Useful in process development and troubleshooting
- Identifies magnitude and direction of important process variable effects
- Greatly reduces the number of runs required with a process experiment
- Identifies interaction among process variables
- Useful in engineering design and development
- Focuses on optimizing system performance

Histogram



- The shape shows the nature of the distribution of the data
- The central tendency (average) and variability are easily seen
- Specification limits can be used to display the capability of the process