

Thatcham Research

ADAS Fitment, location and calibration information

Neil O'Reilly (Collision Engineers)

22/06/2026 10:29 BST

VRM: FG25VOH

Toyota Aygo X 2022- 5 Door Hatchback Edge VVT-i
Petrol 1.0 71bhp Manual 2022

This information is supplied by Thatcham Research ("Thatcham") for use by trained professionals in the motor repair and insurance industries. It is not intended for use by the general public.

You must rely upon your own expertise to ensure that any information, process, procedure or specification used is appropriate for your needs and is followed correctly.

Thatcham shall not be liable for any loss or damage incurred as a result of using this information (including as a result of negligence) save for in respect of death or personal injury or any other losses which cannot be excluded or limited by law.

This information is supplied by Thatcham Research ("Thatcham") under licence from the copyright owner. Copying, reproducing, transmitting, modifying, adapting, all or any part of this information without the written consent of the copyrightowner is prohibited. Committing any unauthorised act may result in civil or criminal actions being taken by, or on behalf of, the copyright owner.

ADAS systems displayed in bold text are fitted as standard. Those displayed in unbold text are optional fitment systems. Click on the table headers to sort by location or component.

1 = Initialisation is required 2 = No calibration required 3 = Calibration is required

Sensor Type	Location	Scenarios	ADAS Systems
Camera	Centre of Bumper Rear	1. No calibration required 2	Reversing Camera Rear Camera(s)
Camera	Centre of Screen Front	1. The camera is removed and refitted or renewed 3 2. The camera screen front component bracket / clip is deformed, damaged or renewed 3 3. The screen is removed and refitted or renewed 3	Lane Departure Alert with Switches on Steering Wheel Lane Departure Warning (LDW) Pre-Collision System with Emergency Steering Assist Autonomous Emergency Braking - Car to Car Emergency Steering Support (ESS) Toyota Safety Sense Forward Collision Warning - Pedestrian Adaptive Cruise Control Speed Limit Recognition Lane Departure Warning (LDW) Lane Keep Assist (LKA) Driver Condition Monitor
Radar	Behind Centre of Bumper Front	1. Repair work is carried out in the area of the sensor 3 2. The radar is renewed 3 3. The sensor or the surrounding components are damaged 3 4. The sensor or the surrounding components	Adaptive Cruise Control Switch on Steering Wheel Adaptive Cruise Control Lane Departure Alert with Switches on Steering Wheel Lane Departure Warning (LDW) Pre-Collision System with Emergency Steering Assist Autonomous Emergency Braking - Car to Car Emergency Steering Support (ESS) Toyota Safety Sense Forward Collision Warning - Pedestrian Adaptive Cruise Control Speed Limit Recognition Lane Departure Warning (LDW)

Sensor Type	Location	Scenarios	ADAS Systems
		are moved 3	Lane Keep Assist (LKA) Driver Condition Monitor
Ultrasonic (4)	Situated in Bumper Front	1. The bumper is renewed 1 2. The ultrasonic sensor is removed and refitted 1 3. The ultrasonic sensor is renewed 1	- Parking Pack - Rear Park distance control (PDC) - Front Park distance control (PDC)
Ultrasonic (4)	Situated in Bumper Rear	1. The bumper is renewed 1 2. The ultrasonic sensor is removed and refitted 1 3. The ultrasonic sensor is renewed 1	- Parking Pack - Rear Park distance control (PDC) - Front Park distance control (PDC)

The above represents the ADAS Thatcham Research has identified in its studies and is applicable for all models in the range at the point of research. Please consider the reinstatement requirements of the above systems and related components when repairing this vehicle.

Thatcham details

Thatcham Research
Colthrop Way
Thatcham
Berks RG19 4NR, UK

Company Information

Company Number: 967763

Copyright © Thatcham Research 2026