

Atkinsons Body Repair
Windmill House Industrial Estate
SUTTON ROAD
Wigginton
York
YO32 2RA


Date: 20/01/2026
Our Ref: 00029038/DME
Your Ref: EHR95052

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Atkinsons Body Repair**

We refer to your instructions received on **20 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VOLKSWAGEN AMAROK HIGHLINE V6		Colour: SILVER	Speedo: 93774	Miles	
Reg No: P70LSP	Registered: Mar 2017	Type: Pickup	Trans: Automatic		
Vin No: WV1ZZZ2HZHH013179	MOT Exp:	R/H/F Tyre	R/H/R Tyre		
Mods:	Cond:	R/H/F Belt	R/H/R Tyre2		
Audio:	Manfd: 2017				
Brakes: Satisfactory	Tax Exp:				Spare Tyre
Steering: Satisfactory	Fuel: Diesel				Centre Belt
Extras:	C.C.: 2967				
Air Bags Deployed:	BHP: 221.	L/H/F Belt	L/H/R Tyre2		
Damage: Light Collision/Impact RH Rear Rear to Front	Incident: 08/01/2026	L/H/F Tyre	L/H/R Tyre		
Vehicle Value: £16,585.00		Repair Cost: £4,197.20 inc VAT	(25.31% of PAV) Roadworthy: Yes		

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered light collision impact to the right hand rear rear to front.

ENGINEER'S COMMENTS

I have examined the vehicle and found damage as listed in this report.

I can confirm repair costs have been agreed with the repairer on best terms possible.

I can confirm repairs have been authorised in accordance with your original instructions.

20/01/2026 -

VEHICLE HISTORY CHECK

20/01/2026 - According to the Experian database; there is a plate change on record



REPAIR SCHEDULE

New parts required:-Rear Bumper Cover, Rear Bumper Support, Rr Bumper Clamp Kit, R/R Inn Parking Sens, Filler, Sundry Parts

Repairable parts:-R/Side Panel Cpl

Repaint only parts:-R/Side Panel Cpl Repair Painting <50%, De Nib, Preparation For Pre-Painting

Specialist/Sundry charges:-Tech Data +, Post_Rep_Diag_Chec Specialist, Pre_Rep_Diag_Check Specialist, Das-Methods, Corrosion Protection Materials External

Remove And Refit parts:-Rear Bumper Cover, Renew Rear Bumper Cover, Rear Crossmember, Right Taillamp, R/R Wheelhouse Cover, L/Loading Sill Cover, Ball Head, Corrosion Prote To 1St Panel

Parts to check:-Wash&Vaccuum, Roadtest-Qc, Iir-Adas

COST OF REPAIRS

An Audatex estimate has been obtained from Vda Ltd in the sum of £982.70 labour plus parts at manufacturer's list prices plus £450.31 for paint and materials plus £258.00 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be reasonable. The labour charge is based on 11.8 hours at a rate of £83.28 per hour. I have also agreed that the cost of paint and materials will be limited to £450.31. The cost of the necessary replacement parts will be approximately £1,806.66, the specialist/sundry charges will be £258.00, giving a total repair cost of £3,497.67 plus VAT **subject to any undisclosed damage** and as your Insured is eligible to recover the VAT there will be no tax liability for your good selves on this repair.

PRE-INCIDENT CONDITION

The vehicle is considered to be in condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 23/03/2017.

The corresponding Glass's Guide (model code: L989) retail value for vehicles of this type and age in the January 2026 guide is £16,585.00 at 93774 Miles, trade value is £13,540.00.

I place the pre-accident value of this particular vehicle at £16,585.00 bearing in mind the condition described herein. As this is a commercial vehicle these values are excluding VAT.

OWNER'S CONTRIBUTION

I do not consider that any betterment contribution is required on this occasion.

RESERVE

Although the total cost of this repair will be approximately £3,497.67 plus VAT I consider that a repair reserve of £3,500.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

Repairs authorised as per instructions.

REPAIR DURATION

I consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

I hope that the foregoing is of assistance and please do not hesitate to contact me should you require anything further in this matter.

For & on behalf of

Exclusive Vehicle Assessors