

Our Ref: qdos221401

Your Ref: JW//14218/1

Date: 24/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL


CONTRACT REPAIR REPORT

Dear Sirs


RE: Road traffic Accident: Dr Sarah Daley: 20/07/2022

In accordance with your instructions received on 24/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 24/08/2022. Vehicle located at Image based assessment. Our findings are as detailed below:


Make	VOLKSWAGEN	Registration	GD08ARZ
Model	EOS SPORT T FSI	Status	Repair
Category		Salvage Value	
Repair Cost	£2,858.89	Legal Status	Roadworthy
Engineer Value	£3,650.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: qdos221401
Your Ref: JW//14218/1

Date: 24/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand front.

ENGINEER'S COMMENTS

Mileage calculated from MOT history

24/08/2022 - Vehicle is unroadworthy due to the damaged/insecure front bumper.

Repairs agreed on a contract basis and costs must not increase.

VEHICLE HISTORY CHECK

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

CONTRACT REPAIR

To ensure no further repair costs are found we have agreed a contract repair figure with the repairers in the sum total of £2,858.89 which is inclusive of VAT but subject to the deduction of any applicable excess.

RESERVE

We consider that a repair reserve of £2,875.00 would be reasonable on this occasion.


Vehicle Data

Retail Value	£3,650.00
Trade Value	£2,220.00
Engineer's Value	£3,650.00
Glass's Code	7LJ9
VIN	WVWZZZ1FZ9V002955
Odometer	79500
Engine	1984
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Front Bumper
Front Bumper Beam

Os Headlamp
Sundries/clips/fixings



Our Ref: qdos221401

Your Ref: JW//14218/1

Date: 24/08/2022

Repairs required

Os Wing

Additional operations

epa Charges

Covid Clean

System Diagnostic Check (Pre Repair)

Energy Surcharge

car Care Kit

system Diagnostic Check (Post Repair)

methods Research

colour Blends

Repair Cost Calculations

Hours	15.12
Hourly Rate	£62.50
Total Labour	£945.00
Parts	£812.76
Paint/Materials	£371.65
Specialist/Other	£253.00
Sub total	£2,382.41
Vat	£476.48
Total Estimated Cost	£2,858.89