

Our Ref: qdos22960

Your Ref: AL/MR/13185/1

Date: 15/06/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Ian Lloyd: 10/06/2022


In accordance with your instructions received on 13/06/2022 requesting us to provide an independent accident damage report, we assessed the damage on 15/06/2022. Vehicle located at Image based assessment. Our findings are as detailed below:

Make	JAGUAR	Registration	OE67MYF
Model	XE S V6 AUTO	Status	Repair
Category		Salvage Value	
Repair Cost	£4,698.46	Legal Status	Roadworthy
Engineer Value	£24,240.00	Impact Magnitude	Moderate



Impact Area





Our Ref: qdos22960

Your Ref: AL/MR/13185/1

Date: 15/06/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand front.

ENGINEER'S COMMENTS

25/08/2022 - UPDATED REPORT - The repairer has been in contact as the front bumper has been able to be repaired instead of being replaced. Parts prices have been confirmed (mainly the R headlamp) and costs have been agreed. The vehicle remains economically repairable.

VEHICLE HISTORY CHECK

15/06/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £4,975.00 would be reasonable on this occasion.


Vehicle Data

Retail Value	£24,240.00
Trade Value	£22,020.00
Engineer's Value	£24,240.00
Glass's Code	
VIN	SAJAB4AV3JCP35783
Odometer	34252
Engine	2995
Fuel	Petrol
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

R/F Bumper Grille
L/F Bumper Bracket
L/F Upp Bumper Brkt
Right Headlamp Assy
R/F Out U-Sonic Sens
Sundry Parts

R/Lwr Trim Insert
R/F Bumper Bracket
R/F Upp Bumper Brkt
R/F Wing Sticker
Bumpers Prep > 15%



Our Ref: qdos22960

Your Ref: AL/MR/13185/1

Date: 15/06/2022

Repairs required

Front Bumper

Additional operations

Check Frt Bumper Support
Check And Road Test
Paint Front Bumper Repair Paint Plastic
Paint R/F Wing Repair Painting <50%
Blend L/Headlamp Wash Trimsurface Paint Plast.
Paint Bumper Prep > 15% Additional Lab
Paint Preparation For Pre-Painting
E.P.A. Charge
Data Research

Check Final Inspection
Paint R/F Out U-Sonic Sensnew Part Paint K1r
Paint Bonnet Repair Painting <50%
Blend Frt Towing Eye Coversurface Paint Plast.
Blend R/Headlamp Wash Trimsurface Paint Plast.
Paint De Nib
Car Care Kit
Pre/Post Sweep
Corrosion Protection Materials External

Repair Cost Calculations

Hours	19.60
Hourly Rate	£65.00
Total Labour	£1,274.00
Parts	£1,685.04
Paint/Materials	£843.84
Specialist/Other	£112.50
Sub total	£3,915.38
Vat	£783.08
Total Estimated Cost	£4,698.46




PDFImage003(1).jpg



PDFImage004(1).jpg



PDFImage005(1).jpg



PDFImage006(1).jpg




**COLLISION
ENGINEERS**

INDEPENDENT AUTOMOTIVE EXPERTS


Our Ref: qdos22960

Your Ref: AL/MR/13185/1

Date: 15/06/2022



PDFImage007(1).jpg



PDFImage008(1).jpg



PDFImage009(1).jpg



PDFImage010(1).jpg



PDFImage011(1).jpg



PDFImage012(1).jpg



PDFImage013.jpg



PDFImage014.jpg




PDFImage015.jpg




PDFImage016.jpg



PDFImage017.jpg



PDFImage018.jpg




PDFImage019.jpg




PDFImage020.jpg




PDFImage021.jpg




PDFImage022.jpg




PDFImage023.jpg



PDFImage024.jpg



PDFImage025.jpg




PDFImage026.jpg



PDFImage027.jpg

- 11.SASM (Steering Angle Sensor Module)
- 12.TPM (Tire Pressure Monitor Module)
- 13.VIM (Vehicle Immobilizer Control Module)
- 14.FCIM (Front Controls Interface Module)
- 15.GSM (Gear Shift Module)
- 16.HVAC (HVAC Control Module)
- 17.IPC (Instrument Panel Cluster Control Module)
- 18.RCM (Restraints Control Module)
- 19.RFA (Remote Function Actuator)
- 20.RGTM (Rear Gate / Trunk Module)
- 21.IPMA (Image Processing Module 'A')
- 22.IPMB (Image Processing Module 'B')
- 23.TCU (Telematic Control Unit Module)
- 24.ECM (Engine Control Module)
- 25.TCM (Transmission Control Module)
- 26.PAM (Parking Assist Control Module)

PDFImage028.jpg



Our Ref: qdos22960

Your Ref: AL/MR/13185/1

Date: 15/06/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos22960

Your Ref: AL/MR/13185/1

Date: 15/06/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

OE67MYF.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos22960.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10