

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr S Warman
Station Road
Ringstead
Kettering
Northamptonshire
NN14 4TU

Date: 11/02/2026
Our Ref: 00076938/PK
Your Ref: EHR96401

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr S Warman**

We refer to your instructions received on **09 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VAUXHALL ASTRA SRI VX-LINE NAV	Colour: WHITE	Speedo: 64849	Miles
Reg No: KY67NVK	Registered: Sep 2017	Type: 5 Door Hatchback	Trans: Manual
Vin No: W0LBF6EC1HG093836	MOT Exp:	R/H/F Tyre 5	R/H/R Tyre 5
Mods:	Cond: Good	R/H/F Belt	R/H/R Belt
Audio:	Manf'd: 2017	Spare Tyre	
Brakes: Not testable	Tax Exp:		
Steering: Not testable	Fuel: Petrol	Centre Belt	
Extras:	C.C.: 1399		
Air Bags Deployed:	BHP: 148	L/H/F Belt	L/H/R Belt
Damage: Light Accidental Damage Rear Bumper	Incident: 04/02/2026	L/H/F Tyre 5	L/H/R Tyre 5
Vehicle Value: £6,453.00		Repair Cost: £3,000.16 inc VAT (46.49% of PAV)	
		Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

VEHICLE HISTORY CHECK

09/02/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rear Bumper Spoiler, Number Plate

Repairable parts:-Repair Method

Repaint only parts:-Rear Bumper New Part Paint K1r, Polish De Nib, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Vehicle Care Kit, Bs10125, Pre Scan, Post Scan, Energy Charge, Sundry Part, Epa, Repair Method, Energy charge

Remove And Refit parts:-Rear Bumper, Renew Rear Bumper (Removed), Disassemble Rear Bumper, Road Test QC, Vacuum Wash, Clean Charge Pre Estimate, Vehicle Shut Down

COST OF REPAIRS

The repairers, Milton Keynes Motor Company, MK2 3JU (Tel. 01933 229 062), have compiled an estimate in the sum of £1,016.02 plus parts at manufacturer's list prices plus £1,261.42 for paint and materials plus £364.61 for

specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £358.11 to £657.91 for the labour and £427.05 to £834.37 for paint and materials in their final account. The labour charge is based on 7.9 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £834.37. The cost of the necessary replacement parts will be approximately £703.24, the specialist/sundry charges will be £304.61, the VAT liability on this repair will amount to some £500.03 giving a total repair cost of £3,000.16 including VAT **subject to any undisclosed damage.** **We are pleased to confirm that we have achieved total gross savings in this matter of £1,014.19.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 01/09/2017. The corresponding Glass's Guide (model code: 239364001) adjusted retail value for vehicles of this type and age in the February 2026 guide is £6,453.00 at 64849 Miles, trade value is £4,068.00 and mid value is £5,260.50. We place the pre-accident value of this particular vehicle at £6,453.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £3,025.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 11th February 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Kendrick AQP AMIMI
Connexus Vehicle Assessors