

Consec Risk Management Ltd
Unit E10A, Knoll Business Centre
325-327
BN
Hove
East Sussex
BN3 7GS

Date: 15/05/2026
Our Ref: 00035049/JEFFP
Your Ref: EHR100570

To the Court

REPAIRABLE REPORT - Supplementary Report

Dear Sirs,

Client: **Consec Risk Management Ltd**

We refer to your instructions received on **24 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	SEAT ATECA XPERIENCE ECOTSI		Colour:	GREY	Speedo:	47784	Miles
Reg No:	GV72OUB	Registered:	Jan 2023	Type:	5 Door Hatchback	Trans:	Manual
Vin No:	VSSZZZ5F2P6525758		MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre Not Kno
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested
Audio:	Not Seen	Manfd:	2023			Spare Tyre	
Brakes:	Not Known	Tax Exp:				Not Known	
Steering:	Not Known	Fuel:	Petrol			Centre Belt	
Extras:	Not Seen	C.C.:	1498	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested
Air Bags Deployed:	Not Known	BHP:	147.	L/H/F Tyre	Not Kno	L/H/R Tyre	Not Kno
Damage:	Collision/Impact		Incident:	21/04/2026			
Vehicle Value: £15,506.00		Repair Cost: £5,726.26 inc VAT		(36.93% of PAV)		Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the rear bumper, and moderate collision/impact to the rear boot.

ENGINEER'S COMMENTS

15/05/2026 - Supplementary Repairs Bigger, T/Gate paint more than 50%, part prices Amended, Decal Cost added and Decal Fitting Cost Added.

VEHICLE HISTORY CHECK

29/04/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rr Towing Eye Cover, Rr Lwr Bump Moulding, Bump Retaining Rail, Badge Model, Sundry



Parts

Repairable parts:-Rear Bumper, Rr Bump Lwr Spoiler, Lower Tailgate, Panel System

Repaint only parts:-Rear Bumper Repair Paint Plastic, Rr Bump Lwr Spoiler Repair Paint Plastic, Lower Tailgate Repair Painting >50%, Machine Polish, Preparation For Pre-Painting

Specialist/Sundry charges:-Corrosion Protection, Bsi Charge, Aries Charge, Panel Sundries, Livery / Decals, Adas Methods, Fit Livery Decals, Texture Materials, Tech Data + Methods, E.P.A. Charge, Car Care Kit

Remove And Refit parts:-Description, Gfs / Guided Function, Both Inner Taillamps, Renew Model Badge, Rear Lock Control, Lower Tailgate Trim, Both Outer Taillamps, Both Rear Reflectors, Rear Centre Bumper Bracket, Rear Lower Bumper Cover, Rear Number Plate, Number Plate Lamps, Rear Bumper Spoiler, Rear Lower Bumper Moulding, Backup Camera, Rear Ultrasonic Sensor, Adjust Backup Camera, Strip Livery / Decal, Road Test And Quality Control, Corrosion Prote To 1St Panel

Parts to check:-Rear Bumper C-Member, Wash & Vac, Veh Diag Post, Veh Diag Pre, Adas Exploration

COST OF REPAIRS

The repairers, Accident Repair Hub - Brighton (Tel. 01273 037570), have compiled an estimate in the sum of £2,863.52 plus parts at manufacturer's list prices plus £819.20 for paint and materials plus £635.47 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 29.9 hours at a rate of £95.77 per hour. We have also agreed that the cost of paint and materials will be limited to £819.20. The cost of the necessary replacement parts will be approximately £453.69, the specialist/sundry charges will be £635.47, giving a total repair cost of £4,771.88 plus VAT **subject to any undisclosed damage** and as the owner is eligible to recover the VAT there will be no tax liability for your good selves on this repair.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 25/01/2023. The corresponding Cazana Guide (model code: 9701263) adjusted retail value for vehicles of this type and age in the April 2026 guide is £15,506.00 at 47784 Miles, trade value is £14,110.00 and mid value is £14,808.00. We place the pre-accident value of this particular vehicle at £15,506.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

Although the total cost of this repair will be approximately £4,771.88 plus VAT we consider that a repair reserve of £4,775.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 29th April 2026, on your behalf the owner being responsible for the VAT.

REPAIR DURATION

We consider that this repair will take some 7 to 8 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to Damage caused rendered the vehicle unroadworthy.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

A handwritten signature in dark ink, appearing to read "JP", followed by a period.

Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors