

Mrs Claire Suggitt
1 The Meadows
Beverley Parklands
Beverle
HU
Beverley Parklands
HU17 0RJ

Date: 30/03/2026
Our Ref: 00032952/JEFPF
Your Ref: EHR98687 \ 807318263

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mrs Claire Suggitt**

We refer to your instructions received on **24 March 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: BMW X2 SDRIVE20I M SPORT AUTO		Colour: WHITE	Speedo: 26963 Miles	
Reg No: ND19GDX	Registered: Mar 2019	Type: 5 Door Hatchback	Trans: Automatic	
Vin No: WBAYH32040EH38672	MOT Exp: 	R/H/F Tyre 5	R/H/R Tyre 3	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2019			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Known
Steering: Not Known	Fuel: Petrol			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1998			
Air Bags Deployed: Not Known	BHP: 189.3	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Collision/Impact LH Front Door	Incident: 20/03/2026	L/H/F Tyre 5	L/H/R Tyre 4	
Vehicle Value: £18,636.00		Repair Cost: £2,777.92 inc VAT (14.91% of PAV)	Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand front door.

ENGINEER'S COMMENTS

30/03/2026 - Instruction sheet O/S/F Door, damage is actually N/S/F Door.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Left Front Door, L/F Door Moulding, L/F Door Insulation, Sound Pad X1, Sundry Parts

Repaint only parts:-Basecoat Clear, Left Front Door New Part Painting, L/F Door Moulding New Part Paint K1r, Preparation For Pre-Painting



Specialist/Sundry charges:-Bsi10125, Methods Research Specialist, E.P.A. Charge, Environmental, Car Care Kit, Corrosion Protection Materials External
Remove And Refit parts:-Description, Add/Time For Main Work, Left Front Door, Adjust L/F Door, Renew L/F Door (Removed), Preparation Time For Cavity Protection, Inject Protective Wax To Lh Front Door, Corrosion Protection Repair Clean, Road Test And Quality Control
Parts to check:-Veh Diag Post, Veh Diag Pre, And Clean Car

COST OF REPAIRS

The repairers, Steer Prestige Hull (Tel. +44 1482 210060), have compiled an estimate in the sum of £795.73 plus parts at manufacturer's list prices plus £584.58 for paint and materials plus £137.00 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 12.43 hours at a rate of £64.00 per hour. We have also agreed that the cost of paint and materials will be limited to £584.58. The cost of the necessary replacement parts will be approximately £797.62, the specialist/sundry charges will be £137.00, the VAT liability on this repair will amount to some £462.99 giving a total repair cost of £2,777.92 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 01/03/2019. The corresponding Percayso Guide (model code: 2380112) adjusted retail value for vehicles of this type and age in the March 2026 guide is £18,636.00 at 26963 Miles, trade value is £16,213.00 and mid value is £17,424.50. We place the pre-accident value of this particular vehicle at £18,636.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,800.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 30th March 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors