

**Our Ref:** qdos221409

**Your Ref:** CJH/14260/1

**Date:** 24/08/2022

FAO The Court  
C/o QDOS Assistance  
1st Floor, Barfield House  
24-28 Alderly Road  
SK91PL

### **REPAIRABLE REPORT**

Dear Sirs



**RE: Road traffic Accident: Stewart Blackburn: 12/08/2022**

In accordance with your instructions received on 24/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 24/08/2022. Vehicle located at Image Based Assessment. Our findings are as detailed below:


|                |                           |                  |                          |
|----------------|---------------------------|------------------|--------------------------|
| Make           | <b>FORD</b>               | Registration     | <b>EU63OZA</b>           |
| Model          | <b>S-MAX TITANIUM TDC</b> | Status           | <b>Repair</b>            |
| Category       |                           | Salvage Value    |                          |
| Repair Cost    | <b>£2,929.51</b>          | Legal Status     | <b>Unroadworthy</b>      |
| Engineer Value | <b>£7,700.00</b>          | Impact Magnitude | <b>Light to Moderate</b> |



Impact Area



Document produced  
using the EVA system



**Our Ref:** qdos221409

**Your Ref:** CJH/14260/1

**Date:** 24/08/2022

### **DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

### **NATURE OF INCIDENT**

The vehicle has suffered light to moderate collision/impact damage to the left hand side.

### **ENGINEER'S COMMENTS**

24/08/2022 - Please note the vehicle is unroadworthy due to the broken/insecure mirror.

### **VEHICLE HISTORY CHECK**

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **RESERVE**

We consider that a repair reserve of £2,950.00 would be reasonable on this occasion.


## **Vehicle Data**

|                  |                          |
|------------------|--------------------------|
| Retail Value     | <b>£7,700.00</b>         |
| Trade Value      | <b>£5,260.00</b>         |
| Engineer's Value | <b>£7,700.00</b>         |
| Glass's Code     | <b>N3LQ</b>              |
| VIN              | <b>WF0SXXGBWSDA55308</b> |
| Odometer         | <b>91025</b>             |
| Engine           | <b>1997</b>              |
| Fuel             | <b>Diesel</b>            |
| Extras           |                          |
| Condition        | <b>Good</b>              |
| Unrelated Damage |                          |

### **Main new parts required**

Side Window Rep Kit  
L/F Out Window Mldg  
L/Fastening Clip  
L/D/Mirror Indicator  
L/Door Mirror  
L/Door Mirror Hsg  
Spacer  
Spacer  
Sundry Parts

L/F Door Window  
L/F Door Moulding  
L/F Protective Foil  
L/Sill Lamp  
L/Door Mirror Glass  
L/F S/Wdw Mntg Kit  
Adhesive Tape  
Spacer



**Our Ref:** qdos221409

**Your Ref:** CJH/14260/1

**Date:** 24/08/2022

Repairs required

L/F Door Lower Sect

Additional operations

Check Final Qc & Road Test  
Paint L/Door Mirror Hsg New Part Paint K1r  
Blend L/F Wing Surface Paint  
Blend L/Wing Grille Surface Paint Plast.  
Paint Preparation For Pre-Painting  
Bsi10125 Charge  
Diagnostic Sweep  
E.P.A. Charge  
Workshop Materialspanel Sundries

Paint L/F Door Moulding New Part Paint K1r  
Paint L/F Door Lower Sect Repair Painting <50%  
Blend L/Wing Moulding Surface Paint Plast.  
Paint De-Nib And Polish 2 Panels  
Sanatising Damage Vehicle  
Diagnostic Sweep  
Car Care Kit  
Methods Research Specialist  
Corrosion Protection Materials External

### Repair Cost Calculations

|                      |                  |
|----------------------|------------------|
| Hours                | <b>13.90</b>     |
| Hourly Rate          | <b>£74.70</b>    |
| Total Labour         | <b>£1,038.33</b> |
| Parts                | <b>£746.28</b>   |
| Paint/Materials      | <b>£400.41</b>   |
| Specialist/Other     | <b>£256.24</b>   |
| Sub total            | <b>£2,441.26</b> |
| Vat                  | <b>£488.25</b>   |
| Total Estimated Cost | <b>£2,929.51</b> |



PDFImage004.jpg



PDFImage005.jpg



PDFImage006.jpg



PDFImage007.jpg

## Panel Sundries

Solution: Audaenterprisegold | Updated: 1 month ago


Panel sundries / consumables are not provided by the vehicle manufacturer nor included within the Audatex calculation. If panel related sundries / consumables are required to complete the repair or panel replacement, these should be entered into Zone 99.

Please consult with your work provider guidelines on how these are to be managed.

PDFImage008.jpg


Print

Page 1 of 2

| Glass, Frames and Mechanisms - Front Door Window Glass                                                                                                      | S-MAX/Galaxy 2006.5 (02/2006-) |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| <b>Removal and Installation</b>                                                                                                                             |                                |
| <b>Removal</b>                                                                                                                                              |                                |
| NOTE: Removal steps in this procedure may contain installation details.                                                                                     |                                |
| 1. Remove the front door trim panel.<br>Refer to: <a href="#">Front Door Trim Panel</a> (501-05 Interior Trim and Ornamentation, Removal and Installation). |                                |
| 2.<br>                                                                   |                                |
| 3. Torque: <b>7 Nm</b><br>                                               |                                |
| 4.<br>                                                                   |                                |
| 5.<br>1.<br>2. Remove the front door window glass towards the outside of the window opening.                                                                |                                |


PDFImage010.jpg

**Date:** 24/08/2022




PDFImage011.jpg


Page 2 of 2




PDFImage012.jpg



PDFImage013.jpg



PDFImage014.jpg



**Our Ref:** qdos221409

**Your Ref:** CJH/14260/1

**Date:** 24/08/2022

### Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA  
engineers@collisionengineers.co.uk



**Our Ref:** qdos221409

**Your Ref:** CJH/14260/1

**Date:** 24/08/2022

FAO The Court  
C/o QDOS Assistance  
1st Floor, Barfield House  
24-28 Alderly Road  
SK91PL

### Fee Note

EU63OZA.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

**Agreed Fee: £100.00**

**Sub Total: £100.00**

**VAT: £20.00**

**Total Due: £120.00**

### Payment

Please make cheques payable to Collision Engineers and quote reference qdos221409.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10