

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Gary Dixon

Date: 30/12/2025

Our Ref: 00075939/PK

Your Ref: 568656

Engineer Repairable Report

Dear Sirs,

Client/Insured:

T/Party: **Gary Dixon**

We refer to your instructions received on **23 December 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: HYUNDAI TUCSON N LINE S T-GDI HEV	Colour: BLACK	Speedo: 2000	Miles	
Reg No: YP25WDM	Registered: Apr 2025	Type: 5 Door Estate	Trans: Automatic	
Vin No: TMAJB8117SJ359240	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2025			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Know
Steering: Not Known	Fuel: Hybrid			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1598	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 212	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light to Moderate Accidental Damage Rear Bumper	Incident: 12/12/2025			
Vehicle Value: £32,218.00		Repair Cost: £3,864.13 exc VAT	(11.99% of PAV) Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate accidental damage to the rear bumper, and to the boot.

VEHICLE HISTORY CHECK

23/12/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rr Bumper Protection, L/R Bumper Moulding, R/R Bumper Moulding, Rear Bumper Moulding, Bootlid/Tailgate, Rear Screen Trim, Badge Limited, Engine Badge, Manufacturer Badge, Badge Model, Badge "Hybrid", Rear Screen Bond Kit, Inn Rr Scr Underlay

Repairable parts:-Repair Rear Bumper Cover

Repaint only parts:-Boot lid/Tailgate New Part Painting, Rear Bumper Repair Paint Plastic, L/R Side Bumper Surface Paint Plast., R/R Side Bumper Surface Paint Plast., L/R Out Parking Sens surface Paint Plast., Boot/T-Gate Moulding surface Paint Plast., Lwr T-Gate Moulding Surface Paint Plast., Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Bsi Compliance charge, Epa Charge, Pre Repair Check, Post Repair Check, Car Care Kit, Methods Research, First Calibration, Methods Research, Aries Support, Sundry Part

Remove And Refit parts:-Rear Bumper, Rear Bumper Protector, R+R Both Rr Bump Trm, Both Fog Lamps, Renew

Tailgate, Rear Bumper Carrier, Add/Work For Sealing Tailgate, Tailgate Adjuster: Additional Work, Road Test And Final Quality Check

Parts to check:-Check Rear Bumper Cover

COST OF REPAIRS

The repairers, The Repair Group Nw Ltd, Unit 4 Wensley Business Park, Blackburn, BB2 1WD (Tel. 03301131907), have compiled an estimate in the sum of £1,416.00 plus parts at manufacturer's list prices plus £980.49 for paint and materials plus £654.94 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £88.00 to £1,328.00 in their final account. The labour charge is based on 16.6 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £980.49. The cost of the necessary replacement parts will be approximately £1,204.70, the specialist/sundry charges will be £350.94, giving a total repair cost of £3,864.13 plus VAT **subject to any undisclosed damage** and as the Third Party is eligible to recover the VAT there will be no tax liability for your good selves on this repair. **We are pleased to confirm that we have achieved total gross savings in this matter of £470.40.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 01/04/2025. The corresponding Glass's Guide retail value for vehicles of this type and age in the December 2025 guide is £32,218.00 at 2480 Miles, trade value is £28,974.00 and mid value is £30,596.00. We place the pre-accident value of this particular vehicle at £32,218.00 bearing in mind the condition described herein.

RESERVE

Although the total cost of this repair will be approximately £3,864.13 plus VAT we consider that a repair reserve of £3,875.00 would be reasonable on this occasion and the Third Party being responsible for the VAT

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 30th December 2025, on your behalf subject to the Third Party being responsible for the VAT.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. CAE AMIMI AQP
Connexus Vehicle Assessors