

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr M Kaul
40 Sabrina Road
Wolverhampton
West Midlands
WV6 8BP

Date: 20/03/2026
Our Ref: 00077502/PK
Your Ref: EHR97686

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr M Kaul**

We refer to your instructions received on **03 March 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: TOYOTA COROLLA EXCEL HEV CVT	Colour: GREY	Speedo: 60320	Miles	
Reg No: FE20JLO	Registered: Mar 2020	Type: 5 Door Hatchback	Trans: Automatic	
Vin No: SB1K93BE20E101458	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: 	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2020			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Know
Steering: Not Known	Fuel: 			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1798	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 120.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light Accidental Damage Rear Bumper	Incident: 05/02/2026			
Vehicle Value: £14,051.00		Repair Cost: £2,264.58 inc VAT	(16.12% of PAV) Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

VEHICLE HISTORY CHECK

03/03/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

Repairable parts:-Repair Rear Bumper, Repair Rr Bumper Ctr Cover

Repaint only parts:-Rear Bumper Repair Paint Plastic, Rr Bumper Ctr Cover Repair Paint Plastic, Rear Bumper Cover Surface Paint Plast., Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, E.P.A. Charge, Methods Research, Bs10125, Pas2060, Pre Scan, Post Scan

Remove And Refit parts:-Rear Bumper Covering Cap, Rear Parking Aid Sensor/S, Rear Bumper, Rr/Ctr Bumper Cover, Left Rear Reflector, Right Rear Reflector

Parts to check:-Check And Clean Car, Check And Quality Control, Check Pre Clean

COST OF REPAIRS

The repairers, Sutton Motor Homes, 11–13 Coleshill Road, Sutton Coldfield, B75 7AA (Tel. Tel: 0121 355 4778), have compiled an estimate in the sum of £1,382.45 plus £776.74 for paint and materials plus £958.13 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £308.14 to £1,074.31 for the labour and £274.19 to £502.55 for paint and materials in their final account. The labour charge is based on 12.9 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £502.55. No new parts are required and the specialist/sundry charges will be £310.29, the VAT liability on this repair will amount to some £377.43 giving a total repair cost of £2,264.58 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £1,594.67.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 02/03/2020. The corresponding Glass's Guide (model code: 300444001) adjusted retail value for vehicles of this type and age in the February 2026 guide is £14,051.00 at 60320 Miles, trade value is £12,001.00 and mid value is £13,026.00. We place the pre-accident value of this particular vehicle at £14,051.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,275.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 20th March 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Kendrick AQP CAE AMIMI
Connexus Vehicle Assessors