

Phoenix Gas Holdings Ltd
Phoenix Gas Services Ltd,
Furlong Road,
ST
Tunstall,
Stoke-on-Trent
ST6 5UD

Date: 29/05/2026
Our Ref: 00035434/JEFPF
Your Ref: EHR100909


To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,

Client: **Phoenix Gas Holdings Ltd**

We refer to your instructions received on **30 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	CITROEN BERLINGO 950 ENTERPRISE	Colour:	WHITE	Speedo:	67882	Miles
Reg No:	MD23LVL	Registered:	Jun 2023	Type:	Panel Van	Trans:
Vin No:	VR7EFYHT2PJ654536	MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Tyre2
Audio:	Not Seen	Manfd:	2023			Spare Tyre
Brakes:	Not Known	Tax Exp:				Not Known
Steering:	Not Known	Fuel:	Diesel			Centre Belt
Extras:	Not Seen	C.C.:	1499			Not Tested
Air Bags Deployed:	Not Known	BHP:	100.	L/H/F Belt	Not Tested	L/H/R Tyre2
Damage:	Moderate Collision/Impact RH Front Bumper	Incident:	22/04/2026	L/H/F Tyre	Not Kno	L/H/R Tyre
						Not Kno



Vehicle Value:	£10,595.00	Repair Cost:	£2,914.45 exc VAT	(27.51% of PAV)	Roadworthy:	No
----------------	-------------------	--------------	--------------------------	-----------------	-------------	-----------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand front bumper.

ENGINEER'S COMMENTS

29/05/2026 - Supplementary for a Front Bumper Clamp Kit.

VEHICLE HISTORY CHECK

06/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Front Bumper, Front Lower Bumper, L/F Bumper Bracket, R/F Bumper Bracket, Front Bumper Damping, Frt Bumper Clamp Kit, Frt Bumper Wind Defl, Grille, Air Guide, Air Guide Bracket, Intercooler, Sundry Parts



Repaint only parts:-Basecoat Clear, Front Bumper New Part Paint K1r, Preparation For Pre-Painting

Specialist/Sundry charges:-Bs10125 Admin Fee, Frt No Plate, Car Care Kit, E.P.A. Charge, Tech Data + Methods, Aries Support

Remove And Refit parts:-Description, Front Bumper, Renew Front Centre Bumper (Removed), R/Air Funnel, Lower Engine Protection, Air Intercooler, Air Intake Resonator, Pre-Clean Vehicle For Repair, Final Check Road Test And Qc

Parts to check:-Veh Diag Pre, Veh Diag Post, Wash & Vac

COST OF REPAIRS

The repairers, XL Motors Ltd (Tel. 02476362181), have compiled an estimate in the sum of £699.55 plus parts at manufacturer's list prices plus £287.12 for paint and materials plus £167.66 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 8.4 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £287.12. The cost of the necessary replacement parts will be approximately £1,760.12, the specialist/sundry charges will be £167.66, giving a total repair cost of £2,914.45 plus VAT **subject to any undisclosed damage** and as the owner is eligible to recover the VAT there will be no tax liability for your good selves on this repair.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/06/2023. The corresponding CAP Guide (model code: 56321) adjusted retail value for vehicles of this type and age in the April 2026 guide is £10,595.00 at 10595 Miles, trade value is £8,550.00 and mid value is £9,572.50. We place the pre-accident value of this particular vehicle at £10,595.00 bearing in mind the condition described herein. As this is a commercial vehicle these values are excluding VAT.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

Although the total cost of this repair will be approximately £2,914.45 plus VAT we consider that a repair reserve of £2,925.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 6th May 2026, on your behalf subject to the owner being responsible for the VAT.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to Damage caused rendered the vehicle unroadworthy.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

 .

Our Ref: 00035434
Claim No: EHR100909

Continued

Page 3

Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors