

Accident Date: Tue Jun 02 2026

Submission date: Tue Jun 02 2026

Case ID: fd208ba4-3c9a-4758-bd6a-9cb5c1f1f89b

Case Details

Repair quote: £1,239.43 (excluding tax)

Vehicle Information

Producer	Toyota
Model	Auris
Type	-
Year of Production	2017
VIN	-
Registration Number	HG17ZTM
Registration Date	-
Mileage	69,444
Vehicle Value	-

Repair Summary

Remove & Install	-
Panel Repair Hours	-
Paint Hours	1 hours @ £6,500.00/hour
Part Costs	£261.98
Paint Material Costs	£305.45
Additional Costs	£165.00

Preliminary AI quote

Panel	Operation	Part Number	Producer	Supplier	Unit cost	Qty	Hours	Paint Material	Totals (£)
Main operations									
Front bumper							3.8		813.98
Front bumper	Replace	521190-Z965			211.12	1	2.8	305.00	698.12
Front bumper right fog lamp cover	Replace	5212502250			50.86	1	1.0	0.00	115.86
PAINT_PREPARATION							0.5		32.95
Preparation for painting	Repair	-			-	1	0.5	0.45	32.95
Other costs							2.0		165.00
CAR_CARE_KIT	-	-			15.00	1	0.3	-	34.50
ELECTRONICS_PART	-	-			20.00	1	-	-	20.00
PAINT_PREPARATION	-	-			0.00	1	1.7	-	110.50
Total cost (£)									813.98

Additional operation	Qty	Unit cost	Labour Hour	Total cost (£)
quote.additionalOperations.operation.CAR_CARE_KIT	1	15.00	0.3	34.50
quote.additionalOperations.operation.ELECTRONICS_PART	1	20.00	-	20.00
quote.additionalOperations.operation.PAINT_PREPARATION	1	0.00	1.7	110.50
Total cost (£)				165.00

Preliminary AI quote

Totals	Rate	Hours	Totals (£)
Part			261.98
Part cost	-	-	261.98
Labour			507.00
Paint labour	£65.00 / hr	1.5	97.50
Body labour	£65.00 / hr	4.8	409.50
Other costs			470.45
Paint material	-	-	305.45
Other costs	£65.00 / hr	-	165.00
Total excluding tax			1239.43
Tax	20%		247.89
Total including tax			1487.32

