

Accident Date: Tue Jun 02 2026

Submission date: Tue Jun 02 2026

Case ID: 1d14eacc-9326-4a35-aca1-5a9ef865ec6e

Case Details

Repair quote: £2,640.10 (excluding tax)

Vehicle Information

Producer	Hyundai
Model	i30
Type	-
Year of Production	2016
VIN	-
Registration Number	Ou66vdc
Registration Date	-
Mileage	188,982
Vehicle Value	-

Repair Summary

Remove & Install	-
Panel Repair Hours	-
Paint Hours	2.3 hours @ £6,500.00/hour
Part Costs	£1,497.90
Paint Material Costs	£710.70
Additional Costs	£165.00

Preliminary AI quote

Panel	Operation	Part Number	Producer	Supplier	Unit cost	Qty	Hours	Paint Material	Totals (£)
Main operations									
Bootlid							2.1		1395.61
Bootlid	Replace	73700-A6200			1064.41	1	2.1	194.70	1395.61
Rear bumper							2.0		1079.49
Rear bumper	Replace	86610-A6810			433.49	1	2.0	516.00	1079.49
Other costs							2.0		165.00
CAR_CARE_KIT	-	-			15.00	1	0.3	-	34.50
ELECTRONICS_PART	-	-			20.00	1	-	-	20.00
PAINT_PREPARATION	-	-			0.00	1	1.7	-	110.50
Total cost (£)									2475.10

Additional operation	Qty	Unit cost	Labour Hour	Total cost (£)
quote.additionalOperations.operation.CAR_CA	1	15.00	0.3	34.50
quote.additionalOperations.operation.ELECTR	1	20.00	-	20.00
quote.additionalOperations.operation.PAINT_PI	1	0.00	1.7	110.50
Total cost (£)				165.00

Preliminary AI quote

Totals	Rate	Hours	Totals (£)
Part			1497.90
Part cost	-	-	1497.90
Labour			396.50
Paint labour	£65.00 / hr	2.3	149.50
Body labour	£65.00 / hr	3.8	247.00
Other costs			745.70
Paint material	-	-	710.70
Other costs	-	-	35.00
Total excluding tax			2640.10
Tax	20%		528.02
Total including tax			3168.12

