

QDOS Assistance
 1st Floor, Barfield House
 24-28 alderley Road
 Wilmslow
 Cheshire
 SK9 1PL

Date: 13/08/2026
 Our Ref: 00042640/MATTG
 Your Ref: 47620/1

To the Court REPAIRABLE REPORT

Dear Sirs,
 Client: **Mr David Smith**

We refer to your instructions received on **11 August 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: BMW 420D M SPORT		Colour: Red	Speedo:	Miles:
Reg No: DF18FEJ	Registered: May 2018	Type: Coupe	Trans: Manual	
Vin No: WBA4X32030AF36267	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2018			Spare Tyre
Brakes: Not Known	Tax Exp:			Not Known
Steering: Not Known	Fuel: Diesel			Centre Belt
Extras: Not Seen	C.C.: 1995			Not Tested
Air Bags Deployed: Not Known	BHP: 187.	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Very Light Collision/Impact Front Bumper	Incident: 10/08/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £12,866.00		Repair Cost: £2,365.02 inc VAT	(18.38% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered very light collision/impact damage to the front bumper.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

The valuation for the purpose of this report has been calculated using an estimated mileage from the vehicles MOT history at the time of loss.

VEHICLE HISTORY CHECK

12/08/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Frt Bumper Air Grill, Panel Sundries, Car Care Kit, Sundry Parts

Repairable parts:-Front Bumper

Repaint only parts:-Two Coat Metallic, Front Bumper Repair Paint Plastic, De Nib & Polish. Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Bsi Compliance, Adas Methods, Epa, Corrosion Protection Materials External

Remove And Refit parts:-Description, Add/Time For Main Work, Front Bumper Cover, Front Bumper Cover Air Grille, Corrosion Prote To 1St Panel

Parts to check:-Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vaccum, Est Pre Wash

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,317.45. The cost of the paint and materials would be £423.45, The cost of the replacement parts would be approximately £103.47, The specialist/sundry charges would be £126.48, and the VAT liability on the total would amount to some £394.17 giving a total repair cost of £2,365.02 including VAT **subject to undisclosed damage**. The labour charge is based on 12.78 hours at a rate of £103.06 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 31/05/2018. The corresponding Cazana Guide (model code: 1104408) adjusted retail value for vehicles of this type and age in the August 2026 guide is £12,866.00 at 78650 Miles, trade value is £10,679.00 and mid value is £11,772.50. We place the pre-accident value of this particular vehicle at £12,866.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,375.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors



CLvehicedamage3jpg-V1.jpg



2_CLvehicedamage2jpg-V1.jpg



3_CLvehicedamage4jpg-V1.jpg



6_CLvehicleVINnumberjpg-V1.jpg