

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 20/05/2026
Our Ref: 00036686/PHILB
Your Ref: 45430/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Demetria Yhap**

We refer to your instructions received on **19 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: BMW 435I M SPORT AUTO		Colour: BLACK	Speedo: Miles	
Reg No: OY64BTE	Registered: Sep 2014	Type: Convertible	Trans: Automatic	
Vin No: WBA3T32090P783035	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2014			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Know
Steering: Not Known	Fuel: Petrol			Centre Belt Not Tested
Extras: Not Seen	C.C.: 2979	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 301.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light to Moderate Collision/Impact Rear		Incident: 17/05/2026		
Vehicle Value: £13,035.00		Repair Cost: £4,103.78 inc VAT (31.48% of PAV)	Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the rear.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

The valuation for the purpose of this report has been calculated using an estimated mileage from the vehicles MOT history at the time of loss.

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Rear Bumper Cover, Rear Bumper Support, Rr Ctr Bumper Guide, Lwr Rr Bumper Cover, Car Care Kit, Glass Lifting Tape, Sundry Parts

Repaint only parts:-Two Coat Metallic, Rear Bumper Cover New Part Paint K1r, De Nib & Polish. Per Panel, Preparation For Pre-Painting



Specialist/Sundry charges:-Bsi Compliance, Epa, Repair Methods

Blend only parts:-L/R Side Panel Surface Paint, R/R Side Panel Surface Paint

Remove And Refit parts:-Description, Add/Time For Main Work, Rear Bumper Trim, Rear Bumper Carrier, Renew Rear Bumper Trim, Rr Ctr Bumper Guide, Add/Work Park Distance Control

Parts to check:-Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,193.11. The cost of the paint and materials would be £914.61, The cost of the replacement parts would be approximately £1,194.23, The specialist/sundry charges would be £117.87, and the VAT liability on the total would amount to some £683.96 giving a total repair cost of £4,103.78 including VAT **subject to undisclosed damage**. The labour charge is based on 10.07 hours at a rate of £118.52 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 22/09/2014. The corresponding Cazana Guide (model code: 6655) adjusted retail value for vehicles of this type and age in the May 2026 guide is £13,035.00 at 80000 Miles, trade value is £10,688.00 and mid value is £11,861.50. We place the pre-accident value of this particular vehicle at £13,035.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £4,125.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Birch ATA VDA
Exclusive Vehicle Assessors



1_CLVreg45430png-V1.png



2_CLVdamage45430png-V1.png



VIN-V1.jpg



3_CLVdamage245430png-V1.png



4_CLVdamage345430png-V1.png