

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 17/04/2026
Our Ref: 00034523/NOELB
Your Ref: 444071


To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Christopher Anastasi**

We refer to your instructions received on **16 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VOLKSWAGEN GOLF GTD S-A	Colour: WHITE	Speedo: 87000	Miles
Reg No: T88SSO	Registered: Mar 2014	Type: 5 Door Hatchback	Trans: Semi-Auto
Vin No: WVWZZZAUZEW268518	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manfd: 2014		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel: Diesel		Centre Belt
Extras: Not Seen	C.C.: 1968		Not Tested
Air Bags Deployed: Not Known	BHP: 182	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact LH Side	Incident: 25/03/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno



Vehicle Value: £9,960.00	Repair Cost: £1,229.35 inc VAT	(12.34% of PAV)	Roadworthy: Yes
---------------------------------	---------------------------------------	-----------------	------------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

The valuation for the purpose of this report has been calculated using an estimated mileage from the vehicles MOT history at the time of loss.

VEHICLE HISTORY CHECK

17/04/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-L/F Door Out Handle, Sundry Parts

Repaint only parts:-L/F Door Out Handle New Part Paint K1r, Preparation For Pre-Painting

Specialist/Sundry charges:-Sundries, Aries Support, Car Care Kit, E.P.A. Charge, Methods Research Specialist

Remove And Refit parts:-Description, Left Front Door Handle, Final Check Road Test And Qc



Parts to check:-Veh Diag Pre, Veh Diag Post, Wash & Vac

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £516.34. The cost of the paint and materials would be £169.17, The cost of the replacement parts would be approximately £68.31, The specialist/sundry charges would be £270.64, and the VAT liability on the total would amount to some £204.89 giving a total repair cost of £1,229.35 including VAT **subject to undisclosed damage**. The labour charge is based on 6.2 hours at a rate of £83.28 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 07/03/2014. The corresponding Percayso Guide (model code: 9374) adjusted retail value for vehicles of this type and age in the March 2026 guide is £9,960.00 at 87000 Miles, trade value is £8,765.00 and mid value is £9,362.50. We place the pre-accident value of this particular vehicle at £9,960.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £1,250.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.** We understand that the vehicle is still being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Noel Barnes Dip VDA AQP
Exclusive Vehicle Assessors



clv damage 1.jpeg



clvdamage1-V1.jpeg