

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr N Dunn
26 Felsmere Drive
Felbridge
East Grinstead
Surrey
RH19 2SY

Date: 12/09/2025
Our Ref: 00073137/PK
Your Ref: EHR88530

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr N Dunn**

We refer to your instructions received on **12 September 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MERCEDES-BENZ GLA 200 D AMG LINE	Colour: GREY	Speedo: 110505	Miles
Reg No: LS16FOT	Registered: Mar 2016	Type: 5 Door Estate	Trans: Automatic
Vin No: WDC1569082J243801	MOT Exp:	R/H/F Tyre	R/H/R Tyre
Mods:	Cond: Good	R/H/F Belt	R/H/R Belt
Audio:	Manf'd: 2016	Spare Tyre	
Brakes: Satisfactory	Tax Exp:		
Steering: Satisfactory	Fuel: Diesel	Centre Belt	
Extras:	C.C.: 2143		
Air Bags Deployed:	BHP: 134	L/H/F Belt	L/H/R Belt
Damage: Light Accidental Damage RH Side Door	Incident: 26/08/2025	L/H/F Tyre	L/H/R Tyre
Vehicle Value: £9,220.00		Repair Cost: £2,772.26 inc VAT (30.07% of PAV)	
		Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the right hand side door, and to the wing.

VEHICLE HISTORY CHECK

12/09/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-R/F Wing Trim, R/F Tyre

Repairable parts:-Repair R/F Wing, Repair Right Front Door, Repair R/Sill Panel Cover

Repaint only parts:-R/F Wing Painting Stage Iii, Right Front Door Painting Stage Iii, Outer Cleaning Carry Out, Polish Vehicle, Security Measures Before, Preparation Work For Two Coat Painting, Add For Preparation Work, Additional Time For 3 Coat System

Specialist/Sundry charges:-Car Care Kit, E.P.A. Charge, Methods Research, Pre / Post Checks, Diamond cut Wheel Refx1, Wheel Alignment, Sundry Part

Remove And Refit parts:-Detach + Refit Front Bumper, R/F Lamp Unit, R/Wing Trim, Right Front Door Trim, Right Mirror, R/Waist Moulding, Right Front Outer Door Handle, Right Sill Trim, Front Wheel, Right Front Tyre, Addition To R/F Tyre, R/Front Wheel Balance, Front Bumper Release, Allowance And Clean Car, Road Test And Quality Control

COST OF REPAIRS

The repairers, Accident Repair Hub, 3-6 Palmer's Rd, Emsworth, PO10 7DH (Tel. 01243 377921), have compiled an estimate in the sum of £785.00 plus parts at manufacturer's list prices plus £494.25 for paint and materials plus £332.91 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £1,320.00. The labour charge is based on 16.5 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £494.25. The cost of the necessary replacement parts will be approximately £70.50, the specialist/sundry charges will be £425.47, the VAT liability on this repair will amount to some £462.04 giving a total repair cost of £2,772.26 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 29/03/2016. The corresponding Glass's Guide (model code: 6MPF) adjusted retail value for vehicles of this type and age in the August 2025 guide is £9,220.00 at 110505 Miles, trade value is £5,960.00 and mid value is £7,590.00. We place the pre-accident value of this particular vehicle at £9,220.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,775.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 12th September 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

. CAE AMIMI AQP
Connexus Vehicle Assessors