

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

2/2

Mr C White
21 Lancaster Gate
Bletchley
Milton Keynes
Buckinghamshire
MK3 6AA

Date: 11/11/2025
Our Ref: 00074836/PK
Your Ref: EHR91554

Engineer Repairable Report - Amended Report

Dear Sirs,

Client/Insured: **Mr C White**

We refer to your instructions received on **07 November 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: HYUNDAI BAYON PREMIUM T-GDI MHE	Colour: GREEN	Speedo: 33272	Miles	
Reg No: KF21FTP	Registered: Jul 2021	Type: 5 Door Hatchback	Trans: Manual	
Vin No: NLHBR81GLNZ075572	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2021			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Know
Steering: Not Known	Fuel: Hybrid			Centre Belt Not Tested
Extras: Not Seen	C.C.: 998	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 98.6	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light Accidental Damage Rear Bumper	Incident: 05/11/2025			
Vehicle Value: £11,130.00		Repair Cost: £3,182.77 inc VAT	(28.60% of PAV) Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

ENGINEER'S COMMENTS

08/12/2025 - Final costs more damage found new cover / retainers / carriers / support.

VEHICLE HISTORY CHECK

07/11/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rear Bumper Cover, L/Upper Retainer, R/Upper Retainer, L/Bumper Carrier, R/Bumper Carrier, Rear Bumper Support

Repairable parts:-Repair Method, Repair R/R Upper Bumper

Repaint only parts:-Rear Bumper Cover New Part Paint K1n, R/R Upper Bumper Repair Paint Plastic, Polish De Nib, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Vehicle Care Kit, Bs10125, Pre Scan, Post Scan, Energy Charge, Sundry Part, Epa, Repair Method, Energy charge

Remove And Refit parts:-Renew Rear Bumper Cpl, Rear Bumper Carrier, Hybrid Vehicle Electric, Road Test Qc, Vacuum Wash

COST OF REPAIRS

The repairers, Milton Keynes Motor Company, MK2 3JU (Tel. 01933 229 062), have compiled an estimate in the sum of £1,128.00 plus parts at manufacturer's list prices plus £328.72 for paint and materials plus £377.13 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £248.00 to £880.00 for the labour and £104.84 to £223.88 for paint and materials in their final account. The labour charge is based on 11 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £223.88. The cost of the necessary replacement parts will be approximately £1,196.55, the specialist/sundry charges will be £351.88, the VAT liability on this repair will amount to some £530.46 giving a total repair cost of £3,182.77 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £453.71.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 22/07/2021. The corresponding Glass's Guide (model code: PRM9) adjusted retail value for vehicles of this type and age in the November 2025 guide is £11,130.00 at 33272 Miles, trade value is £8,860.00 and mid value is £9,995.00. We place the pre-accident value of this particular vehicle at £11,130.00 bearing in mind the condition described herein. The following adjustments have been made to the pre-accident value;

RESERVE

We consider that a repair reserve of £3,200.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 11th November 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

. CAE AMIMI AQP
Connexus Vehicle Assessors