

Mr Derek Burridge
86 Feversham Avenue
Bournemouth
BH
Bournemouth
BH8 9NJ

Date: 08/02/2026
 Our Ref: 00029812/JAKER
 Your Ref: EHR96219

To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,
Client: **Mr Derek Burridge**

We refer to your instructions received on **03 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI Q5 S LINE + TDI QUATTRO AUTO		Colour: GREY	Speedo: 79763 Miles	
Reg No: HF65JJO	Registered: Sep 2015	Type: Estate	Trans: Automatic	
Vin No: WAUZZZ8R5GA035462	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2015			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Known
Steering: Not Known	Fuel: Diesel			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1968			
Air Bags Deployed: Not Known	BHP: 187	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Collision/Impact Front	Incident: 01/02/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £13,554.00		Repair Cost: £3,633.56 inc VAT (26.81% of PAV)	Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the front.

VEHICLE HISTORY CHECK

08/02/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-L/F Air Guide Grille, Frt Centre Air Guide, L/Air Guide Cover, R/Air Guide Cover, Frt Bumper Filling, Front Closing Part, Frt Upp Bumper Cover, Grille, Radiator Grille Cvr, Car Care Kit

Repairable parts:-Repair Front Bumper, Repair Right Headlamp Assy

Repaint only parts:-Front Bumper Repair Paint Plastic, De Nib & Polish.Per Panel, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Geometry Check, Adas Methods, Method Research, Bs10125, Sundry Part, Epa

Remove And Refit parts:-Sound Insulation Pan, Front Bumper Cover, Dis + Ass Front Bumper Cover, Renew



Radiator Grille

Parts to check:-Check Qc & Road Test, Check Pre Rep Diag Scan, Check Post Rep Diag Scan, Check Wash And Vacuum, Check Adas Exploration

COST OF REPAIRS

The repairers, Krashtech Ltd (Tel. 01202 673 091), have compiled an estimate in the sum of £1,102.74 plus parts at manufacturer's list prices plus £356.99 for paint and materials plus £283.21 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £1,514.98. The labour charge is based on 14.7 hours at a rate of £103.06 per hour. We have also agreed that the cost of paint and materials will be limited to £356.99. The cost of the necessary replacement parts will be approximately £866.06, the specialist/sundry charges will be £289.94, the VAT liability on this repair will amount to some £605.59 giving a total repair cost of £3,633.56 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 01/09/2015. The corresponding Percayso Guide (model code: 10571) adjusted retail value for vehicles of this type and age in the February 2026 guide is £13,554.00 at 79763 Miles, trade value is £11,521.00 and mid value is £12,537.50. We place the pre-accident value of this particular vehicle at £13,554.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,650.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 8th February 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jake Roberts CAE AMIMI
Exclusive Vehicle Assessors