

Mr Alex Tyrrell
5 Lindsay Place
Swallownest
Sheffield
South Yorkshire
S26 4NE

Date: 14/05/2026
Our Ref: 00035072/DME
Your Ref: EHR100587

To the Court
REPAIRABLE REPORT - Amended Report

Dear Sirs,
Client: **Mr Alex Tyrrell**

We refer to your instructions received on **24 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	AUDI A5 S LINE BLACK ED 40 TDI S-A	Colour:	White	Speedo:	79479	Miles
Reg No:	CV19FLB	Registered:	Mar 2019	Type:	5 Door Hatchback	Trans: Semi-Auto
Vin No:	WAUZZZF5XKA013370	MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre Not Kno
Mods:	Not Seen	Cond:	Average	R/H/F Belt	Not Tested	R/H/R Belt Not Tested
Audio:	Not Seen	Manfd:	2019			Spare Tyre
Brakes:	Not Known	Tax Exp:				Not Know
Steering:	Not Known	Fuel:	Diesel			Centre Belt
Extras:	Not Seen	C.C.:	1968			Not Tested
Air Bags Deployed:	Not Known	BHP:	188	L/H/F Belt	Not Tested	L/H/R Belt Not Tested
Damage:	Light to Moderate Collision/Impact LH Rear Bumper	Incident:	23/04/2026	L/H/F Tyre	Not Kno	L/H/R Tyre Not Kno



Vehicle Value: £16,726.00	Repair Cost: £4,289.16 inc VAT (25.64% of PAV)	Roadworthy: Yes
----------------------------------	---	------------------------

AMENDED REPORT----- 14/05/2026 ---- SUPPLEMENTARY COSTS.

Please note the repairers have updated the repair method and parts costs with supporting images.

Authority sent via Audatex.

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered light to moderate collision impact to the left hand rear bumper.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.



Authority sent via Audatex.

VEHICLE HISTORY CHECK

28/04/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rear Bumper Spoiler, Rr Bumper Ctr Cover, Rear Bumper Support, Exhaust Pipe Trim, Car Care Kit, Min Paint Mix, Sundries

Repaint only parts:-Rear Bumper New Part Paint K1r, Spectrometer Reading repair Painting <50%, Spectrometer Reading polish For, De Nib, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Bs10125 Comp Charge, Epa, Tech Data & Methods, EIS Aries, PPS Cups, Adas Methods Only, Manufacturer Approval.

Remove And Refit parts:-Rear Bumper Cover, Renew Rear Bumper Cover, Rear Bumper (Impact Carrier), Renew Lower Rear Bumper Spoiler, Exhaust Trim, Min Paint Mix R&R / New Parts, Ice Vehicle Shutdown

Parts to check:-Check Qc & Road Test, Check Pre Repair Scan, Check Post Repair Scan, Check Pre Clean, Check Adas Identification, Check Wash & Vac

COST OF REPAIRS

An Audatex estimate has been obtained from Elite Motor Solutions, Unit 4a -4b Sheffield, S, Greasbro Road, S9 1TN (Tel. 0114 3273808) in the sum of £2,946.72 labour plus parts at manufacturer's list prices plus £1,461.50 for paint and materials plus £252.59 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be high and I have agreed a reduction with the repairers of £1,771.84 to £1,174.88 for the labour and £650.38 to £811.12 for paint and materials in their final account. The labour charge is based on 11.4 hours at a rate of £103.06 per hour. I have also agreed that the cost of paint and materials will be limited to £811.12. The cost of the necessary replacement parts will be approximately £1,335.71, the specialist/sundry charges will be £252.59, the VAT liability on this repair will amount to some £714.86 giving a total repair cost of £4,289.16 including VAT **subject to any undisclosed damage. I am pleased to confirm that I have achieved total gross savings in this matter of £2,982.40.**

OTHER DAMAGE

I noted the following damage on the vehicle:- None noted.

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT CONDITION

The vehicle is considered to be in average condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 19/03/2019.

The corresponding CAP Guide (model code: 85242) adjusted retail value for vehicles of this type and age in the April 2026 guide is £16,726.00 at 79000 Miles, trade value is £13,800.00.

I place the pre-accident value of this particular vehicle at £16,726.00 bearing in mind the condition described herein.

RESERVE

I consider that a repair reserve of £4,300.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 28th April 2026, on your behalf.

REPAIR DURATION

I consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

For & on behalf of

A handwritten signature in blue ink that reads "TIM CLARKE". The signature is written in a cursive, slightly slanted style.

Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors