

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr Mohamed Aswat
27 Maplewood Garden
Maplewood Gardens
Bolton
BL1 3NR

Date: 15/01/2026
Our Ref: 00076254/PK
Your Ref: 569715 \ 22037PC006995732

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr Mohamed Aswat**

We refer to your instructions received on **08 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI A4 TECHNIK 35 TFSI MHEV S-A		Colour: BLACK	Speedo: 16763	Miles
Reg No: MT72CDY	Registered: Nov 2022	Type: 4 Door Saloon	Trans: Semi-Auto	
Vin No: WAUZZZF43PN005151	MOT Exp: 	R/H/F Tyre 	R/H/R Tyre 	
Mods: 	Cond: Good	R/H/F Belt 	R/H/R Belt 	
Audio: 	Manf'd: 2022			Spare Tyre
Brakes: Satisfactory	Tax Exp: 			Centre Belt
Steering: Satisfactory	Fuel: Petrol			
Extras: 	C.C.: 1984			
Air Bags Deployed: 	BHP: 147.	L/H/F Belt 	L/H/R Belt 	
Damage: Light Accidental Damage Rear Bumper	Incident: 06/01/2026	L/H/F Tyre 	L/H/R Tyre 	
Vehicle Value: £20,250.00		Repair Cost: £2,086.18 inc VAT	(10.30% of PAV) Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

VEHICLE HISTORY CHECK

08/01/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Cover Bumper, Rear Bumper Spoiler, L/R Out Bumper Guide, R/R Out Bumper Guide, L/R Bumper Rail, R/R Bumper Rail

Repaint only parts:-Rear Cover Bumper New Part Paint K1r, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Pre Diag Check, Post Diag Check, Car Care Kit, E.P.A. Charge, Methods Research, Energy Payment, Bs10125, Sundry Part

Remove And Refit parts:-Gfs / Guided Function, Rear Bumper Cover, Renew Rear Bumper Cover, Renew Rear Bumper Spoiler (Removed), L/R Inner Bumper Carrier, R/R Inner Bumper Carrier

Parts to check:-Check And Clean Car, Check And Quality Control, Check And Road Test

COST OF REPAIRS

The repairers, Parkway Prestige (Arc) Ltd, Unit 10. Monde Trading Estate, Off Westinghouse Road, Trafford Park, M17 1LP (Tel. 01618725335), have compiled an estimate in the sum of £527.00 plus parts at manufacturer's list prices plus £411.82 for paint and materials plus £321.26 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £59.50 to £467.50 in their final account. The labour charge is based on 5.5 hours at a rate of £85.00 per hour. We have also agreed that the cost of paint and materials will be limited to £411.82. The cost of the necessary replacement parts will be approximately £562.90, the specialist/sundry charges will be £296.26, the VAT liability on this repair will amount to some £347.70 giving a total repair cost of £2,086.18 including VAT **subject to any undisclosed damage.** **We are pleased to confirm that we have achieved total gross savings in this matter of £101.40.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 28/11/2022. The corresponding CAP Guide retail value for vehicles of this type and age in the January 2026 guide is £20,250.00 at 16763 Miles, trade value is £17,550.00 and mid value is £18,900.00. We place the pre-accident value of this particular vehicle at £20,250.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,100.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 15th January 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. CAE AMIMI AQP
Connexus Vehicle Assessors