

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mrs Sophie Howard
14 Mead Park
Holmer Green
High Wycombe
Buckinghamshire
HP15 6UL

Date: 26/01/2026
Our Ref: 00076518/PK
Your Ref: 570398 \ P0004499651

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mrs Sophie Howard**

We refer to your instructions received on **21 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VOLKSWAGEN GOLF R-LINE TSI	Colour: WHITE	Speedo: 1418	Miles
Reg No: DF75WCX	Registered: Nov 2025	Type: 5 Door Hatchback	Trans: Manual
Vin No: WVWZZZCD3TW183962	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2025		
Brakes: Not Known	Tax Exp: 		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1498	Spare Tyre Not Know	
Air Bags Deployed: Not Known	BHP: 147.	Centre Belt Not Tested	
Damage: Light Collision/Impact Rear Bumper	Incident: 21/01/2026	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £26,750.00		Repair Cost: £1,341.96 inc VAT	(5.02% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light collision/impact damage to the rear bumper.

VEHICLE HISTORY CHECK

21/01/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rr Bumper Moulding, Rr Bumper Clamp Kit

Repairable parts:-Repair Rear Cover Bumper

Repaint only parts:-Rear Cover Bumper Repair Paint Plastic, Bumper Prep > 15% Additional Lab, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, Data Link Charge, E.P.A. Charge, Methods Research, Pre / Post Checks, Plastic Repair Kit, Bumper Prep > 15%, Sundry Part

Remove And Refit parts:-Rear Number Plate, Left And Right Number Plate Lamps, Remove And Refit Both Outer Tail lamps, Rear Bumper Cover, Rear Bumper Diffuser, L/- And R/Reflector, Rear Parking Aid Sensors, Rear Bumper Mounting And Bracket, Allowance And Clean Car, Allowance And Quality Control, Allowance Technical Info

COST OF REPAIRS

The repairers, Motofix (High Wycombe), 722 London Road, High Wycombe, HP11 1HE (Tel. 01494 449 940), have compiled an estimate in the sum of £589.50 plus parts at manufacturer's list prices plus £318.30 for paint and materials plus £409.61 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 13.1 hours at a rate of £45.00 per hour. We have also agreed that the cost of paint and materials will be limited to £318.30. The cost of the necessary replacement parts will be approximately £60.89, the specialist/sundry charges will be £149.61, the VAT liability on this repair will amount to some £223.66 giving a total repair cost of £1,341.96 including VAT **subject to any undisclosed damage**. The costs agreed are subject to a parts discount of 2.50%. **We are pleased to confirm that we have achieved total gross savings in this matter of £313.87.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/11/2025. The corresponding CAP Guide retail value for vehicles of this type and age in the January 2026 guide is £26,750.00 at 1418 Miles, trade value is £24,250.00 and mid value is £25,500.00. We place the pre-accident value of this particular vehicle at £26,750.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £1,350.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 26th January 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

Connexus Vehicle Assessors