

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr Martin Richards
22 Conqueror Drive
Plymouth
PL5 3UT


Date: 04/02/2026
Our Ref: 00076795/PK
Your Ref: 569583 \ 5441210P

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr Martin Richards**

We refer to your instructions received on **03 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: BMW X7 XDRIVE40D M SPORT MHEV A	Colour: BLUE	Speedo: 48120	Miles
Reg No: AE22NZC	Registered: Mar 2022	Type: 5 Door Estate	Trans: Automatic
Vin No: WBATB420709L09484	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond:	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Man'f'd: 2022		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel:		Centre Belt
Extras: Not Seen	C.C.: 2993		Not Tested
Air Bags Deployed: Not Known	BHP: 335.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light Accidental Damage RH Front Bumper	Incident: 05/01/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £51,300.00	Repair Cost: £2,420.28 inc VAT	(4.72% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the right hand front bumper, and to the wing.

VEHICLE HISTORY CHECK

03/02/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-R/Out U-Sonic Sender

Repairable parts:-Repair Front Bumper

Repaint only parts:-Front Bumper Repair Paint Plastic, R/F Wheel arch Trim Repair Paint Plastic, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, Tech Data & Methods, Pre/Post Diag, Wheel Alignment, Pre Clean Vehicle, Sundry Part, Epa

Remove And Refit parts:-Add/Time For Main Work, Front Bumper Trim, L/F Ultrasonic Converter, Front Bumper Lower Air Intake Grill, Front Centre Bumper Trim, L/F Bumper Air Grille, R/F Bumper Air Grille, R/F Wheel arch Trim, L/F Wheelhouse Liner Front, R/F Wheelhouse Liner Front, R/Ultrasonic Sensor, L/F Fog lamp, R/F Fog lamp, Left Front Wheel, Right Front Wheel

Parts to check:-Check Quality Control

COST OF REPAIRS

The repairers, Ocean Bodycentre, 12 Lister Close, Plympton, Plymouth, PL7 4BA (Tel. 01752 502645), have compiled an estimate in the sum of £1,130.50 plus parts at manufacturer's list prices plus £451.72 for paint and materials plus £304.75 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 13.3 hours at a rate of £85.00 per hour. We have also agreed that the cost of paint and materials will be limited to £406.55. The cost of the necessary replacement parts will be approximately £175.10, the specialist/sundry charges will be £304.75, the VAT liability on this repair will amount to some £403.38 giving a total repair cost of £2,420.28 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £54.20.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 01/03/2022. The corresponding Guide retail value for vehicles of this type and age in the January 2026 guide is £51,300.00 at 48120 Miles, trade value is £48,500.00 and mid value is £49,900.00. We place the pre-accident value of this particular vehicle at £51,300.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,425.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 4th February 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.** We understand that the vehicle is still being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Kendrick AQP AMIMI
Connexus Vehicle Assessors