

Mr Adem Veli
2 Maple Crescent
Sidcup
DA
Sidcup
DA15 9LT

Date: 28/05/2026
Our Ref: 00035488/JEFFP
Your Ref: EHR100940

To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,
Client: **Mr Adem Veli**

We refer to your instructions received on **01 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VOLKSWAGEN GOLF R-LINE TSI	Colour: YELLOW	Speedo: 56460	Miles
Reg No: VU22NUE	Registered: Mar 2022	Type: 5 Door Hatchback	Trans: Manual
Vin No: WVWZZZCDZNW005696	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manfd: 2022		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Known
Steering: Not Known	Fuel: Petrol		Centre Belt
Extras: Not Seen	C.C.: 1498		Not Tested
Air Bags Deployed: Not Known	BHP: 128.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact LH Rear Bumper	Incident: 27/04/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £16,313.00	Repair Cost: £3,223.93 inc VAT	(19.76% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the left hand rear bumper.

ENGINEER'S COMMENTS

28/05/2026 - Supplementary for surface paint R/Roof Member, R/Side Panel, Fuel Filler Flap.

VEHICLE HISTORY CHECK

06/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Glass Lift Tape, Sundry Parts

Repairable parts:-Rear Cover Bumper

Repaint only parts:-Two Coat Metallic, Rear Cover Bumper Repair Paint Plastic, De Nib And Polish, Preparation



For Pre-Painting

Specialist/Sundry charges:-Pnl Repair Sundries, Methods Research, Car Care Kit, Aries Support, E.P.A. Charge, Tech Data + Methods

Blend only parts:-L/Roof Member Surface Paint, R/Roof Member Surface Paint, L/R Out Park Aid Surface Paint Plast., R/R Out Park Aid Surface Paint Plast., L/R Inner Sensor Surface Paint Plast., R/R Inner Sensor Surface Paint Plast., L/Side Panel Surface Paint, R/Side Panel Surface Paint, Fuel Filler Flap Surface Paint Plast., Screen Mask Frt Surface Paint, Side Glass Mask Surface Paint

Remove And Refit parts:-Description, Rear Number Plate, Left And Right Number Plate Lamps, Remove And Refit Both Outer Taillamps, Rear Bumper Cover, Rear Lower Spoiler, L/- And R/Reflector, Rear Parking Aid Sensors, Rear Towing Hook Cover

Parts to check:-L/R Outer Lamp, Adas Explore, Test Fit Pnl, Qc And Road Test, Estimate Preclean, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum

COST OF REPAIRS

The repairers, FLEETLINE COACHWORKS LTD (Tel. 020 33425522), have compiled an estimate in the sum of £1,762.17 plus parts at manufacturer's list prices plus £737.62 for paint and materials plus £170.66 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 18.4 hours at a rate of £95.77 per hour. We have also agreed that the cost of paint and materials will be limited to £737.62. The cost of the necessary replacement parts will be approximately £16.16, the specialist/sundry charges will be £170.66, the VAT liability on this repair will amount to some £537.32 giving a total repair cost of £3,223.93 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 03/03/2022. The corresponding Cazana Guide (model code: 6588275) adjusted retail value for vehicles of this type and age in the April 2026 guide is £16,313.00 at 56460 Miles, trade value is £14,845.00 and mid value is £15,579.00. We place the pre-accident value of this particular vehicle at £16,313.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,225.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 6th May 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

A handwritten signature in dark ink, appearing to read "JP", followed by a period.

Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors