

Mr Harjit Singh
21 Silvermede Road
Wynyard
Billingham
TS
Wynyard
TS22 5FR


Date: 08/05/2026
Our Ref: 00035567/JEFFP
Your Ref: EHR101041

To the Court **REPAIRABLE REPORT**

Dear Sirs,

Client: **Mr Harjit Singh**

We refer to your instructions received on **04 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI Q2 SPORT 35 TFSI S-A	Colour: BLACK	Speedo: 15437	Miles
Reg No: NV74AEL	Registered: Oct 2024	Type: Estate	Trans: Semi-Auto
Vin No: WAUZZZGA9RA083657	MOT Exp:	R/H/F Tyre 4	R/H/R Tyre 6
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2024		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel: Petrol		Centre Belt
Extras: Not Seen	C.C.: 1498		Not Tested
Air Bags Deployed: Not Known	BHP: 147.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact RH Front Door	Incident: 01/04/2026	L/H/F Tyre 4	L/H/R Tyre 6
Vehicle Value: £24,292.00		Repair Cost: £3,163.18 inc VAT	(13.02% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand front door.

VEHICLE HISTORY CHECK

08/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Sundry Parts

Repairable parts:-R/F Lower Door

Repaint only parts:-Two Coat Metallic, R/Lwr Door Panel Repair Paint Plastic, R/F Lower Door Repair Painting <50%, Machine Polish X3, Preparation For Pre-Painting

Specialist/Sundry charges:-Bsi Kitemark Charge, Repair Materials, Adas Methods, Tech Data + Methods, E.P.A. Charge, Pas2060, Car Care Kit

Blend only parts:-R/F Wing Surface Paint, R/R Lower Door Trim Surface Paint Plast., R/R Door Lower Surface Paint

Remove And Refit parts:-Description, R/F Wheelarch Moulding, Right Front Wheelhouse Shell, Right Door Trim, R/Outer Window Weather Strip, Right Mirror, Right Front Lock Cylinder, R/F Door Handle, Right Rear Door Trim, R/R Outer Window Channel Seal, Right Rear Door Handle, Front Bumper Release



Parts to check:-Pre-Repair Clean, Wash & Vacuum, Road Test & Quality, Veh Diag Pre, Veh Diag Post, Adas Research

COST OF REPAIRS

The repairers, Jobling Arc Ltd (Tel. 0191 565 7291), have compiled an estimate in the sum of £1,803.55 plus £633.77 for paint and materials plus £198.66 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 17.5 hours at a rate of £103.06 per hour. We have also agreed that the cost of paint and materials will be limited to £633.77. No new parts are required and the specialist/sundry charges will be £198.66, the VAT liability on this repair will amount to some £527.20 giving a total repair cost of £3,163.18 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 24/10/2024. The corresponding Cazana Guide (model code: 9780765) adjusted retail value for vehicles of this type and age in the April 2026 guide is £24,292.00 at 15437 Miles, trade value is £21,863.00 and mid value is £23,077.50. We place the pre-accident value of this particular vehicle at £24,292.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,175.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 8th May 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors