

Mr Lloyd Nyatsango
Flat 14
York Place
Camberley
GU
York Place
GU15 4BS

Date: 02/06/2026
Our Ref: 00037115/JEFFP
Your Ref: EHR102306

To the Court **REPAIRABLE REPORT**

Dear Sirs,

Client: **Mr Lloyd Nyatsango**

We refer to your instructions received on **28 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: BMW 320I SPORT AUTO	Colour: Silver	Speedo: 69392	Miles
Reg No: KS70XKD	Registered: Dec 2020	Type: Estate	Trans: Automatic
Vin No: WBA6K32090FK61849	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2020		Spare Tyre Not Know
Brakes: Not Known	Tax Exp:		Centre Belt Not Tested
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1998		
Air Bags Deployed: Not Known	BHP: 181	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact RH Front Bumper	Incident: 23/05/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £18,395.00	Repair Cost: £3,009.47 inc VAT	(16.36% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand front bumper.

VEHICLE HISTORY CHECK

02/06/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-R/F Air Guide Trim, Sundry Parts

Repairable parts:-Front Bumper

Repaint only parts:-Two Coat Metallic, Front Bumper Repair Paint Plastic, Preparation For Pre-Painting

Specialist/Sundry charges:-Sustainability, Panel Sundries, Pas Uplift, Tech Data + Methods, E.P.A. Charge, Car Care Kit

Blend only parts:-Frt Towing Eye Coversurface Paint Plast., Machine Polish Surface Paint

Remove And Refit parts:-Description, Add/Time For Main Work, Front Bumper Trim, Front Bumper Centre Air Grille R + R, L/Fr Air Vent Grille, L/F Bumper Moulding, R/F Bumper Moulding, Front Towing Hook Cover, R/Fr Air Vent Grille, L/F Ultrasonic Sensor, R/F Ultrasonic Sensor, L/F Ultrasonic Converter, R/F Ultrasonic Converter, Front Number Plate

Parts to check:-Pre Clean, Wash & Vac, Road Test & Qc, Veh Diag Pre, Veh Diag Post

COST OF REPAIRS

The repairers, Accident Repair Hub -Farnham (Tel. 01252 978750), have compiled an estimate in the sum of £1,904.23 plus parts at manufacturer's list prices plus £395.65 for paint and materials plus £170.28 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 16.07 hours at a rate of £118.52 per hour. We have also agreed that the cost of paint and materials will be limited to £395.65. The cost of the necessary replacement parts will be approximately £37.73, the specialist/sundry charges will be £170.28, the VAT liability on this repair will amount to some £501.58 giving a total repair cost of £3,009.47 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 09/12/2020. The corresponding CAP Guide (model code: 91563) adjusted retail value for vehicles of this type and age in the May 2026 guide is £18,395.00 at 69392 Miles, trade value is £15,850.00 and mid value is £17,122.50. We place the pre-accident value of this particular vehicle at £18,395.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,025.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 2nd June 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors