

Mr Mark Stuart
1 Church Fields
Wixford
Alcester
B
Wixford
B49 6DY

Date: 13/04/2026
Our Ref: 00033868/JAKER
Your Ref: EHR99580


To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,

Client: **Mr Mark Stuart**

We refer to your instructions received on **07 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	TESLA MODEL 3 PERFORMANCE AWD		Colour:	GREY	Speedo:	1312	Miles
Reg No:	BU26MXF	Registered:	Mar 2026	Type:	4 Door Saloon	Trans:	Automatic
Vin No:	LRW3F7ET9TC755915		MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre Not Kno
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested
Audio:	Not Seen	Manfd:	2026				Spare Tyre
Brakes:	Not Known	Tax Exp:					Not Known
Steering:	Not Known	Fuel:	Electric				Centre Belt
Extras:	Not Seen	C.C.:	0				Not Tested
Air Bags Deployed:	Not Known	BHP:	618.	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested
Damage:	Moderate Collision/Impact LH Front		Incident:	06/04/2026	L/H/F Tyre	Not Kno	L/H/R Tyre Not Kno



Vehicle Value: £40,342.00	Repair Cost: £5,556.66 inc VAT	(13.77% of PAV)	Roadworthy: Yes
----------------------------------	---------------------------------------	-----------------	------------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand front.

VEHICLE HISTORY CHECK

13/04/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Front Bumper Spoiler, Front Driving Camera, Left Headlamp Assy, Screw, Sundry Parts

Repairable parts:-Front Bumper

Repaint only parts:-Description, Frt Towing Eye Covernew Part Paint K1r, Front Bumper Repair Paint Plastic, Bumper Prep > 15% Additional Lab, Preparation For Pre-Painting

Specialist/Sundry charges:-Bsi10125, Adas Methods, Bumper Prep > 15%, Xirallic Uplift, Camera, Tech Data + Methods, Aries Support, E.P.A. Charge, Car Care Kit, Adas Reset

Blend only parts:-L/F Wing Surface Paint



Remove And Refit parts:-Description, Vehicle Preparation Time, Toolbox Tesla Diagnos Schalt/Ab-Anschalt, Front Number Plate Reinforcement, Radiator Grille, Front Spoiler, Renew L/Headlamp, L/F Wheelarch Shell, L/Repeater Lamp, After Adas Ext Road Test

Parts to check:-Frt Lwr Bumper Brkt, Frt Bumper Absorber, Pre Repair Clean, Ev Risk Assessment, Ev Shutdown, Wash & Vac, And Road Test, Veh Diag Pre, Veh Diag Post, Adas Exploration

COST OF REPAIRS

The repairers, Wyndon Motors Ltd (Tel. 02476332303), have compiled an estimate in the sum of £2,081.81 plus parts at manufacturer's list prices plus £556.01 for paint and materials plus £646.86 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 20.2 hours at a rate of £103.06 per hour. We have also agreed that the cost of paint and materials will be limited to £556.01. The cost of the necessary replacement parts will be approximately £1,345.87, the specialist/sundry charges will be £646.86, the VAT liability on this repair will amount to some £926.11 giving a total repair cost of £5,556.66 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 02/03/2026. There are no guide values for vehicles of this age and type. We place the pre-accident value of this particular vehicle at £40,342.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £5,575.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 13th April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jake Roberts CAE AMIMI
Exclusive Vehicle Assessors