

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mrs J Lemke
15 Luke Lane
Innsworth
Gloucester
Gloucestershire
GL3 1HJ

Date: 26/02/2026
Our Ref: 00077056/PK
Your Ref: EHR96659

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mrs J Lemke**

We refer to your instructions received on **12 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD KUGA ST-LINE EDITION ECOBLU	Colour: WHITE	Speedo: 43810	Miles	
Reg No: YS21WHV	Registered: Mar 2021	Type: 5 Door Hatchback	Trans: Manual	
Vin No: WF0FXXWPMFMJ39197	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2021			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Know
Steering: Not Known	Fuel: Diesel			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1499	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 118.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light to Moderate Accidental Damage Rear Bumper	Incident: 11/02/2026			
Vehicle Value: £14,550.00		Repair Cost: £4,755.12 inc VAT	(32.68% of PAV) Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate accidental damage to the rear bumper, and to the underside.

ENGINEER'S COMMENTS

26/02/2026 - Possible more damage.

VEHICLE HISTORY CHECK

12/02/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, L/R Out Bumper Brkt, Rear Ctr Lwr Bracket, Mounting Clamp, Screw, Mounting Clamp, Mounting Clamp, Tow Bar, Rr Exhaust Silencer

Repairable parts:-Repair Rr Bumper Ctr Cover, Repair Methods

Repaint only parts:-Rear Bumper New Part Paint K1r, Rr Bumper Ctr Cover Repair Paint Plastic, Rear Cover Bumper Surface Paint Plast., L/R Out Parking Sens surface Paint Plast., R/R Out Parking Sens surface Paint Plast., L/R Inn Parking Sens surface Paint Plast., R/R Inn Parking Sens surface Paint Plast., Machine Polish Quarters, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-E.P.A. Charge, Aries Charge, Car Care Kit, Adas Reset, Body Filler, Sundry Part, Repair Methods

Remove And Refit parts:-Add/Time For One Main Position, Rear Bumper, Renew Rear Bumper (Removed), Left Rear Bumper Bracket, Tow Bar, Rear Muffler, Exhaust Pipe Trim, Specialist Wire Tow Socket

Parts to check:-Check Parking Help Sensor, Check Pre Wash, Check Wash & Vac, Check And Road Test, Check Veh Diag Post Check, Check Veh Diag Post Check

COST OF REPAIRS

The repairers, SJ Curtis, Southway Drive North Common, Warmley, Bristol, BS305LW (Tel. 01179603073), have compiled an estimate in the sum of £2,586.60 plus parts at manufacturer's list prices plus £1,300.29 for paint and materials plus £523.61 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £1,077.01 to £1,509.59 for the labour and £649.50 to £650.79 for paint and materials in their final account. The labour charge is based on 17.1 hours at a rate of £88.28 per hour. We have also agreed that the cost of paint and materials will be limited to £650.79. The cost of the necessary replacement parts will be approximately £1,606.32, the specialist/sundry charges will be £195.90, the VAT liability on this repair will amount to some £792.52 giving a total repair cost of £4,755.12 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £2,547.74.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 19/03/2021. The corresponding Glass's Guide retail value for vehicles of this type and age in the February 2026 guide is £14,550.00 at 43810 Miles, trade value is £12,111.00 and mid value is £13,330.50. We place the pre-accident value of this particular vehicle at £14,550.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £4,775.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 26th February 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Kendrick AQP CAE AMIMI
Connexus Vehicle Assessors