

Mrs P Heels  
North Farm Summerhouse  
Darlington  
County Durham  
DL2 3UD

Date: 05/02/2026  
Our Ref: 00076694/PK  
Your Ref: EHR95914

## **Engineer Repairable Report - Amended Report**

Dear Sirs,

Client/Insured: **Mrs P Heels**

We refer to your instructions received on **28 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

|                                                    |                             |                                                                                      |                                        |                               |
|----------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------|----------------------------------------|-------------------------------|
| Vehicle: <b>MERCEDES-BENZ A 200 AMG LINE EXE</b>   | Colour: <b>SILVER</b>       | Speedo: <b>9444</b>                                                                  | <b>Miles</b>                           |                               |
| Reg No: <b>ND25XYZ</b>                             | Registered: <b>May 2025</b> | Type: <b>5 Door Hatchback</b>                                                        | Trans: <b>Automatic</b>                |                               |
| Vin No: <b>W1K3F1CB9TJ514741</b>                   | MOT Exp: <b></b>            | R/H/F Tyre <b>Not Kno</b>                                                            | R/H/R Tyre <b>Not Kno</b>              |                               |
| Mods: <b>Not Seen</b>                              | Cond: <b>Good</b>           | R/H/F Belt <b>Not Tested</b>                                                         | R/H/R Belt <b>Not Tested</b>           |                               |
| Audio: <b>Not Seen</b>                             | Man'f'd: <b>2025</b>        |  |                                        |                               |
| Brakes: <b>Not Known</b>                           | Tax Exp: <b></b>            |                                                                                      |                                        | Spare Tyre <b>Not Know</b>    |
| Steering: <b>Not Known</b>                         | Fuel: <b>Diesel</b>         |                                                                                      |                                        | Centre Belt <b>Not Tested</b> |
| Extras: <b>Not Seen</b>                            | C.C.: <b>1950</b>           | L/H/F Belt <b>Not Tested</b>                                                         | L/H/R Belt <b>Not Tested</b>           |                               |
| Air Bags Deployed: <b>Not Known</b>                | BHP: <b>147.</b>            | L/H/F Tyre <b>Not Kno</b>                                                            | L/H/R Tyre <b>Not Kno</b>              |                               |
| Damage: <b>Light Accidental Damage Rear Bumper</b> | Incident: <b>25/01/2026</b> |                                                                                      |                                        |                               |
| Vehicle Value: <b>£24,500.00</b>                   |                             | Repair Cost: <b>£3,261.94 inc VAT</b>                                                | (13.31% of PAV) Roadworthy: <b>Yes</b> |                               |

### **DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

### **NATURE OF INCIDENT**

The vehicle has suffered light accidental damage to the rear bumper.

### **ENGINEER'S COMMENTS**

26/02/2026 - Final costs more repair time required. Uplift added for manufacture approval.

### **VEHICLE HISTORY CHECK**

28/01/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

### **REPAIR SCHEDULE**

**New parts required:-**Rear Bumper Moulding, Bumper Fittings, Bumper Rivets, Rivets

**Repairable parts:-**Repair Rear Bumper Cover, Repair Plastic Part With Swage, Repair/Apply Filler On Plast/Metal Parts

**Repaint only parts:-**Rear Bumper Cover Painting, Add Colour Sample 1, Outer Cleaning Carry Out, Polish Vehicle, Non Water Based Remove, >15% Bumper Prep Azi Rules, Machine Polish Surface Paint, Preparation Work For Two Coat Painting, Add For Preparation Work, Carry Out Colour Shade Determination, Prime Plastic/Metal Parts, Apply Smoothing Filler On Plast/Met Parts, Apply Primer Rear Bumper (Add/Work), Apply Filler Rear Bumper (Add/Work),

Apply Filler Paste Rear Bumper (Add)

**Specialist/Sundry charges:-**Bsi Compliance, Mb Approved, Tech Data + Methods, E.P.A. Charge, Aries Support, Pre Rep Diag Check, Post Rep Diag Check, Sundry Part

**Remove And Refit parts:-**Rear Underbody Covering, Rear Bumper, Add For Rear Bumper, Dis + Ass Rear Bumper (Removed), Addition To Dis + Ass Rear Bumper, Two Wheels, Add To L/R Wheel Remove And Refit, Add To R/R Wheel Remove And Refit

**Parts to check:-**Check Pre Repair Clean, Check Wash & Vac

### **COST OF REPAIRS**

The repairers, James Alpe Ltd, BB7 1QD, have compiled an estimate in the sum of £1,534.45 plus parts at manufacturer's list prices plus £402.04 for paint and materials plus £363.69 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £1,804.60. The labour charge is based on 16.7 hours at a rate of £108.06 per hour. We have also agreed that the cost of paint and materials will be limited to £402.04. The cost of the necessary replacement parts will be approximately £146.50, the specialist/sundry charges will be £365.14, the VAT liability on this repair will amount to some £543.66 giving a total repair cost of £3,261.94 including VAT **subject to any undisclosed damage.**

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **PRE-INCIDENT VALUE**

According to the information available to us the vehicle was first registered in 31/05/2025. The corresponding Guide retail value for vehicles of this type and age in the January 2026 guide is £24,500.00 at 9444 Miles, trade value is £21,010.00 and mid value is £22,755.00. We place the pre-accident value of this particular vehicle at £24,500.00 bearing in mind the condition described herein.

### **RESERVE**

We consider that a repair reserve of £3,275.00 would be reasonable on this occasion.

### **INSTRUCTIONS ISSUED**

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 5th February 2026, on your behalf.

### **REPAIR DURATION**

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

### **ROADWORTHY STATE**

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy.

**The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Kendrick AQP CAE AMIMI  
Connexus Vehicle Assessors