

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mrs H Smith
48 Sumerling Way
Bluntisham
Huntingdon
Cambridgeshire
PE28 3XT


Date: 12/12/2025
Our Ref: 00075221/GC
Your Ref: EHR92456

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mrs H Smith**

We refer to your instructions received on **21 November 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: TOYOTA YARIS DESIGN HEV CVT	Colour: BLUE	Speedo: 23475	Miles
Reg No: FL74EKF	Registered: Sep 2024	Type: 5 Door Hatchback	Trans: Automatic
Vin No: VNKKBAC330A368091	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2024		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Hybrid		
Extras: Not Seen	C.C.: 1490	Spare Tyre Not Know	
Air Bags Deployed: Not Known	BHP: 114	Centre Belt Not Tested	
Damage: Light to Moderate Accidental Damage RH Front Mirror	Incident: 20/11/2025	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £17,120.00		Repair Cost: £1,323.70 inc VAT	(7.73% of PAV)
		Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate accidental damage to the right hand front mirror.

VEHICLE HISTORY CHECK

21/11/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-L/Door Mirror, L/Door Mirror Hsg

Repaint only parts:-De Nib Per Panel

Specialist/Sundry charges:-Bs10125, Car Care Kit, E.P.A. Charge, Pre_Rep_Diag_Check, Post_Rep_Diag_Check, Methods Research, Pas2060, Energy Supplement, Adas Methods, Hybrd Full Charge, Sundry Part

Remove And Refit parts:-L/F Door Mirror, Road Test And Quality Control

Parts to check:-Check Id Adas

DELETED PARTS

We advise that we have removed the following from the repairer's original estimate, as we do not consider they are required; Collection and Delivery cost, Full EV Battery shut down at this stage and should be subject to further checks or explanation

COST OF REPAIRS

The repairers, LD AutoVogue Ltd, Unit 18, 21 Ironside Way, Hingham, Norwich, NR9 4LF (Tel. 01953 454 181), have compiled an estimate in the sum of £416.00 plus parts at manufacturer's list prices plus £523.00 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £240.00 to £176.00 in their final account. The labour charge is based on 2.2 hours at a rate of £80.00 per hour. **We are pleased to confirm that we have achieved total gross savings in this matter of £456.00.** The cost of the necessary replacement parts will be approximately £533.41, the specialist/sundry charges will be £393.67, the VAT liability on this repair will amount to some £220.62 giving a total repair cost of £1,323.70 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 18/09/2024. The corresponding Glass's Guide retail value for vehicles of this type and age in the November 2025 guide is £17,120.00 at 23475 Miles, trade value is £14,180.00 and mid value is £15,650.00. We place the pre-accident value of this particular vehicle at £17,120.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £1,325.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 12th December 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 1 to 2 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

Connexus Vehicle Assessors