

Mr Ravi Subrayan
22 Brockenhurst Road
Croydon
CR
Croydon
CR0 7DR

Date: 27/02/2026
Our Ref: 00031014/DME
Your Ref: EHR97251

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Ravi Subrayan**

We refer to your instructions received on **23 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: TESLA MODEL 3 PERFORMANCE AWD		Colour: Blue	Speedo: 74919 Miles	
Reg No: RRV181N	Registered: May 2023	Type: 4 Door Saloon	Trans: Automatic	
Vin No: LRW3F7EL2PC807777	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Unknown	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2023			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Known
Steering: Not Known	Fuel: Electric			Centre Belt Not Tested
Extras: Not Seen	C.C.: 0			
Air Bags Deployed: Not Deployed	BHP: 482.	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Collision/Impact RH Front	Incident: 18/02/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £20,518.00		Repair Cost: £3,300.97 inc VAT (16.09% of PAV)	Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered moderate collision impact to the right hand front.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.

Authority sent via Audatex.

VEHICLE HISTORY CHECK

27/02/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-R/Bumper Bracket, R/Inn Bumper Bracket, R/F Hub Cap, Body, Sundries

Repairable parts:-Repair Front Bumper, Repair R/F Wing



Repaint only parts:-Front Bumper Repair Paint Plastic, R/F Wing Repair Painting <50%, Frt Tow Eye Cover surface Paint Plast., Machine Polish, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, Methods Research, Wheel Alignment, Recharge, E.P.A. Charge

Remove And Refit parts:-Vehicle Preparation Time, Front Number Plate Reinforcement, Front Bumper, Radiator Grille, Front Spoiler, Right Front Bumper Bracket, Right Front Bumper Bracket, Front Axle Insulation Protect, Right Headlamp, R/F Wheelarch Shell

Parts to check:-Check Valet Car, Check Quality Control, Check Power Down, Check Vehicle Diag Post Check, Check Vehicle Diag Pre Check

COST OF REPAIRS

The repairers, LVS Coachworks (Tel. 0208 9931222), have compiled an estimate in the sum of £1,815.92 plus parts at manufacturer's list prices plus £582.92 for paint and materials plus £492.75 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be reasonable. The labour charge is based on 17.62 hours at a rate of £103.06 per hour. I have also agreed that the cost of paint and materials will be limited to £582.92. The cost of the necessary replacement parts will be approximately £100.86, the specialist/sundry charges will be £251.11, the VAT liability on this repair will amount to some £550.16 giving a total repair cost of £3,300.97 including VAT **subject to any undisclosed damage. I am pleased to confirm that I have achieved total gross savings in this matter of £289.97.**

OTHER DAMAGE

I noted the following damage on the vehicle:- None noted.

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 05/05/2023.

The corresponding Glass's Guide retail value for vehicles of this type and age in the February 2026 guide is £20,518.00 at 74000 Miles, trade value is £17,844.00.

I place the pre-accident value of this particular vehicle at £20,518.00 bearing in mind the condition described herein.

RESERVE

I consider that a repair reserve of £3,325.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 27th February 2026, on your behalf.

REPAIR DURATION

I consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle was not roadworthy at the time of my inspection as a result of the damage sustained due to Wheel damage.

For & on behalf of



Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors