

FAO The Court  
C/o QDOS Assistance  
1st Floor, Barfield House  
24-28 Alderly Road  
SK91PL

### **TOTAL LOSS REPORT**

Dear Sirs


**RE: Road traffic Accident: Gabriel Grancia: 14/04/2026**


In accordance with your instructions received on 22/04/2026 requesting us to provide an independent accident damage report, we assessed the damage on 22/04/2026. Vehicle located at Image based assessment. Our findings are as detailed below:

|                |                     |                  |                     |
|----------------|---------------------|------------------|---------------------|
| Make           | <b>BMW</b>          | Registration     | <b>AU62LCG</b>      |
| Model          | <b>640D SE AUTO</b> | Status           | <b>T/Loss</b>       |
| Category       | <b>N</b>            | Salvage Value    | <b>£795.00</b>      |
| Repair Cost    | <b>£7,417.81</b>    | Legal Status     | <b>Unroadworthy</b> |
| Engineer Value | <b>£5,300.00</b>    | Impact Magnitude | <b>Moderate</b>     |



Impact Area





**Our Ref:** qdos261071

**Your Ref:** 44688/1

**Date:** 24/04/2026

### **DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

### **NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the left hand front.

### **ENGINEER'S COMMENTS**

Parts prices to be confirmed

Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside front.

### **VEHICLE HISTORY CHECK**

According to the Experian database; there is a plate change on record

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **SETTLEMENT**


We consider that an equitable settlement would be £4,505.00 which represents the pre-accident engineer value of the vehicle of £5,300.00 less the value of the salvage of £795.00.

### **SALVAGE**

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at [www.abi.org.uk](http://www.abi.org.uk). We suggest that the sale of the salvage will realise in the order of £795.00. **We have not taken any action towards removal of the salvage at this time.**

## **Vehicle Data**

|                  |                          |
|------------------|--------------------------|
| Retail Value     |                          |
| Trade Value      |                          |
| Engineer's Value | <b>£5,300.00</b>         |
| Glass's Code     | <b>RPLJ</b>              |
| VIN              | <b>WBALX72010DX65867</b> |
| Odometer         | <b>157913</b>            |
| Engine           | <b>2993</b>              |
| Fuel             | <b>Diesel</b>            |
| Extras           |                          |
| Condition        | <b>Good</b>              |
| Unrelated Damage |                          |



**Our Ref:** qdos261071

**Your Ref:** 44688/1

**Date:** 24/04/2026

#### Main new parts required

Left headlamp  
Front bumper mounting kit  
Left front wing

Left headlamp mounting kit  
Front bumper  
Front left wing mounting kit

#### Additional operations

Check Older Vehicle Allowance  
Check Pre & Post Sweeps  
Paint Front bumper New Part (K1R) Parts removed  
Paint Preparation paintwork  
Specialist Vehicle Care Kit  
Specialist Car Care Kit  
Materials

Check QC & Road Test  
Paint Left front wing New Part (K1R) Parts removed  
Paint Left front door Surface (II)  
Specialist Assessment Fee  
Specialist EPA Charge  
Specialist Vehicle manufacturer approval charge


### Repair Cost Calculations

|                      |                  |
|----------------------|------------------|
| Hours                | <b>17.09</b>     |
| Hourly Rate          | <b>£83.28</b>    |
| Total Labour         | <b>£1,423.26</b> |
| Parts                | <b>£3,215.46</b> |
| Paint/Materials      | <b>£1,136.82</b> |
| Specialist/Other     | <b>£405.97</b>   |
| Sub total            | <b>£6,181.51</b> |
| Vat                  | <b>£1,236.30</b> |
| Total Estimated Cost | <b>£7,417.81</b> |










**Our Ref:** qdos261071

**Your Ref:** 44688/1

**Date:** 24/04/2026





**Our Ref:** qdos261071

**Your Ref:** 44688/1

**Date:** 24/04/2026

### **Statement of Truth**

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

N O'Reilly - ATA VDA

engineers@collisionengineers.co.uk