


QDOS Assistance  
1st Floor, Barfield House  
24-28 alderley Road  
Wilmslow  
Cheshire  
SK9 1PL

Date: 15/04/2026  
Our Ref: 00034469/HASSANA  
Your Ref: 44658/1

## To the Court REPAIRABLE REPORT

Dear Sirs,  
Client: **Mr Raj Kumar Singh**

We refer to your instructions received on **14 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

|                                                  |                               |                                                                                     |                                       |                               |
|--------------------------------------------------|-------------------------------|-------------------------------------------------------------------------------------|---------------------------------------|-------------------------------|
| Vehicle: <b>MERCEDES-BENZ B160 BLUEEFFICIEN</b>  |                               | Colour: <b>SILVER</b>                                                               | Speedo: <input type="text"/>          | Miles <input type="text"/>    |
| Reg No: <b>SB10LJL</b>                           | Registered: <b>Jun 2010</b>   | Type: <b>M.P.V.</b>                                                                 | Trans: <b>Manual</b>                  |                               |
| Vin No: <b>WDD2452312J587297</b>                 | MOT Exp: <input type="text"/> | R/H/F Tyre <b>Not Kno</b>                                                           | R/H/R Tyre <b>Not Kno</b>             |                               |
| Mods: <b>Not Seen</b>                            | Cond: <b>Good</b>             | R/H/F Belt <b>Not Tested</b>                                                        | R/H/R Belt <b>Not Tested</b>          |                               |
| Audio: <b>Not Seen</b>                           | Manf'd: <b>2010</b>           |  |                                       | Spare Tyre <b>Not Know</b>    |
| Brakes: <b>Not Known</b>                         | Tax Exp: <input type="text"/> |                                                                                     |                                       | Centre Belt <b>Not Tested</b> |
| Steering: <b>Not Known</b>                       | Fuel: <b>Petrol</b>           |                                                                                     |                                       |                               |
| Extras: <b>Not Seen</b>                          | C.C.: <b>1498</b>             |                                                                                     |                                       |                               |
| Air Bags Deployed: <b>Not Known</b>              | BHP: <b>95</b>                | L/H/F Belt <b>Not Tested</b>                                                        | L/H/R Belt <b>Not Tested</b>          |                               |
| Damage: <b>Moderate Collision/Impact LH Side</b> | Incident: <b>13/04/2026</b>   | L/H/F Tyre <b>Not Kno</b>                                                           | L/H/R Tyre <b>Not Kno</b>             |                               |
| Vehicle Value: <b>£2,866.00</b>                  |                               | Repair Cost: <b>£1,394.36 inc VAT</b>                                               | (48.65% of PAV) Roadworthy: <b>No</b> |                               |

### DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

### NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand side.

### ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

The valuation for the purpose of this report has been calculated using an estimated mileage from the vehicles MOT history at the time of loss.

### VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

### REPAIR SCHEDULE

**New parts required:-**R/Door Mirror Hsg, R/Lwr D/Mirror Cover, R/Door Mirror Glass, R/Mirror Base, Panel Sundries, Car Care Kit, Sundry Parts

**Repaint only parts:-**R/Door Mirror Hsg Painting Stage I-M, Preparation Work For Two Coat Painting

**Specialist/Sundry charges:-**Epa, Methods Research Specialist

**Remove And Refit parts:-**Description, Right Mirror, Renew R/Door Mirror (Removed)

**Parts to check:-**Right Front Door, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vaccum, Est Pre Wash

### **COST OF REPAIRS**

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £618.36. The cost of the paint and materials would be £133.73, The cost of the replacement parts would be approximately £333.65, The specialist/sundry charges would be £76.23, and the VAT liability on the total would amount to some £232.39 giving a total repair cost of £1,394.36 including VAT **subject to undisclosed damage**. The labour charge is based on 6 hours at a rate of £103.06 per hour.

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **PRE-INCIDENT VALUE**

According to the information available to us the vehicle was first registered in 30/06/2010. The corresponding CAP Guide (model code: 15478) adjusted retail value for vehicles of this type and age in the April 2026 guide is £2,866.00 at 79618 Miles, trade value is £1,400.00 and mid value is £2,133.00. We place the pre-accident value of this particular vehicle at £2,866.00 bearing in mind the condition described herein.

### **OWNER'S CONTRIBUTION**

We do not consider that any betterment contribution is required on this occasion.

### **RESERVE**

We consider that a repair reserve of £1,400.00 would be reasonable on this occasion.

### **INSTRUCTIONS ISSUED**

As no estimate has yet been obtained to repair the vehicle we have not been able to authorise repairs. Once an estimate is available we would be pleased to discuss the method and repair schedule with the chosen repairer and agree costs on your behalf, if required.

### **REPAIR DURATION**

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

### **ROADWORTHY STATE**


In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to insecure parts.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

A rectangular box containing a handwritten signature in black ink that reads "H. ANWAR".

Hassan Anwar ATA VDA  
Exclusive Vehicle Assessors



5\_VINjpg-V1.jpg



Imageofclientdamage-V1.jpeg



2\_Imageofclientdamagejpg-V1.jpg