

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mrs Kirsty Campbell
18 Glenney Close
Lee-on-the-Solent
Hampshire
PO13 8FD

Date: 27/01/2026
Our Ref: 00076425/PK
Your Ref: 570152 \ 720069439

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mrs Kirsty Campbell**

We refer to your instructions received on **16 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI Q5 S LINE 45 TFSI MHEV QUAT S	Colour: SILVER	Speedo: 34937	Miles
Reg No: HT72KTO	Registered: Jan 2023	Type: 5 Door Estate	Trans: Semi-Auto
Vin No: WAUZZZFY8P2053393	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2023		Spare Tyre Not Know
Brakes: Not Known	Tax Exp:		Centre Belt Not Tested
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1984		
Air Bags Deployed: Not Known	BHP: 261.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light Accidental Damage LH Rear Bumper	Incident: 13/01/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £30,937.00		Repair Cost: £1,959.50 inc VAT	(6.33% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the left hand rear bumper.

VEHICLE HISTORY CHECK

16/01/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rr Bumper Ctr Cover, Rear Bumper Spoiler

Repairable parts:-Repair Rear Bumper, Repair Rear Bumper Cap

Repaint only parts:-Rear Bumper Repair Paint Plastic, Rear Bumper Cap Repair Paint Plastic, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, E.P.A. Charge, Sundry Part

Remove And Refit parts:-Lower Tail lamps, Rear Bumper Spoiler, Rear Lower Bumper Cover, Renew Rear Bumper Spoiler, Rear Lower Bumper Cover, L/R Bumper Corner Trim

Parts to check:-Check Veh Diag Pre Check, Check Veh Diag Post Check, Check Technical Info, Check And Quality Control

COST OF REPAIRS

The repairers, Peter Cooper, 5 Durban Park, Bognor Regis, PO22 9RJ (Tel. 01243830449), have compiled an estimate in the sum of £909.00 plus parts at manufacturer's list prices plus £500.00 for paint and materials plus £11.76 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £21.00 to £888.00 for the labour and £146.33 to £353.67 for paint and materials in their final account. The labour charge is based on 11.1 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £353.67. The cost of the necessary replacement parts will be approximately £362.50, the specialist/sundry charges will be £28.75, the VAT liability on this repair will amount to some £326.58 giving a total repair cost of £1,959.50 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £200.80.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 20/01/2023. The corresponding CAP Guide retail value for vehicles of this type and age in the January 2026 guide is £30,937.00 at 34937 Miles, trade value is £27,700.00 and mid value is £29,318.50. We place the pre-accident value of this particular vehicle at £30,937.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £1,975.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 27th January 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

Connexus Vehicle Assessors