


Dr Kushan Nanayakkara  
2 Magdalene Drive  
Mickleover  
Derby  
Derby  
DE  
Derby

Date: 21/05/2026  
Our Ref: 00034682/JEFFP  
Your Ref: EHR100260

To the Court  
**REPAIRABLE REPORT - Supplementary Report**

Dear Sirs,  
Client: **Dr Kushan Nanayakkara**

We refer to your instructions received on **20 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

|                                                      |                             |                                                                                     |                                      |
|------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|--------------------------------------|
| Vehicle: <b>MERCEDES-BENZ EQB 250+ AMG LINE</b>      | Colour: <b>BLACK</b>        | Speedo: <b>5864</b>                                                                 | Miles                                |
| Reg No: <b>RJ25UUW</b>                               | Registered: <b>Jun 2025</b> | Type: <b>Estate</b>                                                                 | Trans: <b>Automatic</b>              |
| Vin No: <b>W1N9M0CBXTN143546</b>                     | MOT Exp:                    | R/H/F Tyre <b>Not Kno</b>                                                           | R/H/R Tyre <b>Not Kno</b>            |
| Mods: <b>Not Seen</b>                                | Cond: <b>Good</b>           | R/H/F Belt <b>Not Tested</b>                                                        | R/H/R Belt <b>Not Tested</b>         |
| Audio: <b>Not Seen</b>                               | Manfd: <b>2025</b>          |                                                                                     | Spare Tyre                           |
| Brakes: <b>Not Known</b>                             | Tax Exp:                    |  | <b>Not Know</b>                      |
| Steering: <b>Not Known</b>                           | Fuel: <b>Electric</b>       |                                                                                     | Centre Belt                          |
| Extras: <b>Not Seen</b>                              | C.C.: <b>0</b>              |                                                                                     | <b>Not Tested</b>                    |
| Air Bags Deployed: <b>Not Known</b>                  | BHP: <b>187.</b>            | L/H/F Belt <b>Not Tested</b>                                                        | L/H/R Belt <b>Not Tested</b>         |
| Damage: <b>Moderate Collision/Impact Rear Bumper</b> | Incident: <b>18/04/2026</b> | L/H/F Tyre <b>Not Kno</b>                                                           | L/H/R Tyre <b>Not Kno</b>            |
| Vehicle Value: <b>£37,926.00</b>                     |                             | Repair Cost: <b>£3,222.53 inc VAT</b>                                               | (8.50% of PAV) Roadworthy: <b>No</b> |

**DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

**NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the rear bumper.

**ENGINEER'S COMMENTS**

21/05/2026 - Supplementary Part prices Amended.

26/05/2026 - Supplementary Adas reset.

**VEHICLE HISTORY CHECK**

24/04/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

**REPAIR SCHEDULE**

**New parts required:-**Rear Bumper Moulding, L/R Bumper Moulding, R/R Bumper Moulding, Rr/R/Cent Bump



Mould, Rear Lower Bumper, Rear Number Plate, Sundry Parts

**Repaint only parts:-**Two Coat Metallic

**Specialist/Sundry charges:-**Bsi 10125, Elec Recharge, Adas Methods, Tech Data + Methods, E.P.A. Charge, Aries Support, Car Care Kit, Adas Coding

**Remove And Refit parts:-**Description, Short Test, Rear Underbody Covering, Rear Number Plate, Rear Bumper, Add For R + R Rear Bumper, Remove And Refit Rear Lower Bumper, Rear Parktronic Sensor/S, Rear Lower Bumper Moulding, L/R Bumper Moulding, R/R Bumper Moulding, L/R Bumper Trim, R/R Bumper Trim, Detach + Refit L/R Side Trim, Rear Wheels, L/R Wheelhouse Trim, R/R Wheelhouse Trim, Road Test And Quality Control

**Parts to check:-**Rear Bumper C-Member, Lwr Rear Centre Part, Electric Risk Assess, Wash And Vac, Veh Diag Post, Veh Diag Pre, Adas Exploration Fee, Powerdown Ev/Hybrid, Est Pre Wash

### **COST OF REPAIRS**

The repairers, Impact Accident Repairs (Tel. 0115 959 0290), have compiled an estimate in the sum of £1,360.39 plus parts at manufacturer's list prices plus £549.01 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 13.2 hours at a rate of £103.06 per hour. The cost of the necessary replacement parts will be approximately £776.04, the specialist/sundry charges will be £549.01, the VAT liability on this repair will amount to some £537.09 giving a total repair cost of £3,222.53 including VAT **subject to any undisclosed damage.**

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **PRE-INCIDENT VALUE**

According to the information available to us the vehicle was first registered in 09/06/2025. The corresponding Cazana Guide (model code: 9823032) adjusted retail value for vehicles of this type and age in the April 2026 guide is £37,926.00 at 5864 Miles, trade value is £35,651.00 and mid value is £36,788.50. We place the pre-accident value of this particular vehicle at £37,926.00 bearing in mind the condition described herein.

### **OWNER'S CONTRIBUTION**

We do not consider that any betterment contribution is required on this occasion.

### **RESERVE**

We consider that a repair reserve of £3,225.00 would be reasonable on this occasion.

### **INSTRUCTIONS ISSUED**

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 24th April 2026, on your behalf.

### **REPAIR DURATION**

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

### **ROADWORTHY STATE**

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to bumper parts adrift. We understand that the vehicle is not currently being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

 .

Jeff Parr CAE AMIMI  
Exclusive Vehicle Assessors