

Mr Nasser Peerbaccus  
37 Norman Road  
Ilford  
IG  
Ilford  
IG1 2NH

Date: 20/05/2026  
Our Ref: 00035920/HASSANA  
Your Ref: EHR101317 \\  
FLO368627067775

To the Court  
**REPAIRABLE REPORT - Supplementary Report**

Dear Sirs,

Client: **Mr Nasser Peerbaccus**

We refer to your instructions received on **08 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

|                                                   |                             |                                                                                     |                                      |
|---------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|--------------------------------------|
| Vehicle: <b>PORSCHE MACAN T S-A</b>               | Colour: <b>RED</b>          | Speedo: <b></b>                                                                     | Miles                                |
| Reg No: <b>XX02NAS</b>                            | Registered: <b>Nov 2024</b> | Type: <b>Estate</b>                                                                 | Trans: <b>Semi-Auto</b>              |
| Vin No: <b>WP1ZZZ958SLB02064</b>                  | MOT Exp: <b></b>            | R/H/F Tyre <b>Not Kno</b>                                                           | R/H/R Tyre <b>Not Kno</b>            |
| Mods: <b>Not Seen</b>                             | Cond: <b>Good</b>           | R/H/F Belt <b>Not Tested</b>                                                        | R/H/R Belt <b>Not Tested</b>         |
| Audio: <b>Not Seen</b>                            | Manfd: <b>2024</b>          |  | Spare Tyre                           |
| Brakes: <b>Not Known</b>                          | Tax Exp: <b></b>            |                                                                                     | <b>Not Known</b>                     |
| Steering: <b>Not Known</b>                        | Fuel: <b>Petrol</b>         |                                                                                     | Centre Belt                          |
| Extras: <b>Not Seen</b>                           | C.C.: <b>1984</b>           |                                                                                     | <b>Not Tested</b>                    |
| Air Bags Deployed: <b>Not Known</b>               | BHP: <b>261.</b>            | L/H/F Belt <b>Not Tested</b>                                                        | L/H/R Belt <b>Not Tested</b>         |
| Damage: <b>Moderate Collision/Impact RH Front</b> | Incident: <b>07/05/2026</b> | L/H/F Tyre <b>Not Kno</b>                                                           | L/H/R Tyre <b>Not Kno</b>            |
| Vehicle Value: <b>£60,669.00</b>                  |                             | Repair Cost: <b>£5,984.39 inc VAT</b>                                               | (9.86% of PAV) Roadworthy: <b>No</b> |

**DESKTOP ASSESSMENT**

This report has been compiled from a desktop review of the information available relating to this claim.

**NATURE OF INCIDENT**

The vehicle has suffered moderate collision/impact damage to the right hand front.

**VEHICLE HISTORY CHECK**

14/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

**REPAIR SCHEDULE**

**New parts required:-**R/F Wheel Cover, L/F Tyre Press Valve, R/F Tyre Press Valve, R/F Tyre, Car Care Kit, Sundry Parts

**Repairable parts:-**Front Bumper

**Repaint only parts:-**Description, Front Bumper Repair Paint S3, Bonnet Repair Paint S3, Preparation For Painting S3, Preparation For Painting

**Specialist/Sundry charges:-**Bsi Compliance, Alloy Refurb Std X2, Pas 2060 / Aries, Wheel Alignment, E.P.A. Charge, Tech Data + Methods, Adas Coding, Car Care Kit



**Blend only parts:-**Fr Bump Lwr Grill Cvsurface Painting S2, L/F Lower Wing Surface Painting S2

**Remove And Refit parts:-**Description, Remove And Refit Front Bumper Trim, L/F Air Guide Grille, R/F Air Guide Grille, Radiator Grille, Front Spoiler, Front Bumper Lower Grille Cover R + R, L/Upper Headlamp Cover, R/Upper Headlamp Cover, Left Additional Headlamp, Right Additional Headlamp, Front Manufacturer Badge, Front Wheel (Wheels), Left Front Tyre, Right Front Tyre, Program Surround Camera Control Unit

**Parts to check:-**R/F Upper Wing, Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Spare Wheel Swap, Est Pre Wash

### **COST OF REPAIRS**

The repairers, Essex Emergency Services Ltd (Tel. 01279 883641), have compiled an estimate in the sum of £1,543.50 plus parts at manufacturer's list prices plus £1,463.76 for paint and materials plus £700.00 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £2,439.14. The labour charge is based on 20.58 hours at a rate of £118.52 per hour. We have also agreed that the cost of paint and materials will be limited to £1,463.76. The cost of the necessary replacement parts will be approximately £304.15, the specialist/sundry charges will be £779.94, the VAT liability on this repair will amount to some £997.40 giving a total repair cost of £5,984.39 including VAT **subject to any undisclosed damage.**

### **PRE-INCIDENT CONDITION**

The vehicle is considered to be in good condition for its age and type.

### **PRE-INCIDENT VALUE**

According to the information available to us the vehicle was first registered in 23/11/2024. The corresponding Cazana Guide (model code: 9679468) adjusted retail value for vehicles of this type and age in the May 2026 guide is £60,669.00 at 11130 Miles, trade value is £55,815.00 and mid value is £58,242.00. We place the pre-accident value of this particular vehicle at £60,669.00 bearing in mind the condition described herein.

### **OWNER'S CONTRIBUTION**

We do not consider that any betterment contribution is required on this occasion.

### **RESERVE**

We consider that a repair reserve of £6,000.00 would be reasonable on this occasion.

### **INSTRUCTIONS ISSUED**

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 14th May 2026, on your behalf.

### **REPAIR DURATION**

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

### **ROADWORTHY STATE**


In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to wheel impact.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Hassan Anwar ATA VDA  
Exclusive Vehicle Assessors