

Calculation

Client:
Make / Model / Type: Mercedes-Benz / CLS- Class 4 door Coupe Model 2019 / E220 2.0d (194ps)
 9G-Tronic Plus 2021.5MY [10.2020]
Glass's national Code 322997001
Vehicle Registration Number: VX21TZD
VIN: W1K2130042A925294
Date: 14.10.2022

Paint system: AZT
Hail damage logic: ETG
Labour time unit: 1 Hour
Currency: £
Database version: 2022.10.

Body		Repair type	Labour time	Overlap-time	Labour costs	Material costs
88995001	Roof Drip Moulding (R)	UI	0.00	0.20		0.00
NN	Rear Bumper Lining	R	1.00			0.00
	Selected criteria: Automatic Parking System					
54107301	Rear Bumper Outer Side	RP	1.50			89.50
	Distance-Sensor (R)					
88880201	Rear Bumper Lining					
NN	Rear Lamp LED Outer (Both)					
NN	Side Panel Liner Unfasten and Fasten (L)					
NN	Side Panel Liner Unfasten and Fasten (R)					
	Selected criteria: Automatic Parking System					
NN	Reflector (L)	RP	0.10			9.65
	Annotation (time): Autovista time net					
NN	Reflector (R)	RP	0.10			9.65
	Annotation (time): Autovista time net					
NN	Repair Method Research	EC	0.50			0.00 F
	Allowance					
NN	System Diagnostic Check	EC	0.00			45.00 F
	(Post Repair)					
NN	System Diagnostic Check	EC	0.00			45.00 F
	(Pre Repair)					
NN	Car Care Kit	EC	0.00			10.00 F
NN	Check and adjust four wheel alignment	EC	0.00			110.00 F
NN	De-Nib/Polish	EC	0.30			0.00 F
NN	Final Inspection & Road Test	EC	0.20			0.00 F
NN	Tyre	EC	0.50			185.00 F
NN	Wash/Clean	EC	0.30			0.00 F
Labour costs					0.00	
Material costs						503.80
Total Body						£ 503.80

Auxiliary work		Repair type	Labour time	Overlap-time	Labour costs	Material costs
60459301	Rear Side Panel Strip & Set-Up for Paint (R)	UI	0.20	0.70		0.00
88995001	Roof Drip Moulding (R)					
88602401	Side Panel Fuel Filler Lid (R)					
Labour costs					0.00	

Material costs	0.00
-----------------------	-------------

Total Auxiliary work	£ 0.00
-----------------------------	---------------

Paint	Paint type	Paint level	Labour time	Labour costs	Material costs
Roof Panel, Side (R)	200	B	0.40		23.20
Rear Side Panel, Complete K (R)	200	B	0.70		117.50
Fuel Filler Lid (R)	200	B	0.30		8.10
Rear Bumper k/e	200	K2	1.00		196.40
Rear Bumper Distance-Sensor (R)	200	K1R	0.10		0.91
Prep. metal (on vehicle without pre-painting)	200		0.70		93.37
Prep. synthetics (combined-operation work)	200		0.50		37.68
Colour mixing (1)			0.30		0.00
Sample colour creation (1)			0.30		9.19
Labour costs				0.00	
Material costs					486.35
Total Paint					£ 486.35

Summary	Labour rate	Labour time	Labour costs	Material costs
Body	0.00	4.50	0.00	503.80
Auxiliary work	0.00	0.20	0.00	
Paint	0.00	4.30	0.00	486.35
Total Labour		9.00	0.00	
Total Material				990.15
Repair costs excl. VAT				990.15
VAT (20.00 %)				198.03
Repair costs incl. VAT				£ 1,188.18

Part name	Part no.	Previous part no.	Material costs
Rear Bumper Outer Side Distance-Sensor	22390540009999		89.50
Reflector	0998208700		9.65
Reflector	0998208700		9.65
Total Parts			£ 108.80

Attention: Listed part numbers are for information only and CANNOT be used for ordering purposes.

Part name	Position no.
Roof Drip Moulding	88995001
Rear Bumper Lining	
Rear Bumper Outer Side Distance-Sensor	54107301+88880201
Reflector	
Reflector	
Rear Side Panel Strip & Set-Up for Paint	60459301+60301801+88602401
Repair Method Research Allowance	
System Diagnostic Check (Post Repair)	
System Diagnostic Check (Pre Repair)	
Car Care Kit	
Check and adjust four wheel alignment	
De-Nib/Polish	
Final Inspection & Road Test	

Tyre
Wash/Clean

Abbreviations	Description
F	User defined operations
R	RIGHT
L	LEFT
UI	Uninstall and install
R	Repair
RP	Replace
EC	Surcharge
NN	No part number

Paint type	Paint level, Procedure, Method
B	Adjacent Panel Blend
200	2 Coat
K2	Surface spraying
K1R	Part priming/part raw

Selected criteria
Automatic Parking System

Additional Fields	
Paint material index	100.000 %
Part index	100.000 %

Glass's does not take responsibility for accuracy and completeness of data originating from vehicle manufacturers.