

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 19/05/2026
Our Ref: 00036588/HASSANA
Your Ref: 45393/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Taha Ali**

We refer to your instructions received on **18 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD GRAND C-MAX ZETEC TDCI AUT		Colour: RED	Speedo: 79133 Miles	
Reg No: NL66ZKW	Registered: Nov 2016	Type: M.P.V.	Trans: Automatic	
Vin No: WF0WXXGCEWGL03423	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Average	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2016			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Know
Steering: Not Known	Fuel: Diesel			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1499	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 118	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Moderate Collision/Impact Rear	Incident: 13/05/2026			

Vehicle Value: **£5,546.00** Repair Cost: **£1,314.30 inc VAT** (23.70% of PAV) Roadworthy: **No**

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the rear.

ENGINEER'S COMMENTS

Vehicle is a previous CAT S - total loss, as a result the valuation has been deducted -20%

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

VEHICLE HISTORY CHECK

According to the Experian database; Category S total loss claim Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 31/03/2023, loss dated 25/02/2023

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rear Bumper Spoiler, Car Care Kit, Sundry Parts

Specialist/Sundry charges:-Epa, Methods Research Specialist

Remove And Refit parts:-Description, Add/Time For One Main Position, R/F Fog Lamp, Left Rear Reflector, Rear Bumper, Renew Rear Bumper (Removed), Add/Time For Renew Rear Bumper Cover, Rear Inner Parking Aid



Sensor/S

Parts to check:-Bootlid/Tailgate, R/R Outer Lamp, Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Est Pre Wash

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £516.34. The cost of the replacement parts would be approximately £502.68, The specialist/sundry charges would be £76.23, and the VAT liability on the total would amount to some £219.05 giving a total repair cost of £1,314.30 including VAT **subject to undisclosed damage**. The labour charge is based on 6.2 hours at a rate of £83.28 per hour.

UNRELATED DAMAGE

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; ns quarter.

PRE-INCIDENT CONDITION

The vehicle is considered to be in average condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 26/11/2016. The corresponding Cazana Guide (model code: 11745) adjusted retail value for vehicles of this type and age in the May 2026 guide is £6,932.00 at 79133 Miles, trade value is £4,853.00 and mid value is £5,892.50. We place the pre-accident value of this particular vehicle at £5,546.00 bearing in mind the condition described herein. The following adjustments have been made to the pre-accident value; previous Total Loss adjustment -£1,386.40.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £1,325.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

As no estimate has yet been obtained to repair the vehicle we have not been able to authorise repairs. Once an estimate is available we would be pleased to discuss the method and repair schedule with the chosen repairer and agree costs on your behalf, if required.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE


In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to insecure parts.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Hassan Anwar ATA VDA
Exclusive Vehicle Assessors



1_Mileagejpg-V1.jpg



5_CLVdamage445393jpeg-V1.jpeg



CLVdamage45393jpeg-V1.jpeg



2_CLVdamage245393jpeg-V1.jpeg



3_CLVdamage345393jpeg-V1.jpeg



11_VINjpg-V1.jpg



VINjpg-V1.jpg