

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Miss A Mitchell
Withycombe
Furzton
Milton Keynes
Buckinghamshire
MK4 1ET

Date: 02/09/2025
Our Ref: 00072694/PK
Your Ref: EHR88009


Engineer Repairable Report

Dear Sirs,

Client/Insured: **Miss A Mitchell**

We refer to your instructions received on **29 August 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	RENAULT CLIO RS LINE TCE		Colour:	BLACK	Speedo:	94547	Miles
Reg No:	EA69MXJ	Registered:	Nov 2019	Type:	5 Door Hatchback	Trans:	Manual
Vin No:	VF1RJA00664344037	MOT Exp:		R/H/F Tyre	5	R/H/R Tyre	5
Mods:		Cond:	Good	R/H/F Belt		R/H/R Belt	
Audio:		Manf'd:	2019				Spare Tyre
Brakes:	Satisfactory	Tax Exp:					
Steering:	Satisfactory	Fuel:	Petrol				Centre Belt
Extras:		C.C.:	999				
Air Bags Deployed:		BHP:	99.2	L/H/F Belt		L/H/R Belt	
Damage:	Light Accidental Damage Rear Bumper	Incident:	28/08/2025	L/H/F Tyre	5	L/H/R Tyre	5



Vehicle Value:	£7,400.00	Repair Cost:	£2,809.14 inc VAT	(37.96% of PAV)	Roadworthy:	Yes
----------------	------------------	--------------	--------------------------	-----------------	-------------	------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

VEHICLE HISTORY CHECK

29/08/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rear Number Plate, Rear Bumper Skirt, Rear Apron Moulding

Repaint only parts:-Rear Bumper New Part Paint K1r, Rr Towing Lug Cover Surface Paint Plast., Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Energy Uplift, Bs10125 Admin Fee, Manufacture Approval, Methods Research, E.P.A. Charge, Pre Rep Sys Check, Post Rep Sys Check, Car Care Kit, Sundry Part

Remove And Refit parts:-Rear Bumper, Renew Rear Bumper, Rear Number Plate, Rear Parking System Sensor/S, 12V Battery Standard Shutdown, Final Checks Road Test And Qc

Parts to check:-Check Pre Repair Clean, Check Wash And Vac, Check Adas Exploration

COST OF REPAIRS

The repairers, XL Motors Ltd, Bedworth Road, Coventry, Warwickshire, CV6 6LA (Tel. 02476362181), have compiled an estimate in the sum of £1,208.00 plus parts at manufacturer's list prices plus £928.99 for paint and materials plus £474.97 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £472.00 to £736.00 for the labour and £371.17 to £557.82 for paint and materials in their final account. The labour charge is based on 9.2 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £557.82. The cost of the necessary replacement parts will be approximately £644.57, the specialist/sundry charges will be £402.56, the VAT liability on this repair will amount to some £468.19 giving a total repair cost of £2,809.14 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £2,210.04.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 08/11/2019. The corresponding Glass's Guide (model code: T6Q6) adjusted retail value for vehicles of this type and age in the August 2025 guide is £7,400.00 at 94547 Miles, trade value is £5,050.00 and mid value is £6,225.00. We place the pre-accident value of this particular vehicle at £7,400.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,825.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 2nd September 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

. CAE AMIMI AQP
Connexus Vehicle Assessors