

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

2/2

Mr D Mclean
21 Mayo Road
Croydon
Surrey
CR0 2QP

Date: 30/01/2026
Our Ref: 00074835/GC
Your Ref: EHR91477

Engineer Repairable Report - Supplementary Report

Dear Sirs,

Client/Insured: **Mr D Mclean**

We refer to your instructions received on **07 November 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: NISSAN MICRA ACENTA IG-T	Colour: BLACK	Speedo: 61582	Miles
Reg No: NA69EEO	Registered: Oct 2019	Type: 5 Door Hatchback	Trans: Manual
Vin No: VNVK1400462179504	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Man'f'd: 2019		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 999		
Air Bags Deployed: Not Known	BHP: 98.6	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Accidental Damage LH Front Bumper	Incident: 31/10/2025	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £6,700.00		Repair Cost: £2,276.24 inc VAT	(33.97% of PAV)
		Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate accidental damage to the left hand front bumper.

ENGINEER'S COMMENTS

12/03/2026 - Supplementary cost: Repair costs have increased due to the parts price increasing and the repairer requiring time to detail mask the Front Bumper.

VEHICLE HISTORY CHECK

07/11/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Grille Badge

Repairable parts:-Repair Methods, Repair Front Bumper

Repaint only parts:-Front Bumper Repair Paint Plastic, Detail Masking Image 33, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, E.P.A. Charge, Energy Cost, Pas 2060 Charge, Post Repair Sweep, Pre Repair Sweep, Panel Rep Sundries, Bs10125 Charge, Vm Approval Charge, Sundry Part, Repair Methods

Remove And Refit parts:-Job Allowance, Front Bumper Cpl, Both Fog Lamps, L/F Bumper Covering, R/F Bumper Covering, Front Number Plate, Front Lower Bumper Spoiler, Badge Nissan, Radiator Grille, Inc Sanitise Pre Repair Clean, Allowance R/Test & Final Qc, Allowance Wash And Vac

COST OF REPAIRS

The repairers, Fleetline Coachworks Limited, Lancefield House, 5 Commerce Way, Croydon, CR0 4XA (Tel. 0208 680 8888), have compiled an estimate in the sum of £910.80 plus parts at manufacturer's list prices plus £393.31 for paint and materials plus £384.66 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £956.80. The labour charge is based on 10.4 hours at a rate of £92.00 per hour. We have also agreed that the cost of paint and materials will be limited to £415.65. The cost of the necessary replacement parts will be approximately £94.13, the specialist/sundry charges will be £430.29, the VAT liability on this repair will amount to some £379.37 giving a total repair cost of £2,276.24 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/10/2019. The corresponding Glass's Guide retail value for vehicles of this type and age in the October 2025 guide is £6,700.00 at 61582 Miles, trade value is £4,780.00 and mid value is £5,740.00. We place the pre-accident value of this particular vehicle at £6,700.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,300.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 30th January 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

Connexus Vehicle Assessors