

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr J Davies
353d Charleston Drive
Dundee
Scotland
DD2 4HP


Date: 21/01/2026
Our Ref: 00076476/GC
Your Ref: EHR95554

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr J Davies**

We refer to your instructions received on **20 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD FOCUS ST-LINE MHEV	Colour: RED	Speedo: 6844	Miles
Reg No: SP25HMY	Registered: Mar 2025	Type: 5 Door Hatchback	Trans: Manual
Vin No: WF0NXXGCHNSJ84426	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2025		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel:		
Extras: Not Seen	C.C.: 999		
Air Bags Deployed: Not Known	BHP: 123.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Moderate Accidental Damage Rear Bumper	Incident: 19/01/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £19,230.00		Repair Cost: £2,560.61 inc VAT	(13.32% of PAV)
		Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate accidental damage to the rear bumper.

VEHICLE HISTORY CHECK

20/01/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, L/R Lwr Bumper Brkt, L/R Upp Bumper Brkt, Rear Bumper Spoiler, L/R Lower Spoiler, L/R Outer Lamp, L/R Tyre, L/R Pressure Valve

Repaint only parts:-L/R Lower Spoiler New Part Paint K1r, De Nib, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Wheel Alignment, E.P.A. Charge, Car Care Kit, Pre_Rep_Diag_Check, Post_Rep_Diag_Check, Methods Research, Energy Charge, Sundry Part

Remove And Refit parts:-Add/Time For One Main Position, Rear Bumper, Renew Rear Bumper (Removed), Left Tail Lamp, Renew Rear Bumper Cover (Add/Work), Left Rear Bumper Bracket, Remove And Refit Tyres Pressure Sensors, Left Rear Wheel, L/R Tyre

Parts to check:-Check And Quality Control, Check And Clean Car

DELETED PARTS

We advise that we have removed the following from the repairer's original estimate, as we do not consider they are required; N/S/R Quarter Panel repair and N/S/R Alloy Wheel Refurb at this stage and should be subject to further checks or explanation

COST OF REPAIRS

The repairers, Autocosse Autobody, DD2 4US, have compiled an estimate in the sum of £616.28 plus parts at manufacturer's list prices plus £275.09 for paint and materials plus £604.00 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £249.85 to £366.43 for the labour and £158.65 to £116.44 for paint and materials in their final account. The labour charge is based on 4.4 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £116.44. The cost of the necessary replacement parts will be approximately £1,191.23, the specialist/sundry charges will be £459.74, the VAT liability on this repair will amount to some £426.77 giving a total repair cost of £2,560.61 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £706.20.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 10/03/2025. The corresponding Glass's Guide retail value for vehicles of this type and age in the January 2026 guide is £19,230.00 at 6844 Miles, trade value is £17,052.00 and mid value is £18,141.00. We place the pre-accident value of this particular vehicle at £19,230.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,575.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 21st January 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

Connexus Vehicle Assessors