

Mrs Michelle Teather
122 Gudge Heath Lane
Fareham
Hampshire
PO
Fareham
Hampshire

Date: 26/01/2026
Our Ref: 00029073/DME
Your Ref: EHR95586

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mrs Michelle Teather**

We refer to your instructions received on **20 January 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: BMW X3 XDRIVE30D XLINE AUTO		Colour: White	Speedo: 55259	Miles
Reg No: YE20CCU	Registered: Jul 2020	Type: 5 Door Estate	Trans: Automatic	
Vin No: WBATX760X0N042703	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Unknown	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2020			Spare Tyre
Brakes: Not Known	Tax Exp:			Not Know
Steering: Not Known	Fuel: Diesel			Centre Belt
Extras: Not Seen	C.C.: 2993			Not Tested
Air Bags Deployed: Not Deployed	BHP: 261	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Collision/Impact Rear	Incident: 20/01/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £25,566.00		Repair Cost: £4,993.26 inc VAT	(19.53% of PAV) Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered moderate collision impact to the rear.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.

Authority sent via Audatex.

VEHICLE HISTORY CHECK

23/01/2026 - I confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Badge, Rear Badge, Rear Screen, Rear Screen Bond Kit, Cleaner R1 Rr Screen, Clamp, Sundries

Repairable parts:-Repair Tailgate

Repaint only parts:-Tailgate Repair Painting <50%, Rear Bumper Cover Repair Paint Plastic, De-Nib And Polish 1



Panel, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Bsi10125 Charge, Car Care Kit, E.P.A. Charge, Adas Method Research, Anti-Corrosion

Remove And Refit parts:-Add/Time For Main Work, L/R Wheelarch Trim, R/R Wheelarch Trim, Rear Bumper Trim, Rear Bumper Trim, Rear Ultrasonic Sensors, Rear End Panel Cover, R/Parcel Shelf Bracket, L/Parcel Shelf Bracket, Sun Blind, Tailgate Seal, Tailgate Trim, Renew Rear Bmw Badge, Renew Rear Model Badge, Rear No-Plate, Renew Rear Window, Both Inner Tail lamps, L/R D-Pillar Trim, R/R D-Pillar Trim, L/R C-Pillar Trim, R/R C-Pillar Trim, Insert Floor, Hoover Glass, Allowance Identify Adas, Allowance R/Test & Final Q/C, Corrosion Protection To 1St Panel

Parts to check:-Check Veh Diag Post Check, Check Veh Diag Pre Check

COST OF REPAIRS

The repairers, Accident Repair Hub - Emsworth (Tel. 01243377921), have compiled an estimate in the sum of £2,456.26 plus parts at manufacturer's list prices plus £778.30 for paint and materials plus £161.00 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be reasonable. The labour charge is based on 23.83 hours at a rate of £103.06 per hour. I have also agreed that the cost of paint and materials will be limited to £723.21. The cost of the necessary replacement parts will be approximately £844.69, the specialist/sundry charges will be £136.89, the VAT liability on this repair will amount to some £832.21 giving a total repair cost of £4,993.26 including VAT **subject to any undisclosed damage. I am pleased to confirm that I have achieved total gross savings in this matter of £95.04.**

OTHER DAMAGE

I noted the following damage on the vehicle:- Not provided.

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 09/07/2020.

The corresponding Glass's Guide retail value for vehicles of this type and age in the January 2026 guide is £25,566.00 at 55000 Miles, trade value is £22,671.00.

I place the pre-accident value of this particular vehicle at £25,566.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

I do not consider that any betterment contribution is required on this occasion.

RESERVE

I consider that a repair reserve of £5,000.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 26th January 2026, on your behalf.

REPAIR DURATION

I consider that this repair will take some 6 to 7 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle was not roadworthy at the time of my inspection as a result of the damage sustained due to Rear screen smashed.

For & on behalf of



Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors