

Miss Claire Richardson
1 Wicklehurst Cottages, Bath Road
Littlewick Green
Maidenhead
Berkshire
SL6 3RQ

Date: 12/02/2026
Our Ref: 00030032/DME
Your Ref: EHR96411 \ FLO365489033904

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: Miss Claire Richardson

We refer to your instructions received on **06 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MINI COUNTRYMAN CLSSC S ALL4 MH	Colour: Black	Speedo: 1001	Miles
Reg No: RJ75YWN	Registered: Jan 2026	Type: 5 Door Hatchback	Trans: Automatic
Vin No: WMW22GA0707U38416	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: As New	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2026		
Brakes: Not Known	Tax Exp: 		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1998		
Air Bags Deployed: Not Deployed	BHP: 214.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact LH Rear Bumper	Incident: 05/02/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £31,432.00		Repair Cost: £2,682.12 inc VAT	(8.53% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered light to moderate collision impact to the left hand rear bumper.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.

Authority sent via Audatex.

VEHICLE HISTORY CHECK

12/02/2026 - I confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper Mounting Kit, Rear Bumper Spoiler, Panel Sundries, Sundries

Repairable parts:-Repair Rear Bumper Cover

Repaint only parts:-Rear Bumper Cover Repair Paint Plastic, Machine Polish 0.3 Per Panel, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-ADAS Methods, Bs10125, Car Care Kit, Epa, Methods Research, Trans 2 specialist ADAS Subcontracted

Remove And Refit parts:-Add/Time For Main Work, Rear Bumper, Rear Bumper Spoiler, No Plate Lamp(S), Rear No-Plate, Specialist Adas Exploration, Post Scan, Pre Scan, Ice Shutdown

Parts to check:-Check Pre Clean, Check R/T And Q/C, Check Wash And Vac, Check Workshop Movement

COST OF REPAIRS

An Audatex estimate has been obtained from Junction Road Motor Company, 6-8 Woodside Grove London, N, North Finchley, London, N12 8QU (Tel. 02084451242) in the sum of £1,627.69 labour plus parts at manufacturer's list prices plus £302.51 for paint and materials plus £744.21 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be high and I have agreed a reduction with the repairers of £138.28 to £1,489.41 for the labour and £48.20 to £254.31 for paint and materials in their final account. The labour charge is based on 12.57 hours at a rate of £118.52 per hour. I have also agreed that the cost of paint and materials will be limited to £254.31. The cost of the necessary replacement parts will be approximately £168.95, the specialist/sundry charges will be £322.43, the VAT liability on this repair will amount to some £447.02 giving a total repair cost of £2,682.12 including VAT **subject to any undisclosed damage.**

OTHER DAMAGE

I noted the following damage on the vehicle:- None noted.

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT CONDITION

The vehicle is considered to be in as new condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 19/01/2026.

The corresponding CAP Guide (model code: 104055) adjusted retail value for vehicles of this type and age in the February 2026 guide is £31,432.00 at 1000 Miles, trade value is £29,875.00.

I place the pre-accident value of this particular vehicle at £31,432.00 bearing in mind the condition described herein.

RESERVE

I consider that a repair reserve of £2,700.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 12th February 2026, on your behalf.

REPAIR DURATION

I consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

For & on behalf of



Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors